PROPELLER LOG BOOK



SENSENICH PROPELLER MFG. CO. Lititz, Pennsylvania 17543

Internet: http://www.sensenich.com.

THIS LOG BOOK IS TO BE KEPT
WITH THE PROPELLER
FOR RECORDING OF ALL PROPELLER MAINTENANCE WORK PERFORMED

LBGEN 6/99

PROPELLER MAINTENANCE RECORD

	12 FM 859-1-85
PROPELLER MODEL .	2/2/2
PROPELLER SERIAL NU	IMBER 36353

TABLE OF PROPELLER ATTACHING BOLT WRENCH TORQUE Sensenich Metal Propellers (the proper torque is also shown on Blade Information Decal)

PROPELLER SERIES**	BOLT DIA. (inches)	RECOMMENDED WRENCH TORQUE		
		Inlb.	ftlb.	nm.
69CK, M69CK (6 bolts) 72CK (6 bolts) 74CK, M74CK (6 bolts) 76AK, M76AK (6 bolts) 76AM6, M76AM (6 bolts) 74DM6, M74DM (6 bolts) 74DR, M74DR (8 bolts)	³/a (0.375)	280-300	23-25	32-34
74DM7 (6 bolts)	⁷ /16 (0.4375)	480-540	40-45	54-61
72CC, 72FM8 (6 bolts) 74DC, M74DC (6 bolts) 76EM8, M76EMM (6 bolts) 80BM8, M80BMM (bolts)	1/2 (0.500)	720-780	60-65	81-88

^{*} Not in production
** These are the basic propeller models. Spacer addition does not affect recommended wrench torque

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4/10/05	0	Install peop.	Mckeen
5/15/06	176	Removed Slab - postalla	Cut Ca Ca Ca
11/1	072 0	new solighed skiner.	ned)
2/1/02	373.5	Charles of Co to 10	Marie
8-15-14	1010	Dispected Propland Bolts	STAN acces