ENGINE MODEL: TSIO-520-R(9B)
ENGINE S/N: 1007930
REG NO: N6364B
WORK ORDER: 8359-07-2019

J.A. Air Center

Repair Station No. NF2R029L
43W730 US RT 30
Sugar Grove, Illinois 60554
Phone: 630.584 3200

DATE: 03 February, 2020
A/C TSN: 515.4
ENG TT: 199.8
TSMOH:
HOBBS: 515.4

Engine Entries

2 Completed an Annual Inspection on this engine as per Cessna Model 210 and T210 Service Manual Inspection Chart and Continental TSIO-520 Maintenance Manual for an Annual Inspection as a guide, and AC 43.13-1B Chapter 9. Compressions were tested as follows: #1-65, #2-72, #3-66, #4-65, #5-67 and #6-68 all over 80 PSI. The oil and filter was changed. Opened and inspected the filter. Serviced the engine with 10 Qts of Phillips 20W50 X/C oil and a new AA48108-2 filter.

Maintenance Release
I certify the aircraft and/or component(s) on was repaired and/or inspected in accordance with an annual inspection, and current regulations of the Federal Aviation Administration and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station CRS NF2R029L and EASA.145 5424 under Work Order No. 8359-07-2019. Dated 03 February, 2020.

DATE: 03 February, 2020 SIGNED: Don Morgan
Don Morgan
Certified Repair Station No. NF2R029L

Work Order: 8359-07-2019

Printed by EBis 3 (datcomedia.com)