# Manufacturer BEECHCNAFT Model F33A Serial CE-293 Registration Number N233FC Date of Manufacture MARCH 27-1970 Engine(s) currently installed: Manufacturer CONTINENTAL Model 10-520-BA Serial 90/30d H Manufacturer Model Serial Propeller(s) currently installed: Manufacturer MCCAULEY Model 3A32C76-SM HUB Model 3A32C76-SM Serial 239894 Serial Blade Model S82NC-2 Serial F4250975 Serial F4250975

© 1992 ASA

Aircraft Record General Information

**Blade Model** 

DATE 19 97	TOTAL TIME IN SERVICE	Current Weight and Balance Information									
	SERVICE	Empty Weight	Empty C.G.	Useful Load	Remarks						
 	3138-35	2239	80.09	1161	B. DISHANNON HEAVY GLAS Q-WET VAC STC INSTI- WEIGHED BY DOWN TOWN AIR SERVICE REPORT DATED 7 OCT 1997						

DA1

© 1990 ASA

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				-
			293 N233FC CO INSTALLE WINDSHIF REVISION LEFT AND IN ACCOR SA2870WIN BERYL D' VACUUM THE FAA NUMBER S/N B0121 ACCORD MODIFIEL CURRENT	ONSISTS OF THE FOLLOWING INSTALLATION AS FOLLOWS; ED BERYL D' SHANNON AVIATION SPECIALTIES, INC. SPEED SI OPED ELD INSTALLED IN ACCORDANCE WITH S. T.C. SA997SO DRAWING B19000, ID, DATED 11/09/79. 3/8" SSW-L P/N B19005-221 S/N B043088-110 INSTALLED DRIGHT HAND COCKPIT SIDE WINDOW P/N B1300-111 S/N B043088-155 & 266 RDANCE WITH BERYL D' SHANNON AVIATION SPECIALTIES S.T.C. E DRAWING LIST DLB-1301 DATED 02/07/75. REPLACED SECOND AND THIRD DOWS WITH FAA PMA'D REPLACEMENT WINDOWS. INSTALLATION OF 'SHANNON AVIATION SPECIALTIES ENGINE CRANKCASE, BREATHER, AND I PUMP AIR-OIL SEPARATOR AS PER S.T.C. SA2653WE IN ACCORDANCE WITH APPROVED DRAWING LISTS SHOWN ON THE MASTER ELIGIBILITY LIST MEL-1014 DATED 10/01/76, OR LATER FAA APPROVED DRAWING LISTS. KIT 189-002 INSTALLATION OF WET VACUUM PUMP AS PER S.T.C. SA1643SO IN ANCE WITH DRAWING NO. 19050 REVISION A. THE AIRCRAFT WAS D AND INSPECTED IN ACCORDANCE WITH APPROVED DATA AND IT REGULATIONS OF THE FAA AND IS APPROVED FOR RETURN TO SERVICE. NT DETAILS OF THIS MODIFICATION ARE ON FILE AT THIS REPAIR
			STATION	1:03 Dayles 5 Kelly

E 1001 ASE

DATE

Aircraft
Tach rea
Aircraft
Engine
Propelle
Propelle
Prop Ge
Perform
C/W Ai
total tim
switch
Repalce
new rea
tire. Re
exhaus
All wo
and ba
I certific
condition

Villia

er of stries.) RECORDING TACH TODAYS TOTAL FLIGHT TIME IN

Description of Inspections, Tests, Repairs and Alterations
Entries must be endorsed with Name, Rating and Certificate Number of

Downtown Air Service Inc.

11 Omni Drive

Cahokia, Il. 62206

Aircraft: N233FC Beechcraft F33A s/n CE-293

Tach reading: 163.1

DATE

Aircraft total time: 3138.35

Engine s/n 901302-H total time 1863.1 TSMOH 163.1

Propeller total time unknown

Propeller TSMOH est 1091.55 last overhaul date 01-07-91

Prop Governor Woodward 210452 TSMOH 163.1

Performed the following work:

C/W AD72-22-01 by lubrication of the uplock rollers. C/W AD95-04-03 by penetrant inspection-no cracks found-next due 36 total time(663.1 tach). C/W AD97-14-15 by testing door latch button for proper locking operation. C/W AD76-07-12 Bendix switch due again at 3235.35 total time. Lubed controls, checked control travels. Replaced flap position transmitter with new p Repalced one overhead wemac w/new part. Straightened top cowl hinge. Replaced fuel cap orings p/n MS29513-338. Constrainew rear floorboard to exact same configuration as original part, using exact same materials as original. Replaced nose tire with tire. Replaced ELT battery and C/W 91.207d. due again 10-30-98. Adjusted flap travels. Replaced landing lite p/n 4313. Replexhaust stack ball joint hardware including springs, bolts, nuts. Replaced speaker with 5.25 inch replacement and 6x9 adapter All work done in accordance with the Beech F33A shop manual and AC43.13 1A and 2A. Jacked Aircraft and weighed. New and balance report done dated 10-7-97.

I certify that this aircraft has been inspected in accordance with an ANNUAL inspection and has been found to be in an airwo condition.

Villiam R. Baumheuter, II AP341524370IA

21 245

Thursday, October 09

DATE 19 <u>98</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
3-15	205 54		3180-79	N233FC CE-293 F33A
				REMOVED RH EIEVATOR FOR PAINT, USED
				JET 610 571-527 MEDIUM-GRAY. CHECKED BALANCE
				IN ACCORDANCE WITH BENANZA 33 SERIES SHOP
				MANUAL' FOUND WITHIN LIMITS. REINSTALLED ELEVATED
				CHECKED RIGGING IN AKLERDANCE WITH BENAULA 33
				SERIES SHOP MANUAL; FOUND WITHIN LIMITS
				Coxelance C. Smitte APS00669679IA
Page .				

0.196

DAT

19.

.

19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
AIRCR	AFT	P.O. B	CRAC BOX 101	GIN AVIATION SERVICES ADDISON, TEXAS 75001 • (214) 239-8503
N23	3FC			
	CH 24, 1 H: 211.5			
REPI RIGI DOU	LACED BO	TH MAI BRAKI ZUL ZIEBA	IN GEAR E CYLINI	FT MAIN TIRE, SN 71991349, REMOVED AND BRAKE LININGS AND RESEALED LEFT AND DERS.

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
		Ρ.		RAGIN AVIATION SERVICES  1 • ADDISON, TEXAS 75001 • (214) 239-8503
	N233FC			
	APRIL 17,	1998		
	TACH TIME	E:0232.	12	
	REPLACED	CONTRO NOSE W	L YOKE T	ROLLERS, PN 118641. RIM ASSY. PN 35-380072-1. RINGS AND RACES.

© 1991 ASA

DATE

Description of Inspections, Tests, Repairs and Alterations TOTAL RECORDING TODAYS DATE Entries must be endorsed with Name, Rating and Certificate Number of TIME IN FLIGHT TACH Technician or Repair Facility. (See back pages for other specific entries.) SERVICE TIME

CRAGIN AVIATION SERVICES
P.O. BOX 101 • ADDISON, TEXAS 75001 • (214) 239-8503

# AIRFRAME

N233FC

MAY 15, 1998

HOBBS 1496.1

TACH 257.1

REMOVED AND REPLACED LANDING GEAR HORN SWITCH AND LANDING

c 1891 ASA

LIGHT BULB .

DOUGLAS J. ZIEBA

A&P 370489635

DATE

RECORDING TACH TIME TODAYS FLIGHT TOTAL TIME IN SERVICE **Description of Inspections, Tests, Repairs and Alterations** 

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

# FLITE ELECTRONICS, INC.

ADDISON AIRPORT 4786 AIRPORT PARKWAY, DALLAS TX 75248 – PHONE (214) 239-3791 CRS DG2R767K

## LOG BOOK MAINTENANCE RELEASE

The aircraft and/or appliance identified was repaired and/or inspected in accordance with current Federal Aviation Agency Regulations and was found airworthy for return to service, with respect to work performed.

23

AI

TO

RE 97

NE

WE

As

MalPle 7-7-98

Communication and Alberta Communication and

© 1981 ASA

THE VOICE

DATE	
19	

RECORDING TACH TIME TODAYS FLIGHT TOTAL TIME IN SERVICE

**Description of Inspections, Tests, Repairs and Alterations** 

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

# **CRAGIN AVIATION SERVICES**

P.O. BOX 101 • ADDISON, TEXAS 75001 • (214) 239-8503

233FC

# AIRCRAFT

SEPT. 4, 1998

TOTAL TIME: 3317.50 TACH TIME: 341.80

REPAIRED CABIN DOOR AT LOWER LATCH PIN. REPLACED CABIN DOOR HANDLE PER AD 97-14-15, CHECKED BALANCE AND INSTALLED SERVICABLE RH ELEVATOR, INSTALLED NEW LANDING LIGHT BULB, INSTALLED NEW READING LIGHT SWITCH, RIGGED RIGHT MAIN GEAR, CHECKED LEFT AND NOSE GEAR RIGGING, LUBED LANDING GEAR, REPACKED WHEEL BEARINGS.

HARLIN D. OBENSHAIN A&P 454294256 IA

E 1991 AS

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
-			CB	AGIN AVIATION SERVICES

P.O. BOX 101 • ADDISON, TEXAS 75001 • (214) 239-8503

DATE

233FC


AIRFRAME

OCTOBER 14, 1998 TACH 411.48

REPAIRED FUEL STRAINER DOOR. INSTALLED NEW SEAT BACK ADJUSTING MECHANISM ON COPILOTS SEAT, ADJUSTED LANDING GEAR INDICATOR, RELAMPED LANDING LIGHT AND TAXI LIGHT. INSTALLED AND CALIBRATED NEW RITHT FUEL QUANITY C/B. COMPLIED WITH AD 72-22-01 BY LUBE UPLOCK ROLLERS, COMPLIED WITH AD 76-07-12 MAG SWITCH. THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

soling of HARLIN D. OBENSHAIN A&P 454294256IA

E 1991 ASA



DATE 19_99	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
03-08	Tach 540	2		elw 100 hour insp. this date. Replaced
	Total 35	5.45		Nose gear sissers bushings, adjusted both coul
*				door latchs Replaced pose wheel stearing links
				and replaced bushings in stearing yoke. Replaced
				Rt and Lt Flap up stop bumper. Replaced Lt.
				fuel tank sump drain. Replaced hobb's meter
				press, Sw. Resealed Lt brake master cyl and
				right brake wheel cyl. Replaced Rt and Lt Brake
				disk & brake linings, Resealed wose strut. Clean.
	THAT THIS	ADNOS	<b>レンエイレ カド</b>	or in a label dela de la dive
ANNUAL:	Azamorthy	CONDE	TON	t Certify that this matter has been
AIP WE	58487 I	1011	100	inspected in accordance with a
לעד וון	70 (0 / 1	PAY		determined to be in airvicitly condition.
			1	Donglas A Zeila AP 370489635

© 1991 A5A

		TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Technician or Repair Facility. (See back pages for other specific
25-24 7	4.4 662	,		Replaced Reilt main times tubes Report
				all wheel bearings Resealed At Prela
				cleaned ground connections Rt was lig
				rigged were year position indicator. In
				center pedistal. Lubril landing gear - End-
				Douglo of Zeele AP370 489635
06-02	Tach 665	,5		Removed and replaced turn condinator (
				ck good. Douglas of Zicha AP370489635
07-18-64	40660	2017 0		Replaced tack ven horrmeter time oc
	Tack	7376		Dough A Ziela AP 572449636

A STATE OF S

A Park

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed v	tions, Tests, Repairs and Alterations with Name, Rating and Certificate Number of y. (See back pages for other specific entries.)
Retr brak o.k. warn Insta to C cran cont Airc sele insta 200 Per pan	es. Lubed uploc Landing gear pring systems optilled new comparties. C/W AD 76-07-1 kcase. C/W AD rols cleaned. In raft rigging chector valve check alling placard to 0-6. New ELT b FAR 91207(d), els re-installed.	r cleaned a ck cables to reload che ts check o.l ass. Error c 2. C/W AI 96-12-07 spected, lu- cks o.k. Fu ted for prop fuel select pattery insta Aircraft sy	nd lubed. Who C/W AD 72- cks o.k. Landi k. Pressure che ard installed. D 77-13-22 by by inspection bed. C/W AD el screen clea per operation. For valve. AD alled. Ecpires stems opts che inspected in a d to be in airway.	eel bearings packed. Relined 22-01. Uplock cable tension ing gear emergency extent and eck of exhaust heat exchange. Opts check of magneto switch inspection of engine of impulse coupling. Flight 95-0403 by inspection of spar. ed. Fuel caps, vents and C/W AD 99-05-13 by s researched thru release 4-02. Inspected ELT eck o.k. All fairhings and accordance with a Annual orthy condition this date	
0) 454				LDO BOOM ENTRY CANAL E.L.T. BATTERY REPLACEMENT DATE CAPACI	RAFT SUPPLIES, INC.  @ No. Curby, OF 57013  de 006-32-4801  14/2000  12002

DATE

19	RECORDING TACH TIME	TODAYS FLIGHT	12000	E IN VICE	Te	ntries echnic	must to	e end Repai	orsed r Facili	with Name ity. (See ba	, Rating ack page	and Co s for o	ertificate N ther specif	ic entries.)
8-10-	100 1	1233 lacec	F (	Le	f.t.	5	tue, eru	ch l b	/ad	Mer, Ma	the che	38 x chee 2 c	19 1 fo War	enera DIA
		SERVICEABLE	BEECHCRAFT FUEL CELL	Component L.H. 40GALLON BAFFLED	UNIROYAL US-943 AUG 1975	Mr data 35-380135-11	Part number W-2516	Serial number F 0 4 2 1 0 0 0 0 2	Work Order Number	Date Inspected Inspector	Remarks This component identified was:	OModified  Omodified	and inspected in accordance with career is approved the Federal Aviation Administration, and is approved for return to service. Pertinent details of the work performed are on file at this repair station under order.	Eagle Fuel Cells-ETC. Inc. 300 Airport Road, Eagle River, WI 64521 F.A. Certified Repair Station NL5R071N

f 5.)

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
7/9/01	133,1		3846,4	ANNUAL Inspection Ect PATE 4-02 ups
1- 1				of IAW 91.767(d) Inspected of Cibes Contains
				Chested Cts Gearen COND Lt Now Lt. Reday
				Lak on Cabin Door. Replaces Fuel Areno
			-	CWAD 72-22-01 Uplock dollers are 100
				CW AD 76-07-12 Surtch ops ok are 10
				CW AD 76-07-12 Switch ops ok are 100 AD 95-04-03 Span Tuspechen Due 4339,370TAL
				IF AVIATION INC.
				1000 W. JEFFERSON STREET Has Been Inspected in Accordance
				JOLIET III IMOIS 60435 With AN ANNUAL Inspection & Was
(				1 . 1 . 0
,				Med 1 14 324600168
1				

DATE

¢ 1991 ASA

19	RECORDING TACH TIME	FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
7/23/02	146.5		3859.8	ANNUAL TUSPECTEN PERFORMEN REPLICED  ECT Saffeny 9/04 ops of IAW91. 2076)  Services Blake Reservoire Clease + Gorses  Wheel Branips Brakes de Performes Color  Petraction Tests. Cleases + Closes Controls  CW AD 72-22-01 Uplack Rollers ave res  CW AD 76-07-12 Switch ops of pieces  JF AVIATION INC.  DATE 1/23/02 TACH 146.5  1 CERTIFY That This Aircraft Engine  Has Been Inspected In Accordance  Which AV ANNUAL Inspection & Wes  Determined To Be in Airworthy Condition

Possy Pite C TODAYS TOTAL Description of Inspections, Tests, Repairs and Alterations DATE FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of SERVICE Technician or Repair Facility. (See back pages for other specific entries.) 19\_\_ ALTIMETER SYSTEM AND ALTITUDE UIPMENT TESTS AND INSPECTIONS AS This altimeter has been inspected, tested, and certified to comply with FAR 91.411 iaw FAR 43 APPENDIX "E" FAR 91.411 per FAR 43 Appendix E to an altitude of 20,000 PN 5734\_M - 51 SN 4 7264 PERFORMED. ALCE FQ5R866M ROCKFORD IL TATIC SYSTEM WO# 557406 DATE 9-4-02 Inspection Ko REP ) ALTIMETER CUR 5934.1A.91 SN L7264 ADM S/N Mid-Continent Instrument Co. - Wichita, KS SER ED TO 20 K FT. DATE 9-9-02 ☐ Mid-Continent West - VanNuys, CA A (C) INTEGRATED SYSTEM TEST W.Q.# 6500 THI GNED BYE TOWN ATC TRANSPONDER TESTS AND INSPECTIONS AS REQUIRED BY FAR 91.413 iaw FAR 43 APPENDIX "F" HAVE BEEN PERFORMED: AVIONICS PLACE FOST 866M ROCKFORD II MODEL TOR - 950 S/N V - 1 © 1991 ASA

R

I

P

T

P

V

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
-23-03	175.0	5 try	spel and	brepainted aircrift with Do Pont Burn.
Colors:	white	45414	X, Maro	on 143 UH, Gray 6334X alt 2, Gold 5242X alt 1
centrals	were res	noved	balance	land reinstalled after painting. Installed new-
winds	ield, mas	ligh	I lens,	calin dursed. Repaired front edge of both
				performed retraction test. And Effig. \$48396 5230
7/25/03	179.6		389219	ANNUAL Inspertion Performes Est 9/04
1 1				Inspected Controls. Clemes of Grasses Bennies
				Protesok detast tests ok. CWAD 72-72-01
				uplace Rolles of Due 100 HIS ewas 76-07-
				Benoix Switch ok over NO 185
				40 95-04-3 Span Inspection are 4329.3 ToTAL
			DAT	7/25/03 TACH /79.6 JF AVIATION INC.
			I CE	PTIFY That This Aircraft Engine 4000 W. JEFFERSON STREET
				Been Inspected In Accordance  JOLIET, ILLINOIS 60435  AN ANNUAL Inspection & Was
			Deb	rmined To Be In Airworthy Condition
			3,000	11. K) TA329618765

DATE

19\_

19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspection Entries must be endorsed with Technician or Repair Facility.	Name, Rating and Certific	cate Number of
			A & M Clow In	M Maintenance Services – 1C5 ternational Airport, Bolingbrook, IL.		
	TYPE: BE "N" #: N 2 DATE: 08/	233FC	FT F33A	TACH TIME: AIRFRAME T.T.	181.8 Hrs. 3895.1 Hrs.	
			wheel bearing	aced with a new Condor 5.00 - 5 of e was replaced with a new 5.00 - ngs were cleaned, inspected and g	5 inner tube	
	Gerald W 1 AP 2753424		¥.	END		

DATE

19

rations Priority : COR TODAYS RECORDING DATE nber of FLIGHT TACH BOL : entries.) MONTE : WIMBORNE I CONSIGNEE TIME 19 Terms Desc : 30 days due net A & M Maintenance Services - 105 TTTO : AND Clow International Airport, Bolingbrook, IL. 192.4 Hrs. TACH TIME: TYPE BEECHCRAFT F33A 3905.7 Hrs. AIRFRAME T.T. "N" #: N 233FC DATE: 02/25/2004 At this time the throttle cable was removed and a new throttle cable, P/N 36-380061-1, was installed and adjusted for proper travel Mark Beck AP 359381387

€ 1991 ASA

DATE	1			
	A & M M	laintenance Services - 1C5		
19	Clow Intern	ational Airport, Bolingbrook, IL.		
-	-	TACH TIME:	193.8 Hrs.	
	TYPE: BEECHCRAFT F33A	AIRFRAME T.T:	3907.1 Hrs.	
	"N" # N 233FC	AIRFRAME 1.1	3907.11118	
	DATE: 05/19/2004			
	At this time the right-hand main strut	was aired to proper extension	with nitrogen.	
	Removed nesting material from engin	e compartment Repositioned	left-hand side panel of	
	center console to firewall and secure	1		
	Center console to incwan and secure	END		
	1 2 / /			
	Var like hal			
	Josef Dlaby			
	John J. Blaha, Jr.			
	John J. Blaha, Jr. AP/2238954			
			*	
			*	
			*	

scription of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) THE FOLLOWING ALTIMETER SYSTEM AND ALTITUDE REPORTING EQUIPMENT TESTS AND INSPECTIONS AS REQUIRED BY FAR 91.411 iaw FAR 43 APPENDIX "E" HAVE BEEN PERFORMED. AVIONICS PLACE FQ5R866M ROCKFORD IL PARA (A) STATIC SYSTEM DATE 0722 04 PARA (B) ALTIMETER PILOTS 5034.14-9/SN 17264 S/N TESTED TO 2 O FT. DATE PARA (C) INTEGRATED SYSTEM TEST FT. DATE @ DATE 27 22 04 W.O.# 8359
SIGNED BY FOR THE STS AND INSPECTIONS AS REQUIRED BY FAR 91.413 iaw FAR 43 APPENDIX "F" HAVE BEEN PERFORMED: DATE 07 22 021 AVIONICS PLACE POST 866M ROCKFORD IL MODEL TO 2 5 S/N / 19 SIGNED BY FORM J SIGNED BY

© 1991 ASA

		ions ioe,	TE HOURS	A SUBJECT AND STATE OF LOCK HAVEN, INC.  Subject Air Note on file at this repair station und subject Air of the repair are on file at this repair station und subject Air of the repair are on file at this repair station und subject Air of the repair subject Air of the re
DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Detriber of open party of the p
8/10/04	195.4		3908.7	ANNAL Inspection Persons Reptices ELT
	Smo H	933		CWAD 72-22-01 Uplack Rollins (one 1004
1	ET	9/06		CWAO 76-07-12 Bevoix Switch Oce 100) AD 95-04-03 Span Inspection Die 4329. Cleares + Greases Bearing: Bistes ok Performs Gest Notact tots. Fuel Ovartily senders on Left, Side Apparises (see TMG)
				I CERTIFY That This Aircraft Engine  JF AVIATION INC.  4000 W. JEFFERSON STREE
				With AN ANNUAL Inspection & Was JOLIET, ILLINOIS 60435  Determined To Be In Airworthy Condition  TA 329608765
1.000				0.1991

DATE 19	RECORDING JACH — TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
22/05	237.2		3950,5	ANNUAL INSpection Personno EG 9/06 OPS de IAW 91,2076) Inspected + Cobos Controls Installes JET Frel Flow System IAW STC SAON615
RAND	cer = 3	30.43	1 C	Supplement Installer, Ground tests ok. Replaced  Out Guage (see Tag) Cleanes of Green Bearings  Perturnes Gear Lotanet Tests of Conagency enter-  CWAD 72-22-01 Uplack Rollers ok are (100)  CWAD 76-07-12 Ign Switch de (ace 100)  AD 95-04-03 Sear Inspection Ove 4329.3 TOTAL  THE 4/22/05 TACH 237.2  BERTIFY That This Aircraft Engine 4000 W. JEFFERSON STREET  The AN ANNUAL Inspection & Was JOLIET, ILLINOIS 60435  TA 328605785

DATE 19\_/

ALT TEST DATE AFF

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10/6/0	6 256.9		3170.2	ANNUAL TOSSICOLOS PERTORAS REPARASET  BATER OCT 2008 AS OR TAWALIZOTA.  Tospected + Cibes Costas & Checked CB  Clean + Gresses Weel Senings Birkes of  Repass Rt Gun Down Switch for 100-381000-1
_ (	EARTEX ANTE	EX AIRCHAPT SUPP Nel He AE Accord 678-7829 608 3 FC T ZOO		COUND 72-22-01 Uplock Koller & acion of COUND 76 07-12 South of ac are NOTE AD 95:04-03 SPAN INSPECTION DUE 4325.
				DATE JOSE TACH 256.5  1 CERTIFY That This Aircraft Engine 4000 W. JEFFERSON STREET Has Been Inspected In Accordance 4000 W. JEFFERSON STREET WITH A.V. AND Inspection & Was JOLIET, ILLINOIS 60435  Determined To Be in Airworthy Condition
				JA38608765

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	DA 19
3/07	288.5			Annual Inspected Performs EtT OF 18	14
				Controls Chalcel Cts Cleans Grand Lean,	51
				CWAD 72-22-01 Uplock Koller (DUE 100) CWAD 76-07-12 Swift ite (DUE 100)  FAVIATION INC. DATE 11/3/07 TACH 288.5	
			4000	W. JEFFERSON STREET   CERTIFY That This Aircraft   W. JEFFERSON STREET   CERTIFY That This Aircraft   W. JEFFERSON STREET   CERTIFY That This Aircraft   W. Jefferson Street   W	106
				Determined To Be in Airworthy Condition  IA379608765	ELT MPI

19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
14/11/08	310.7		4024	Annual Inpection Pertorne Replace Es
SMOH	1048,3			Battery (OCT 2010) ofs de IAW 91, 2070. Imparted + Cobio Contras Checket Cts
				+ Genes Wheel Bearings Brites ok
CART	V			CWAD 72- 22-01 ACORPALLES SC.
#AKIE	N233F	PPRA (2P) \$7101 100-547-850*	-	DATE 12/11/28 TACH 310,7 JE AVIATION INC.
ELT BATTERY REPLACEMENT DA	OCT ZO	010	)	CERTIFY That This Aircraft 4000 W. JEFFERSON STRE
				With AN ANNO Inspection & Was  Determined To Be In Airworthy Condition
-	+			1 = 13.29608765
-				
_				
_	-	-		

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
4/13/10	325.9	Airting	4034.2	JAW 91.20 Kd) OCT 2010. Insected + Cubes
	SINCH	1668.5		Controls Charled Cts Cleres + Grewer wheel
TOTAL	ENGLE	2763.5		Begnings Digles de Aghras NoseTine Tibe CWAD 08-13-17 New Cincit Brester Sciferes Installs
				Cu AD 76-07-12 Surter offs of pre 12 miss cu AD 07-08-08 UPLock Rollers of DRILLIES Portomed Gear retraction Tests
				DATE 4/13/10 TACH 325.9  I CERTIFY That This Aircraft Engine 1000 W. JEFFERSON STREET  Has Reen Inspected in Accordance 1000 W. JEFFERSON STREET  With A A A WAL Inspection & Wall IFT II INOIS 60435  Determined To Be in Airworthy Condition
				14 IA 3428812
		-		

© 1991 ASA

DATE 19

7

1/4/

=

19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Altera Entries must be endorsed with Name, Rating and Certificate Numbe Technician or Repair Facility. (See back pages for other specific ent
5/14/11	338.2			ANNUAL Inspection Performs ETS.
				Replaces New Our CATE Acty 13 450
				Typices New Our CATE Acy 13 450 FAW 91. 707(d) Inspected + Cate Con
				Comes of Bankes de Metral test of
4				WAD 76-07-12 Sutch ope ok
1				CWAD 07-08-08 Mark Nolles of
				JF AVIATION INC. Date 5/14/11 Tech 3
				4000 W. JEFFERSON STREET Country that this Alterest Engine
				JOLIET, ILLINOIS 60435 with an Annual Inspection & v
				determined to be in already condi
				# In 3428812

19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries I Technic  Description of Inspections, Tests, Repairs and Alterations Certificate Number of Centries.	DA 19
HAVE BE AVIONIC PARA (A) DATE PARA (B)	LOWING AL ING EQUIPMI ED BY FAR 91 EN PERFORM S PLACE FOS STATIC SYS ALTIMETER	.411 iaw F MED. R866M R0 TEM	AR 43 APPE	ND ALTITU PECTIONS A ENDIX "E"  L N Z 3	de
C.P.'s TESTED T PARA (C) DATE SIGNED B' ATC TRAN	O 2 O INTEGRATED S-20-2	K FT D SYSTEM	DATE 5 TEST W.O. #_/ S	3 5 2	
AVE BEE	413 iaw FAR N PERFORMI J-26-2 PLACE FQSR TOR-53-	ED: 866M ROC	DIX "F"		
					7

9	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
14/12	355.4			Annual Inspector Performs Et ove Ang 2013 ops et IAW91.2010) Inspekt Cotols Cherkel (to Gene Notices tests et
				Aug 2013 ops et 24W91, 2010) Fypel
				Costols Cheskel Cts. Gene lothers tests of
				Wheel Berngs of Ties & Bustes of
				Applice of frel draw Vale Kt wag.
				- CWAD 07-08-08 Uplock Kellers ok
6.77				- Carp 76-01-12 Sufer go of
9				Boto 6/19/12 Boto 355 V
	11	4)5.		I could that this Alexant Engine IF AVIATION INC.
	3 Mg-275 5 2	190		has been inspected in accordance 4000 W. JEFFERSON STREET
	36.00	-		with a NAUNA inspection & was JOLIET, ILLINOIS 60435
	20			STASTE 88Y Z
	4.504		-	-97
1/26/13	368,9			Aracinst de For Ferry Flight From
1				1CS TO K JET STASYBEIZ

19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
(23/13	36A.Z		4082.5	ANNUAL INSpection Restorate Replaces FIX
	5 то н	1104.8		TAW 91.70 XD. In perfort + Cubes Controls. Adjuster Gen Warning Swith Service Rabber
				CWAD 07-08-08 Uplock Roller OK. Dr. 469.7 CWAD 76-07-12 Swiff Ope 1 K Dr. 469.7
			154	JE AVIATION INC. Date 8/23/13 Tech 369 2
			4	JOLIET, ILLINOIS 60435 has been inspected in accordance with av Auxor inspection & was
				### determined to be in airwarthy condition
190° A3A				

ions ations of per of es.) , ----- untries.) THE FOLLOWING ALTIMETER SYSTEM AND ALTITUDE REPORTING EQUIPMENT TESTS AND INSPECTIONS AS REQUIRED BY FAR 91.411 iaw FAR 43 APPENDIX "E" HAVE BEEN PERFORMED. AVIONICS PLACE FQ5R866M ROCKFORD IL PARA (A) STATIC SYSTEM PARA (B) ALTIMETER 3, 2 PILOTS 5934-1A-7 S/N C.P.'s SIN Z TESTED TO 20,000 PARA (C) INTEGRATED SYSTEM TEST
DATE SIGNED BY 26 2014 W.O. # 16346
ATC TRANSPONDED DESTS AND INSPECTIONS AS REQUIRED
BY FAR 91.413 iaw FAR 43 APPENDIX "F" FT. DATE HAVE BEEN PERFORMED:
DATE SET 2014
AVIONICS PLACE FOSR866M ROCKFORD IL
MODEL 70 6 50 SAL 1-SIGNED BY 2

DATE 19	RECORDING TACH TIME	TODAYS FEIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
0/14/14	371.6		4084.9	ANNUAL INSpection Performed EUT July 15 Ops of IAW 91.7070. Impeted & Wheel Control
	SmoH	1109.2	2	Clem + Part Styling Box. Whoels + Brakes Ste Returnion Tests the Cleans Gene Legs Date 10/14/14 Tach 371.6 JF AVIATION INC.
				has been inspected in accordance JOLIET, ILLINOIS 60435
				determined to be in airworthy condition AS428812
10/25/16	372.2			Ameraft & for ferry Flight ICE to KJOT

€ 1991 ASA

DATE 19	RECORDING TACH TIME	FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with N Technician or Repair Facility. (S	s, Tests, Repairs and Alterations lame. Rating and Certificate Number of ee back pages far other specific entries.)
11 18 16	372.3		4085.6.	ANNUAL Inspection	Cybres Ect Battey Now
	Ect oct	2018		Dec (007 2019) ops ok	TAW 91.2070) Make
	SMOH	1109	9	Gen Atunt tests	TAW91.207D Rother TAW91.207D Rother ens + Blood System ok. Wheels & Bearings of
				J.F. Aviation Inc. 4000 W. Jefferson St. Joliet, IL 60431	Cate 11/18/16 Tach 1 certify that this Alrundt Engine has been inspected in accordance
			•	DIA 3	determined to be in alresorthy condition 292887 Z

Description of Inspections, Tests, Repairs and Alteration AE IN Entries must be endorsed with Name, Rating and Certificate Number of SERVICE Technician or Repair Facility. (See back pages for other specific entries.) DATE THE FOLLOWING ALTIMETER SYSTEM AND ALTITUDE REPORTING EQUIPMENT TESTS AND INSPECTIONS AS REQUIRED BY FAR 91.411 iaw FAR 43 APPENDIX "E" 5/23 HAVE BEEN PERFORMED. PARA (A) STATIC SYSTEM PARA (B) ALTIMETER N233FC PILOTS 5934-1A-91 S/N L7264 C.P.'s S/N PARA (C) INTEGRATED SYSTEM TEST ATC TRANSPONDER TESTS AND INSPECTIONS AS REQUIRED BY FAR 91.413 iaw FAR 43 APPENDIX "F" HAVE BEEN PERFORMED #1 MODEL TOR 950 SN Y-19575-A #2 MODEL DATE 11-18,2016N 233 FC W.O. # 18040 SIGNED BY CONTROL AVIONICS PLACE FQ5R866M ROCKFORD IL TACH 375.0 Ancres H We For Forg Flight Clockto Jot C.1991 ASI E 1991 ASA

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Te- Entries must be endorsed with Name, Technician or Repair Facility. (See back	Rating and Certificate Number of k pages for other specific entries.)
5/23/18	375.8		4089.1	Annial Inspection Perfor	NO. EU OF OR THE
	SMOH	1113,4		Annial Inspection Perfor 91.70 (1) 60 Hay Die (OCT 20 Pertorno Gear Noticet to	ests. Wheels & Barkes of
	TT Prop	199.9		AO 07-08-08 Uplat Rol	las oce 469.2
				AD 76-07-12 CW Suth AD 78-04-03 Spin Due	4329.1 TOTAL TIME
				Date 5/8s/8 Tach 3 % 8	J.F. Aviation Inc.
				Tourity that this Aircraft liague has been inspected in accordance	4000 W. Jefferson St. Joliet, IL 60431
				with an Annate inspection & was determined to be in sirworthy condition	10
					18 IA342882

ns ..)