DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERF SIGNATURE & CERTIFICATE NO. OF PERSON	ORMED— N PERFORMING WORK	
		TOTAL bro	ught forward from previous page		
			<u> </u>		
				143	
					9
				2	
-0	MAKE Cessna MCOEL 208B	=	Trident Aircraft Maintenance, Inc.	DATE: 17 April: 2012 A/C TSN: 1205.7	
	S/N 20880935 REG. NO N900J WORK ORDER	⊕ TR	200 Airport Road Suite A Stevensville, MO 21888	HOBBS 1205.7	
	536-03-2012 Airframe Ent	ries	Phone: 410:804.1333	<u> </u>	
_	(4) Tightened of aircraft Oxygen wick P/N C592	system IAW mail	able clamps at both ends and cable end bolt at valve. Verified operation an idenance manual ch 12-12-01 (10) Replaced broken static wick on left el	d flow (8) Serviced evator with new static	
			A		
_	DATE: 17 April	the desired to the same of the		Werk Order: 536-03-2012 EBis 3 (datcomedia.com)	
-			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
			<u> </u>	1.2	

	TOTAL	TACH OR		MANUEL MA	Page No
DATE	IN SERVICE	RECORDING METER TIME	DESCRIPTIO SIGNATURE & CERTIFICA	ON OF WORK PERFORMED— TE NO. OF PERSON PERFORMIN	NG WORK
		TOTAL broug	ght forward from previous page		148
	MAKE C	essne Tride	ent Aircraft Maintenance, Inc.		V. 16.5
	MODEL:: S/N: 2086 REG. NO	30935	port Road	DATE: 13 June, 2012 A/C TSN: 1216.9	
	WORK O	ROER: Stevens	Wille, MD 21566	TACH:	
		ne Entries	410.604.1333	-	
	—— (2) Tigh	itened oxygen nush	Dull cable clamps at both ands and cable	ME DOWN V. V. WALLES SHOOT- CONT.	
	flow S1628-	(5) Installed new sea 337, AND S2418-3.	pull cable clamps at both ends and cable end boi ils and related parts in nose gear strut, P/N MS2	at valve. Verified operation and 8775-337, MS28775-236,	
	DATE: 1	3 June, 2012	SIGNED: Donald Phty	Work Order: 622-05-2012	
			Donald Purtell, A&P: 3030561	Printed by EBis 3 (datcomedia.com)	
				1 ,	
				2	
				94	
				-	
	-0		1 of 1		
			AIDADED	TD	
	-		AIREREPA	AIK .	7
- 1			AIR REPAIR, INC. 29137 NEWNAM UNIT 8 - EA	STON, MD 21601	1
	D-1 0"				1 _
	Date: 8/0	06/2012; Aircraft:	N900JA; Type: CESSNA CARAVAN 208	B; S/N: 208B0935; Hobbs: 1245.10	; Tach:
	CAPACIT	ED WITH CAP CH	HECK OF BATTERY P/N RG-380E/44, S/	N 40318969. BATTERY PASSED	AT 98%
	The aircra	off aircraft engine	or configuration of		-
	- current m	aintenance rules	e, or appliance identified above was repair of the Federal Aviation Regulations and is ls of the repair are on file at this repair sta	ed and/or inspected in accordance approved for return to service for	with the work
-	Signed	XX		MISS BIRDE FEORING ONDER #12-03	15. 9
	o.g.i.o.g	gnature of autho	rized representative) CRS#XR5R175Y		1
	- 57		.,,		1 -
	SW 127				. ·
- 1	1	3.01			- T
	KE Cessna		Trident Aircraft Maintenance, Inc	DATE: 07 Augus A/C TSN	t, 2012 1245 1
9/	DDEL: 2088 N: 20880935	THIDEN	200 Airport Road	HOBBS	
	G. NO: N900JA ORK ORDER:	Dissolumnia	Stevensville, MD 21666		
68	6-07-2012		Phone: 410.604 1333		
51.73	irframe Entri				-
(2) C/W Cessna (Caravan 1 208B Pha	secard Mini check inspection Per pages 1 through fit yoke PTT mic switch with new switch and veri	ph 3 of the minicheck checklist dated fied operation (4) Assisted Donald Pur	tell
re-	move P3 filter to	o be sent out for clea	aning and installed new filter PN 3029268 with ne	w o-rings (5) Stop drilled crack in oil o	cooler
- nt	ossure regulato	or lines and fittings for	new cleveland brake pads on left and right brake or leaks, none detected, adjusted regulator up to	18 psi, IAW 208 MM ch. 36-10-00 par. 6	and
7.	(9) Checked anual ch. 12-12	for new and reocurri	ng ADs and SBs (10) Serviced aircraft oxygen	bottle to 1850 psi IAW 208 maintenance	
	aintenance Releas				
7.55			A was repaired and inspected in accordance with curren	t FARs rules of the Federal Aviation Regulation	sand
96	e aircran andror c as found Airworth	amponent(s) on Nation y for return to service	The space of the s	- The take a set of partial comment the Breatant	V 41/00/2
	ATE: 07 August	2012 SIGN	ien /	Work Order: 686-07	7-2012

Carry lorward to next page

ATE	TOTAL TIME A IN SERVICE	TACH OR JECORDING METER TIME	DESCRIPTION SIGNATURE & CERTIFICAT	N OF WORK PERFORM E NO. OF PERSON PE	MED- ERFORMING WORK
1	Eme	rald Coast	Aviation		1
Orde S/N:	e: CESSNA er No.: 1796 208B0935		Model: 208B Hobbs Time: 1257.20		Reg. No.: N900J/ pleted: 08/17/12 00:00 TTAF
1. F	11/1	tire with owner supp	Polied tire. Installed new 22x8.0-8 Robert P. Kilbourne A&P 34		assembly,
	_	Skylech,	*		. Westminster, MD 21157 4 / Fax: (410) 848-8451
1)	- W/O; D	og Entry September 4, 2012 MW-101033	Hobbs: 1284.5 Total Time: Cycles:	Registration #: Make/Model: S/N:	N900JA Cessna 208B 208B0935
	MAINTENAN The aircraft	CE RELEASE	pring inspection IAW Cessna 208 MM Rev. I and RH MLG springs (Zone 1) by removing and re-installed fairings. If above was repaired and inspected in accordance with respect to the work performed. Perfin 101033. for Skytech, Inc. 200 Airport Dr. Westmins	nce with current Federal Aviatio	ucture noted at
	à.				
-	MAKE Cassita	200 Airport Road	ft Maintenance, Inc.	DAT	E 07 September 2012 A/C TSN: 1289 7 HOBBS: 1289 7
+	MODEL 2086 Sin 208B0935 REG NO N900JA WORK ORDER 720-08-2012 Airframe Entries (5) Removed and N		3		

SUB-TOTAL this page

DATE

TOTAL TIME IN SERVICE

TACH OR RECORDING METER TIME

DESCRIPTION OF WORK PERFORMED-SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

MAKE Cessna MODEL 208B S/N: 208B0935 REG NO N900JA WORK ORDER 778-10-2012

Trident Aircraft Maintenance, Inc.

200 Airport Road Suite A Stevensville, MD 21666 Phone: 410 604 1333

DATE 23 October 20 A/C TSN 1350 HOBBS 1350

Airframe Entries

(1) C/W Cessna Caravan 1 208B Phasecard Mini check inspection Per pages 1 through 3 of the minicheck checklist dated 9/30/2008 Rev 08-1 ... (2) Installed new GE-4626 lamp, right taxi lamp. Checked operation, found no defects... (3) Right wing courtesy light, cleaned contacts on bulb socket and installed new GE-306 lamp. Operational check ok... (4) Replaced left main brake liners with new P/N RA066-03300.... (5) Replaced right main brake liners with new P N RA066-03300.... (6) Dressed prop blades as needed.... (8) Serviced nose to 42 psi, and mains to 57 psi. I/A/W Cessna 208 MM Chapter 32.... (9) Removed and

Maintenance Release

The aircraft and/or component(s) on N900JA was repaired and inspected in accordance th current FARs rules of the Faceral Aviation Regulations and was found Airworthy for return to service

DATE: 23 October, 2012

SIGNED 100 Donald Purtel: A&P 3030561

Work O:der: 778-10-2012

Printed by EBis 3 (datcomedia.com)

1 of 1

MAKE Cessna MODEL: 2088 S/N: 208B0935 REG. NO: N900JA WORK ORDER 781-10-2012



Trident Aircraft Maintenance, Inc.

200 Airport Road Suite A Stevensville, MD 21686 Phone 410 604 1333

DATE 12 November 2012 A/C TSN: 1379 1 HO68S: 1379 1

Airframe Entries

(1) C/W Cessna Service Bulletin CAB11-5 for ICA. Conversion to Cessna Task-Based Inspection Program. Completed Annual replaced Stand by Alternator control unit (2618500-1) with new ACU same PN. Verified output voltage IAW 208 MM chapter 24-36-00.... (6) Removed left engine intake inertial separator. Repaired crack in fiberglass wrap on engine air intake duct. Repaired crack IAW Cessna SRM section 51-73 Reinstalled inertial separator and saffied, verified correct operation.... (7) Installed placard for max baggage in rear cargo area IAW POH section 2-31.... (8) Replaced outboard and center rod ends with new P/N S1105-3. S1005-4 and S1104-3. Replaced inboard rod ends P/N 2654029-20 IAW Cessna maintenance manual chapter 78.... (9) Replaced right wing fuel cap lanyard P/N MS27380-3. Replaced right and left fuel cap o-rings P/N MS29513-338. All work done IAW Cessna maintenance manual chapter 28.... (10) Installed new fire extinguisher, Pilots door mount P/N RT-A600.... (11) Removed and replaced right brake pad shim with new shim PN 068-02800... (12) Replaced O-rings in both break calipers and serviced brakes with Mil-H-5606.... (13) Installed shirns on the shirnmy damper mounting bracket achieved a .025 vertical movement.... (14) Re-torque and safety wired nose gear spring yoke mounting bolts to 85 lbs.in.l/A/W C-208B MM Chapter 32-20-01 pg 205.... (15) saftied emergency power lever IAW Cessna maintenance manual Chapter 76... (16) Removed and replaced both right and left P/P rod end sets for both flaps, P/N S3060-H3.... (17) Right Flap Cable Tension Adjusted to 30 lbs. Turnbuckle safety wired with all threads engaged.... (19) Rigged Left and Right Flap to Manufacturer's specification IAW Cessna 208 Chapter 27-50-02. Operational check satisfactory.... (21) Serviced Oxygen IAW MM 12-12-01.... (22) Installed new roll servo P/N 065-00179-0100.... (23) Rudder stops safety wired.... (25) Checked ELT IAW 91.207(d), found no defects. ELT battery next due: Oct. 2015.

Maintenance Release

The aircraft and/or component(s) on NSCOJA was repayed and inspected in accordance with cupeful ARs rules of the Federal Aviation Regulations and was found Airworthy for return to service

DATE: 12 November, 2012

SIGNED: AL

Work Order: 781-10-2012

Donald Purteil, IA: 3030561

Printed by EBis 3 (datcomedia.com)

SUB-TOTAL this page

-	TIME REC	CH OR CORDING IETER TIME	DESCRIPTI SIGNATURE & CERTIFIC	ON OF WORK PERFORMED— ATE NO. OF PERSON PERFORMING WORK	
	MAKE: Cessna MODEL: 2088 SW: 20889939 REG. NO: N990JA WORK ORDER: 793-11-2012	O morning	Trident Aircraft Maintenance, Inc. 200 Airport Road Side A Side A Side A Side No. 21666 Phone: 410.604, 1333	DATE: 14 November, 2012 A/C TSN: 1379,1 HOBBS: 1379,1	
	(1) Installed n IAW Cessna I	ew trim tab right ailer MM and AC 43,13-18	on hinge parts P/N's 2624012-7, 26240 Chap 4, Sec 4.	112-10, and 2624012-16. Installed	
	Maintenance Re The aircraft and Aviation Regula	(or components) on Nor	20JA was repaired and inspected in accordance worth, for return to service.	nce with current FARs rules of the Federal	
	DATE: 14 Nover		D. Danalot Hite Purtell, A&P: 3030561	Work Order: 793-11-2012 Printed by EBis 3 (datcomedia.com)	
	-				
S/T RE	AKE Cessna ODEL 208B N 208B0935 SG NO N900JA	THIDENT	Trident Aircraft Maintenance 200 Airport Road Suite A	e, Inc. DATE 16 January 2013 ACTSN 1471 4 HDBBS 1471 4	-
82	ORK OROER 1-12-2012 rframe Entries		Stevensville. MO 21888 Phone: 410 804 1333	· · · · · · · · · · · · · · · · · · ·	-
ins	spection, found no		ed with St. CAL-53-02 by visual inspect	od all inspection tems due in the next 12 months () Complied with SL CAL-53-01 by visual tion, found no defects (7) Performed battery	
M±	intenance Release				L
	e aircraft and/or comp s found Airworthy for TE: 16 January, 2		repaired and inspected in accordance with o	current FARs rules of the Federal Aviation Regulations and	-
	TE. 10 Sandary, 2		tell, IA. 3030561	Work Order: 821-12-2012 Printed by EBis 3 (datcomedia.com)	1
	¥2		1 of 1		
	es el n			_	
MC S/N RE WC	IKE Cessna IDEL 2088 I 20880935 G NO N900JA DRK ORDER 3-03-2013	Trident Airca 200 Airport Road Suite A Stevensville MD : Phone 410.604.1		DATE 13 March, 2013 A/C TSN 1543.7 HOBBS 1543.7	
MC S/N RE WC 913 Air (1)	POEL 2088 1 20880935 5 NO N900JA DRK ORDER 3-03-2013 rframe Entries Removed and rep	200 Airport Road Suite A Stevensville MD : Phone 410,604.1	21666 333	A/C TSN 1543.7	
MC S/N RE WC 913 Aii (1) 80-	DEL 2088 i 20880935 g NO: NBCOJA DRIK ORDER 3-03-2013 rframe Entries Removed and rep-	200 Airport Road Suite A Stevensville MD: Phone 410,604,1 blaced Starter General orrect operation.	21666 333	A/C TSN 1543.7 HOBBS 1543.7 HOBBS 1543.7 HOBBS 1543.7	
MC S/N RE WC 913 Aii (1) 80-	EDEL 2088 1 20880935 5 NO N900JA DRK ORDER 3-03-2013 rframe Entries Removed and rep	200 Airport Road Suite A Stevensville MD: Phone 410.604.1 placed Starter General correct operation.	21666 333	A/C TSN 1543.7 HOBBS 1543.7	

TOTAL TACH OR TIME DESCRIPTION OF WORK PERFORMED-RECORDING DATE METER SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING W SERVICE TIME TOTAL brought forward from previous page MAKE: Cessna MODEL 2088 DATE 18 April, 2013 A/C TSN 1564.5 Trident Aircraft Maintenance, Inc. S/N: 208B0935 200 Airport Road HOBBS: 1564.5 REG NO N900JA Suite A WORK ORDER Stevensville MD 21666 Phone 410 604 1333 852-01-2013 Airframe Entries (7) Completed 100hr inspection IAW Cessna's task based maintenance program Document 0A. Replaced both vacuum filters with new filters. Checked for new and reoccurring ADs and MSBs.... (8) Removed and replaced left main tire with new Michelin 8:50-10 tire and tube. Serviced with Nitrogen and reinstalled IAW MM.... (10) Completed Document 06 IAW Cessna's MM.... (11) Completed Document 10 IAW Cessna's MM.... (14) Applied wing walk compound to both step ladders into cockpit.... (15) Installed serviceable RG-380E/44 Concorde Battery S/N 40450482. Passed capacitance check with 102%.... (19) Set aileron trim cable tension to with in limits.... (21) Removed Hot plate and capped plug. Cleaned and buffed windshield.... (22) stop drilled crack in left plastic wing root fairing.... (23) Prepared all pneumatic boots with Goodrich shine master prep, and applied Goodrich shine master cosmetic treatment.... (24) Safetied standby flap switch guard.... (26) Removed Garmin 530 for internal battery replacement by West Air, and reinstalled (27) Reconnected ground wire for rear 115v outlet. I certify that this sincraft has been inspected in accordance with a 100 in spection and determined it to be in an anworthy condition at this time DATE: 18 April, 2013 SIGNED: Work Order: 852-01-2013 Brian Katherman, A&P, 3442048 Printed by EBis 3 (datcomedia.com), 1 of 1 ALOOPN Cessna 208B SN: 208B0935 TT: 1618.2 Airframe Repaired pilots window latch. Re-secured pilots vent knob. Removed and replaced Right main tire and tube with tube and serviced with nitrogen IAW maintenance manual chapter 12. Replaced all the brake linings on both mair new linings. Serviced oxygen IAW maintenance manual chapter 12. Brian Katherman A&P 3442048 May 30, 2013

SUB-TOTAL this page

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DES SIGNATURE & CE	CRIPTION OF WORK PERI RTIFICATE NO. OF PERSO	FORMED— N PERFORMING WORK
1	MAKE Cess MODEL 208 S/N, 208809 REG. NO. N WORK ORD 1026-08-201	98 7 900JA 25 PER	Trident Aircraft Ma PRIDENT 9475 Jet Lane Easton MD 2:601 Phone 443-365-0590		DATE: 26 August, 2013 A/C TSN: 1655.4 HOBBS: 1655.4
	Airframe			F	
	(2) Comple with new fill reoccurring with N2 IAV and replace	eted 100hr inspectio iter. Lubricated fligh i ADs and MSBs. AL IV Cessna 208B MM ad both main wheel	n IAW Cessna's task based maintena t controls and landing gear. Serviced in D update report printed and inserted in I chapter 12 (13) Replaced top nose bearing seals with new seals. Lubrica el left half (19) Reinstalled overhau	orakes and shimmy damper (4) Ito log book, Maintenance tracker Its strut plastic plug PN: EP40 with	Checked for new and updated (10) Serviced tires new plug (15) Removed
	certify that t	his aircraft has been in	spected in accordance wetra 100 hr inspect	ion and determined it to be in an airwo	rthy condition at this time
	DATE: 28 A	August, 2013	SIGNED		Work Order: 1026-06-2013
			Bran Katherman, A&P 3442048	Print	ed by EBis 3 (datcomedia.com)
MOD S/N REG WOR 1218	E Cessna EL 2086 20860935 NO: N900JA RK ORDER -11-2013	TRIDENT D Jacobs Girman	Trident Aircraft Maintenand 9475 Jet Lane Easton, MD 21801 Phone 443-385-0590	ce, Inc.	ATE: 22 November, 2013 A/C TSN 1748.1 HOBBS 1746.1
(1) In Docutester comp MSBe discs boot a 100-5 Repla wing & C5920 All wo	ly with FAR 91.2 s, and iCAs. Upds with new discs F adge dressing	orticing the check aga (1976) (2076) (50) Complated maintenance trep 164-22201 (65) (71) Re-atlached trap (75) Verified operation a-ice boot hose PN pitot tube (78) ReReplaced ELT batters done IAW the market ma	208B task based maintenance inspect and 20 IAW Cessna MM (46) Comp in in 3months (49) Completed Doc. eted task 5-20-01-280 Expanded reco acker (67) Re applied fillet seal to be acker in the seal of the sealed right and left wing root free saling edge of left flap vortex generator (73) Removed corrosion spots on 220010 (15") (75) Re seated lower eplaced right wing fuel cap o-ring (8 my PN 452-0133 with new battery that surfactures maintenance manuals and repaired and inspected in accordance with	20 task 25-60-720. ELT inspectified check. Checked for new and both MLG legs at trunion (68) Rish air ducts(70) Touched up the control of the contr	0-720. Battery on and test to reoccurring ADs, eplaced both brake te top of both MLG RPM indicator PN with paint (74) it Re sealed right new wicks PN eeration.
	22 November, 2	lie version	1/2-	A Indicated Avia	own regulations and
	- a reviember, 2		man IA: 3442048	Work O	der: 1218-11-2013
	1 =	STORY CHERE	1 of 1	Printed by EBis 3	(datcomedia.com)
-					
	su	B-TOTAL this	page	Fort Log BOOK ENTRY	ELECTRONICS, Inc. acts - CAGE Code 18560 auderdale, FL 33312
	тот	TAL-Carry forw	ard to next page	E.L.T. BATTERY REPLACEMENT DATE	Jan /2019

DATE

de

TOTAL TIME IN SERVICE

TACH OR RECORDING METER TIME

DESCRIPTION OF WORK PERFORMED-SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

MAKE: Cessna MODEL: 208B S/N 20880935 REG NO N900JA WORK ORDER 1299-01-2014



Trident Aircraft Maintenance, Inc.

9475 Jet Lane Easton MD 21801 Phone: 443-385-0590 DATE 07 February, 2014 A/C TSN 1771.9 HOBBS 1771.9

Airframe Entries

(2) Complied with Capacitance check of battery PN RG-380E/44 SN 40484919. Battery passed at 86%. Re-check again in 3

DATE: 07 February, 2014

Work Order: 1299-01-2014

Brian Katherman, A&P 3442048

Printed by EBis 3 (datcomedia.com)

J.A. AIR CENTER

Aurora Airport • Sugar Grove, IL 60554 FAA Repair Station #NF2R029L AIRFRAME LOG ENTRY

208B s/N 208B0935 900JA

Description of work done:

Tested Altimeter(s), Altitude Reporting and Static System(s) in accordance with Part 43, Appendix E for compliance with

FAR 91.411 and FAR 91.413. Pilot Altimeter P/N KEA-130A S/N 32507

Range.

Copilot Altimeter P/N 5934PA-3 S/N 422812

Range

Transponder tested in accordance with Part 43, Appendix F for compliance with FAR 91.413 this date.

Date May 14

-Make_Garmin

GTX330 - Model -

S/N_84111477

25k

MAINTENANCE RELEASE

Doug Mall Inspector (print)....

SUB-TOTAL this page

MAKE: Cessna MODEL: 208B S/N: 208B0935 REG. NO: N900JA WORK ORDER: 2337-02-2014



J.A. Air Center

Répair Station No. NF2R029L 43W730 US RT 30 Sugar Grove, Illinois 60554 Phone: 630 584 3200 DATE: 02 May, 2014 A/C TSN: 1779.8 Landings: 1780 HOBBS: 1779.8

Airframe Entries

- Removed propeller (Model # 3GFR34C703-B S/N 011494) from aircraft N900JA S/N 208B0935 and sent for overhaul. Original propeller found to be unserviceable by Aircraft Propeller Services.

 Installed overhauled Propeller (Model#3GFR34C703B/106GA-0, S/N 051003) with a total time of 1024.7 and 0.0 time since overhaul on Aircraft Cessna 208B N900JA S/N 208B0935. Propeller was removed from Cessna 208 C-FFCL S/N 20800301 in servicable condition. Propeller overhauled by Intercontinental Jet service corporation CRS IZ2R916K W0#2183-61-1 reference 8130-3 dated 14-Apr-2014. Work done in accordance with C208B maintenance manual chapter 61-11-00
- 4 Removed worn propeller de-ice brush block assembly and installed new block assembly P/N C40257. Work done in accordance with Cessna 208 maintenance manual chapter 30-60-00.
- 6 Replaced vacuum filter using (1) AAD9-18-1 and vacuum relief filter with (1) ARB3-5-1.
- Removed propeller primary governor P/N 8210-002 S/N 11420101 to comply with 3800hr/72month overhaul. Reinstalled governor after OVERHAUL by Aircraft propeller service #EY2R811K reference 8130-3 dated 26/MAR/2014 WO# 113135/60-4263. Next overhaul required in 6 year or 4500 hrs per SB 33580M.
- 10 Removed propeller over-speed governor P/N D210507W S/N 13051089 to comply with 4500hr/72month overhaul. Reinstalled OVERHAULED governor after OVERHAUL by Aircraft Propeller Service #EY2R811K reference 8130-3 dated 26/MAR/2014 WO# 113136/60-4263. Next overhaul due in 6500hrs or 6 years per SB 33580M.
- 12 Installed R134A Air Conditioner System as per Cessna Service Bulletin CAB05-11 using used serviceable condenser assy, evaporator assys, blowers, compressor and compressor drive, LH lower cowl and close outs. All new Cessna OEM parts needed to completed the installation were used. Installed required POH supplement D1352-S7-00. The aircraft was weighed on Certified Jack Point Load Cells after all work was completed.
- 15 Removed the air conditioning drive seal and installed a new seal P/N 3022375 and o-ring P/N AS3209-029.
- Installed Aero Twin, Inc. P/N AP8-100 Auxiliary Dry Air Pump Kit S/N R322 as per STC SA4626NM Fabrication and installation of Aero Twin, Inc. Auxiliary Dry Pump Kit No. AP8-100 in accordance with Aero Twin, Inc Master drawing List No. AP8-100, dated April 20, 1990, or later FAA approved revisions. System is to be maintained as per Aero Twin, Inc. Instructions for Continued Airworthiness Document No. AP8-ICA. Revised the aircraft weight and balance and equipment list.
- 17 Removed damaged fire loop segments (P/N 644-040303416 and 644-13403485) from firewall and disconnected from wiring harness. Installed new loop segments and connected to wiring harness. Routed loop segments and secured with existing insulators and stand offs. Work done in accordance with C208B maintenance manual chapter 26-10-00 and C208B wiring diagrams chapter 26-10-01-01. Operational check of system satisfactory.
- 18 Removed two Mid Continent 115VAC static inverters (P/N MD50, S/N H11-10816 and S/N M11-10936). System was disabled, all wiring was capped and stowed. Aircraft was weighed on certified load cells. A revised weight and balance was placed in the Aircraft flight manual.
- 20 Removed damaged center fire loop segment and installed new segment P/N 140303 using new and existing insulators and stand-offs. Work done in accordance with C208B maintenance manual chapter 26-10-00. Operational test of system satisfactory.
- 21 Installed primary exhaust duct with new flange assembly P/N 2654006-10 work done in accordance with C208B maintenance manual chapter 78-10-00.
- Ran aircraft and verified engine control freedom and operation. Adjusted low idle speed to 52-55% with 40 amp generator load and bleed air heat on. Secured and safetied low idle adjust screw. Inspected all remaining linkages and connections for security and safety. Engine control parameters meet specifications in accordance with C208B maintenance manual chapter 76-10-02 and 76-10-03.
- Removed all eight Cessna single seats for 8 place configuration. Installed 11 place seating removed from 208B S/N 208B1126 configuration including crew seats, 3 LH single seats and 3 RH bench seats. Seats positioned in reference to POH supplement for STC-ST00026AT. Weight and Balance has been revised and placed in the POH.
- 24 Aircraft weighed on certified jack point load cells with full oil, all fuel drained after installation of factory air conditioning. Aero Twin Aux Vacuum System, installation of 11 place seats and removal of additional inverters and plugs.

Aircraft as weighted

	Weight	Arm	Moment
Nose jack point	1620.00	100.00	153000.00
LH main jack point	1780.00	227.44	404843.20
RH main jack point	1828.00	227.44	415760,32
Drainable unusable fuel	24.10	206.40	4974.24

New aircraft empty weight 5252.10 New aircraft useful load 3497.90 New aircraft EWCG 188.03

- Removed oil cooler and forward wiring harness to access oil pressure line to reduction gear case. Removed forward transfer casting and associated lines. Found cut packing at reduction gear case replaced packing and reinstalled oil cooler and harness. Serviced oil system and no further leakage note from oil pressure line. Work done accordance with PT6A-114A maintenance manual chapter 79-20-01.
- 26 Glareshield was stripped from the exisiting coverings and recovered in FR2250A/SKD-7 black IZIT Leather
- 27 Removed Torque gauge P/N 2606011-3, S/N M21201, MFG. TYPE MD82-3. Installed Serviceable unit P/N 2606011-3, S/N C05-11513 from Cessna 208B S/N 208B1126 . MFG. Type MD82-3.
- Drained oil from reduction gear box and removed transfer casting and tube. Replaced packings and reinstalled transfer casting and tube.

Maintenance Release

The aircraft, engine, appliance or component identified was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station CRS NF2R029L and EASA.145.5424 under Work Order No. 2337-02-2014, Dated 02 May, 2014.

DATE: 02 May, 2014

SIGNED

Work Order: 2337-02-2014

Printed by EBis 3 (datcomedia.com)

Jon Hilgenberg Certified Repair Station No. NF2R029L



N900JA ACTT 1835.7 CYCLES 1824 LANDINGS 1869 HOBBS N/A

C/W Cessna 208B Caravan Phasecard Inspection – Mini-Check 1 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 208B Caravan Phasecard Inspection – Mini-Check 1 and was determine to be in airworthy condition.

DATE 6/9/2014

Bo Johnson A&P 263064249

N900JA ACTT 1920.6 CYCLES 1905 LANDINGS 1952 HOBBS N/A DATE 6/21/2014

C/W Cessna 208B Caravan Phasecard Inspection ~ Phase 1 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 208B Caravan Phasecard Inspection ~ Phase 1 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249 7504150~

N900JA ACTT 2011.1 CYCLES 1996 LANDINGS 2044 HOBBS N/A DATE 7/7/2014

C/W Cessna 2088 Caravan Phasecard Inspection - Mini-Check 2 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 2088 Caravan Phasecard Inspection - Mini-Check 2 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249 Bo \$2000

N900JA ACTT 2108.4 CYCLES 2091 LANDINGS 2141 HOBBS N/A DATE 7/22/2014

C/W Cessna 208B Caravan Phasecard Inspection – Phase 2 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 208B Caravan Phasecard Inspection – Phase 2 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249 Ballow

N900JA ACTT 2202.6 CYCLES 2185 LANDINGS 2243 HOBBS N/A DATE 8/6/2014

C/W Cessna 2088 Caravan Phasecard Inspection – Mini-Check 3 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 2088 Caravan Phasecard Inspection – Mini-Check 3 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249 Balloo

N900JA ACTT 2307.6 CYCLES 2285 LANDINGS 2344 HOBBS N/A DATE 8/20/2014

C/W Cessna 2088 Caravan Phasecard Inspection — Phase 3 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 2088 Caravan Phasecard inspection —Phase 3 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249

N900JA ACTT 2406.6 CYCLES 2381 LANDINGS 2446 HOBBS N/A DATE 9/8/2014

C/W Cessna 2088 Caravan Phasecard Inspection — Mini-Check 4 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 2088 Caravan Phasecard Inspection — Mini-Check 4 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249 Bod Ania

C/W Phase 3 items Interior and exterior placard and decal detailed inspection, Brake system serving, shimmy damper servicing, landing gear lubrication, N/A-Hartzell propeller lubrication, static discharge system functional check, N/A- marathon ni-cad battery functional check, N/A- cargo nets detailed inspection, flight control lubrication, stall warning system operation check, flap tracks and rollers lubrication, fuel vent line float valve operational check, fuel filler assembly detailed inspection, bleed air pressure regulator functional check, shimmy damper functional check, pitot tube heaters operational check, N/A- portable oxygen mask detailed inspection, emergency power lever annunciator light. I certify that this aircraft has been inspected IAW cessna 208B Caravan phasecard inspection – phase 3 and was determined to be airworthy condition.

Brian Zeigler 3784418 A&P Bum S

N900JA ACTT 2499.1 CYCLES 2467

LANDINGS 2534

HOBBS N/A

DATE 09/23/2014

C/W Phase 4 items Interior and exterior placard and decal detailed inspection, Brake system serving, shimmy damper servicing, landing gear lubrication, N/A-Hartzell propeller lubrication, static discharge system functional check, N/A- marathon ni-cad battery functional check, N/A- cargo nets detailed inspection, flight control lubrication, stall warning system operation check, flap tracks and rollers lubrication, fuel vent line float valve operational check, fuel filler assembly detailed inspection, bleed air pressure regulator functional check, shimmy damper functional check, pitot tube heaters operational check, N/A- portable oxygen mask detailed inspection, emergency power lever annunciator light. I certify that this aircraft has been inspected IAW Cessna 208B Caravan phasecard inspection - phase 4 and was determined to be airworthy condition.

Brian Zeigler 3784418 A&P Ba M 3

ACTT 2499.1

CYCLES 2467

LANDINGS 2534

HOBBS N/A DATE 9/23/2014

C/W Cessna 2088 Caravan Phasecard Inspection -- Phase 4 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 2088 Caravan Phasecard Inspection - Phase 4 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249

ACTT 2604.6

CYCLES 2590

LANDINGS 2656

HOBBS N/A DATE 10/22/2014

C/W Cessna 208B Caravan Phasecard inspection - Mini-Check 5 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 208B Caravan Phasecard Inspection - Mini-Check 5 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249

ACTT 2706.4

CYCLES 2691

LANDINGS 2759

HOBBS N/A DATE 11/13/2014

C/W Cessna 208B Caravan Phasecard Inspection - Phase 5 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 2088 Caravan Phasecard Inspection - Phase 5 and was determine to be in airworthy condition.





C/W Phase 5 items Interior and exterior placard and decal detailed inspection, Brake system serving, shimmy damper servicing, landing gear lubrication, N/A-Hartzell propeller lubrication, static discharge system functional check, N/A- marathon ni-cad battery functional check, N/A- cargo nets detailed inspection, flight control lubrication, stall warning system operation check, flap tracks and rollers lubrication, fuel vent line float valve operational check, fuel filler assembly detailed inspection, bleed air pressure regulator functional check, shimmy damper functional check, pitot tube heaters operational check, N/A- portable oxygen mask detailed inspection, emergency power lever annunciator light. I certify that this aircraft has been inspected IAW Cessna 208B Caravan phasecard inspection – phase 5 and was determined to be airworthy condition.

Brian Zeigler 3784418 A&P

Br M

N900JA ACTT 2804.9

CYCLES 2784

LANDINGS 2853

HOBBS N/A DATE 12/4/2014

C/W Cessna 2088 Caravan Phasecard Inspection - Mini-Check 6 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 2088 Caravan Phasecard Inspection - Mini-Check 6 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249

3

N900JA ACTT 2905.8

CYCLES 2877

LANDINGS 2946

HOBBS N/A DATE 12/31/2014

C/W Cessna 2088 Caravan Phasecard Inspection – Phase 6 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 2088 Caravan Phasecard Inspection – Phase 6 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249

Bo JAnon

N900JA ACTT 3006.6

CYCLES 2981

LANDINGS 3051

HOBBS N/A DATE 3/22/2015

C/W Cessna 2088 Caravan Phasecard Inspection – Mini-Check 7 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 2088 Caravan Phasecard Inspection – Mini-Check 7 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249

Bothon

- N900JA ACTT 3105.4

CYCLES 3088

LANDINGS 3142

HOBBS N/A DATE 4/3/2015

C/W Cessna 2088 Caravan Phasecard Inspection – Phase 7 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this alreraft has been inspected in accordance with Cessna 2088 Caravan Phasecard Inspection – Phase 7 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249

Bo Assa

DOD-TOTAL TITO Page

- N900JA ACTT 3194.9 CYCLES 3185 LANDINGS 3234 HOBBS N/A DATE 4/29/2015

C/W Cessnit 208B Caravan Phasecard Inspection — Mini-Check 8 IAW Cessnit 208 MM, PWC Mt* ** Cauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessnit 208B Caravan Phasecard Inspection — Mini-Che. ** And was determine to be in airworthy condition.

Bo Johnson A&P 263064249

N900JA ACTT 3284,5 CYCLES 3291 LANDINGS 3335 HOBBS N/A DATE 5/13/2015

C/W Cessna 208B Caravan Phasecard Inspection – Phase 8 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 208B Caravan Phasecard Inspection – Phase 8 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249 30 130

N900JA ACTT 3359.6 CYCLES 3366 LANDINGS 3408 HOBBS N/A DATE 5/30/2015

C/W Cessna 208B Caravan Phasecard Inspection – Mini-Check 9 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 208B Caravan Phasecard Inspection – Mini-Check 9 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249 Bo Aloa

N900JA ACTT 3456.0 CYCLES 3523 LANDINGS 3498 HOBBS N/A DATE 6/23/2015

C/W Cessna 208B Caravan Phasecard Inspection – Phase 9 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 208B Caravan Phasecard Inspection – Phase 9 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249 Bo

N900JA ACTT 3540.2 CYCLES 3603 LANDINGS 3578 HOBBS N/A DATE 7/10/2015

C/W Cessna 2088 Caravan Phasecard Inspection – Mini-Check 10 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 2088 Caravan Phasecard Inspection – Mini-check 10 and was determine to be in airworthy condition.

Bo Johnson ABP 263064249 Bo Alaco

N900JA ACTT 3626.4 CYCLES 3683 LANDINGS 3658 HOBBS N/A DATE 7/30/2015

C/W Cessna 2088 Caravan Phasecard Inspection – Phase 10 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 2088 Caravan Phasecard Inspection – Phase 10 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249 BoAloo

N900JA ACTT 3711.5 CYCLES 3766 LANDINGS 3741 HOBBS N/A DATE 8/28/2015

C/W Cessna 208B Caravan Phasecard Inspection – Mini-Check 11 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 208B Caravan Phasecard Inspection – Mini-Check 11 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249 Bo \$200

N900JA ACTT 2905.8 CYCLES 2877

LANDINGS 2946

HOBBS N/A

DATE 12/31/2014

C/W Phase 6 items Interior and exterior placard and decal detailed inspection, Brake system serving, shimmy damper servicing, landing gear lubrication, N/A-Hartzell propeller lubrication, static discharge system functional check, N/A- marathon ni-cad battery functional check, N/A- cargo nets detailed inspection, flight control lubrication, stall warning system operation check, flap tracks and rollers lubrication, fuel vent line float valve operational check, fuel filler assembly detailed inspection, bleed air pressure regulator functional check, shimmy damper functional check, pitot tube heaters operational check, N/A- portable oxygen mask detailed inspection, emergency power lever annunciator light. I certify that this aircraft has been inspected IAW Cessna 208B Caravan phasecard inspection – phase 6 and was determined to be airworthy condition.

Brian Zeigler 3784418 A&P

N900JA ACTT 3105.4 CYCLES 3088

LANDINGS 3142

Bu M

HOBBS N/A

DATE 4/3/2015

C/W Phase 7 items Interior and exterior placard and decal detailed inspection, Brake system serving, shimmy damper servicing, landing gear lubrication, N/A-Hartzell propeller lubrication, static discharge system functional check, N/A- marathon ni-cad battery functional check, N/A- cargo nets detailed inspection, flight control lubrication, stall warning system operation check, flap tracks and rollers lubrication, fuel vent line float valve operational check, fuel filler assembly detailed inspection, bleed air pressure regulator functional check, shimmy damper functional check, pitot tube heaters operational check, N/A- portable oxygen mask detailed inspection, emergency power lever annunciator light. I certify that this aircraft has been inspected IAW Cessna 208B Caravan phasecard inspection – phase 7 and was determined to be airworthy condition.

Brian Zeigler 3784418 A&P

N900JA ACTT 3284.5 CYCLES 3291

LANDINGS 3335

Bn m 88

Bu M ()

HOBBS N/A

DATE 5/13/2015

C/W Phase 8 items Interior and exterior placard and decal detailed inspection, Brake system serving, shimmy damper servicing, landing gear lubrication, N/A-Hartzell propeller lubrication, static discharge system functional check, N/A- marathon ni-cad battery functional check, N/A- cargo nets detailed inspection, flight control lubrication, stall warning system operation check, flap tracks and rollers lubrication, fuel vent line float valve operational check, fuel filler assembly detailed inspection, bleed air pressure regulator functional check, shimmy damper functional check, pitot tube heaters operational check, N/A- portable oxygen mask detailed inspection, emergency power lever annunciator light. I certify that this aircraft has been inspected IAW Cessna 208B Caravan phasecard inspection – phase 8 and was determined to be airworthy condition.

Brian Zeigler 3784418 A&P

SUB-TOTAL this page

ALOOGN ACTT 3194.9 CYCLES 3185

LANDINGS 3234

HOBBS N/A

DATE 4/29/2015

C/W Phase 9 items Autopilot servos lubrication, power distribution boxes detailed inspection, crew seats detailed inspection, passenger seats detailed inspection, spoiler system functional check, aileron trim tab actuator (2660044-1) lubrication, elevator trim tab actuator (2660017-1) lubrication, fuel quantity and low fuel warning systems functional check, flight data recorder underwater locator beacon functional check, brakes operational check, passenger/cargo compartment lighting operational check, crew doors detailed inspection, passenger/cargo doors and door frames detailed inspection, primary and secondary exhaust duct general visual inspection. I certify that this aircraft has been inspected iaw Cessna 208B caravan phasecard- phase 9 was determined to be airworthy condition. Bum &

Brian Zeigler 3784418 A&P

N900JA ACTT 3456.0 CYCLES 3523

LANDINGS 3498

HOBBS N/A

DATE 6/23/2015

C/W Phase 9 items Interior and exterior placard and decal detailed inspection, Brake system serving, shimmy damper servicing, landing gear lubrication, N/A-Hartzell propeller lubrication, static discharge system functional check, N/A- marathon ni-cad battery functional check, N/A- cargo nets detailed inspection, flight control lubrication, stall warning system operation check, flap tracks and rollers lubrication, fuel vent line float valve operational check, fuel filler assembly detailed inspection, bleed air pressure regulator functional check, shimmy damper functional check, pitot tube heaters operational check, N/A- portable oxygen mask detailed inspection, emergency power lever annunciator light. I certify that this aircraft has been inspected IAW Cessna 208B Caravan phasecard inspection - phase 9 and was determined to be airworthy condition.

Brian Zeigler 3784418 A&P

Bum XX

N900JA ACTT 3626.4 CYCLES 3683 LANDINGS 3658

HOBBS N/A

DATE 7/30/2015

C/W Phase 10 items Interior and exterior placard and decal detailed inspection, Brake system serving, shimmy damper servicing, landing gear lubrication, N/A-Hartzell propeller lubrication, static discharge system functional check, N/A- marathon ni-cad battery functional check, N/A- cargo nets detailed inspection, flight control lubrication, stall warning system operation check, flap tracks and rollers lubrication, fuel vent line float valve operational check, fuel filler assembly detailed inspection, bleed air pressure regulator functional check, shimmy damper functional check, pitot tube heaters operational check. N/A- portable oxygen mask detailed inspection, emergency power lever annunciator light. I certify that this aircraft has been inspected IAW Cessna 208B Caravan phasecard inspection - phase 10 and was determined to be airworthy condition.

Brian Zeigler 3784418 A&P

N900JA ACTT 3801.1 CYCLES 3844

LANDINGS 3819

HOBBS N/A

DATE 9/29/2015

C/W Phase 11 items Interior and exterior placard and decal detailed inspection, Brake system serving, shimmy damper servicing, landing gear lubrication, N/A-Hartzell propeller lubrication, static discharge system functional check, N/A- marathon ni-cad battery functional check, N/A- cargo nets detailed inspection, flight control lubrication, stall warning system operation check, flap tracks and rollers lubrication, fuel vent line float valve operational check, fuel filler assembly detailed inspection, bleed air pressure regulator functional check, shimmy damper functional check, pitot tube heaters operational check, N/A- portable oxygen mask detailed inspection, emergency power lever annunciator light. I certify that this aircraft has been inspected IAW Cessna 208B Caravan phasecard inspection - phase 11 and was determined to be airworthy condition.

Brian Zeigler 3784418 A&P

Bu M'

N900JA ACTT 2499.1 CYCLES 2467 LANDINGS 2534 HOBBS N/A DATE 9/23/2014 C/W Phase 4 Compressor drive belt functional check, nose landing gear detailed inspection. I certify that this aircraft has been inspected IAW Cessna 208B Caravan phasecard inspection - phase 4 and was determined to be airworthy condition.

Brian Zeigler 3784418 A&P Bu M

N900JA ACTT 3284.5 CYCLES 3291

LANDINGS 3335

HOBBS N/A

DATE 5/13/2015

C/W Phase 8 Compressor drive belt functional check, nose landing gear detailed inspection. I certify that this aircraft has been inspected IAW Cessna 208B Caravan phasecard inspection – phase 8 and was determined to be airworthy condition.

Brian Zeigler 3784418 A&P Ba M

N900JA ACTT 3194.9 CYCLES 3185

LANDINGS 3234

HOBBS N/A

DATE 4/29/2015

Removed Battery P/N RG-380E/44 S/N 40540543. Replaced P/N RG-308/44 S/N 40664672 IAW Cess. MM. 24-31-00. Ops check good. Aircraft returned to service for work performed.

Brian Zeigler 3784418 A&P

N900JA ACTT

CYCLES

LANDINGS

HOBBS N/A

DATE 1/16/2015

Removed Concorde Lead Acid Battery P/N RG-380E/44 SN: 40484919 due CAP check. Installed inspected battery of same part number SN: 40531659. (See TAG 8130-3) IAW: AMM 24-33-00. Ops checked correct. ACFT is returned to service for the work performed.

N900JA ACTT 2706.4

CYCLES 2691

Bu M

LANDINGS 2759

HOBBS N/A

DATE 11/13/2014

C/w Phase 5 items Avionics cooling fan operational check, Garmin autopilot (GFC 700) functional check, Garmin autopilot (GFC 700) slip clutch override operational check, Concord sealed lead acid battery functional check (cap check), flap actuator mount bracket detailed inspection, flap bellcrank detailed inspection. I certify that this aircraft has been inspected IAW Cessna 208B caravage phasecard inspection. Phase 5 was determined to be airworthy condition.

Brian Zeigler 3784418 A&P Bu M

N900JA ACTT 3194.9 CYCLES 3185 LANDINGS 3234

HOBBS N/A

DATE 4/29/2015

C/w Phase 9 items Avionics cooling fan operational check, Garmin autopilot (GFC 700) functional check, Garmin autopilot (GFC 700) slip clutch override operational check, Concord sealed lead acid battery functional check (cap check), flap actuator mount bracket detailed inspection, flap bellcrank detailed inspection. I certify that this aircraft has been inspected IAW Cessna 208B caravan phasecard inspection. Phase 9 was determined to be airworthy condition. pru MX

Brian Zeigler 3784418 A&P

HOUSE HELL STEEL SOLL HOUSE HAVE STEEL STEEL SOLL	N900JA	ACTT 3801.1	CYCLES 3844	LANDINGS 3819	HOBBS N/A	DATE 9/29/2015
---	--------	-------------	-------------	---------------	-----------	----------------

C/W Cessna 2088 Caravan Phasecard Inspection – Phase 11 IAW Cessna 208 MM, PWC MM, McCauley MM, and Seaport Airlines AAIP. I certify that this aircraft has been inspected in accordance with Cessna 2088 Caravan Phasecard Inspection – Phase 11 and was determine to be in airworthy condition.

Bo Johnson A&P 263064249

Bu Alma

	CUP TOTA	AL this page	
			6
		7/	nn
			9
	X .		
			10.7

N900JA ACCT 1920.6 CYCLES 1905 LANDINGS 1952 HOBBS N/A DATE 06/21/2014 C/W Phase 1 inspection items Nose landing gear drag link support servicing(airplanes incorporating CAB-32-02 only) B- M X Brian Zeigler 3784418 A&P N900JA ACCT 2108.4 CYCLES 2091 LANDINGS 2141 HOBBS N/A DATE 07/22/2014 C/W Phase 2 inspection items Nose landing gear drag link support servicing(airplanes incorporating CAB-32-02 only) Brian Zeigler 3784418 A&P Br. M N900JA ACCT 2307.6 CYCLES 2285 LANDINGS 2344 HOBBS N/A DATE 08/20/2014 C/W Phase 3 inspection items Nose landing gear drag link support servicing(airplanes incorporating CAB-32-02 only) Brian Zeigler 3784418 A&P Br M N900JA ACCT 2499.1 CYCLES 2467 LANDINGS 2534 HOBBS N/A DATE 09/23/2014 C/W Phase 4 inspection items Nose landing gear drag link support servicing(airplanes incorporating CAB-32-02 only) Brian Zeigler 3784418 A&P Bu M N900JA ACCT 2706.4 CYCLES 2691 LANDINGS 2759 HOBBS N/A DATE 11/13/2014 C/W Phase 5 inspection items Nose landing gear drag link support servicing(airplanes incorporating CAB-32-02 only) Brian Zeigler 3784418 A&P Bu M N900JA ACCT 2905.8 CYCLES 2877 LANDINGS 2946 HOBBS N/A DATE 12/31/2014 C/W Phase 6 inspection items Nose landing gear drag link support servicing(airplanes incorporating CAB-32-02 only) Brian Zeigler 3784418 A&P Bu M N900JA ACCT 3105.4 CYCLES 3088 LANDINGS 3142 HOBBS N/A DATE 04/3/2015 C/W Phase 7 inspection items Nose landing gear drag link support servicing(airplanes incorporating

Brian Zeigler 3784418 A&P Bu M

CAB-32-02 only)

CAB-32-02	er 3784418	A P D	.6	n	M					
brian zeig	ei 3704410	AGE	M	101	SU					
N900JA A C/W Phase CAB-32-02	ACCT 3456.0 9 inspection only)	CYCL	ES 3523 Nose landi	LANDIN	GS 3498 Irag link su	HOBBS N//	A DATE sing(airpla	06/23/201 nes incor	5 porating	
Brian Zeigl	er 3784418	A&P	Bu	m	&					
C/W Phase CAB-32-02	**	on items	Nose land	ding gear	drag link s	HOBBS N// upport serv	A DATE icing(airpl	07/30/201 anes inco	5 rporating	3
Prion Zoigle	er 3784418	A&P	Bon	M	0					
N900JA A C/W Phase CAB-32-02	CCT 3801.1 11 inspection	CYCL on items	ES 3844 Nose land	ding gear	drag link su					1
N900JA A C/W Phase CAB-32-02	CCT 3801.1	CYCL on items	ES 3844	ding gear	drag link su					1
N900JA A C/W Phase CAB-32-02	CCT 3801.1 11 inspection	CYCL on items	ES 3844 Nose land	ding gear	drag link su					1
N900JA A C/W Phase CAB-32-02	CCT 3801.1 11 inspection	CYCL on items	ES 3844 Nose land	ding gear	drag link su					J
N900JA A C/W Phase CAB-32-02	CCT 3801.1 11 inspection	CYCL on items	ES 3844 Nose land	ding gear	drag link su					
N900JA A C/W Phase CAB-32-02	CCT 3801.1 11 inspection	CYCL on items	ES 3844 Nose land	ding gear	drag link su					
N900JA A C/W Phase CAB-32-02	CCT 3801.1 11 inspection	CYCL on items	ES 3844 Nose land	ding gear	drag link su					
N900JA A C/W Phase CAB-32-02	CCT 3801.1 11 inspection	CYCL on items	ES 3844 Nose land	ding gear	drag link su					

N900JA ACTT 3,801.1 CYCLES 3,844

LANDINGS 3,819

HOBBS N/A

DATE 01/01/2016

Disassembled cleaned inspected lubed and reassembled RH Elevator Trim Tab Actuator P/N 2661215-1 IAW Cessna 208 MM 27-30-02. Op's check good. A/C BTS for work performed.

Brian Zeigler 3784418 A&P

N900JA ACTT 3,801.1 CYCLES 3,844 LANDINGS 3,819

HOBBS N/A

DATE 01/01/2016

Disassembled cleaned inspected lubed and reassembled LH Elevator Trim Tab Actuator P/N 2661215-1 IAW Cessna 208 MM 27-30-02. Op's check good. A/C RTS for work performed.

Brian Zeigler 3784418 A&P

Ban MX

N900JA ACTT 3,801.1 CYCLES 3,844 LANDINGS 3,819

HOBBS N/A

DATE 01/01/2016

Dissembled, inspected and lubricated aileron trim actuator IAW Cessna 208 MM 27-10-02. No defects noted. Acft. returned to service for work performed.

Brian Zeigler 3784418 A&P

N900JA ACTT 1920.6 CYCLES 1905

LANDINGS 1952

HOBBS N/A

DATE 06/21/2014

C/W Phase 1 items Interior and exterior placard and decal detailed inspection, Brake system serving, shimmy damper servicing, landing gear lubrication, N/A-Hartzell propeller lubrication, static discharge system functional check, N/A- marathon ni-cad battery functional check, N/A- cargo nets detailed inspection, flight control lubrication, stall warning system operation check, flap tracks and rollers lubrication, fuel vent line float valve operational check, fuel filler assembly detailed inspection, bleed air pressure regulator functional check, shimmy damper functional check, pitot tube heaters operational check, N/A- portable oxygen mask detailed inspection, emergency power lever annunciator light. I certify that this aircraft has been inspected IAW Cessna 208B Caravan phasecard inspection - phase 1 and was determined to be airworthy condition.

Brian Zeigler 3784418 A&P

N900JA ACTT 2108.4 CYCLES 2091

LANDINGS 2141

HOBBS N/A

DATE 07/22/2014

C/W Phase 2 items Interior and exterior placard and decal detailed inspection, Brake system serving, shimmy damper servicing, landing gear lubrication, N/A-Hartzell propeller lubrication, static discharge system functional check, N/A- marathon ni-cad battery functional check, N/A- cargo nets detailed inspection, flight control lubrication, stall warning system operation check, flap tracks and rollers lubrication, fuel vent line float valve operational check, fuel filler assembly detailed inspection, bleed air pressure regulator functional check, shimmy damper functional check, pitot tube heaters operational check, N/A- portable oxygen mask detailed inspection, emergency power lever annunciator light. I certify that this aircraft has been inspected IAW Cessna 208B Caravan phasecard inspection - phase 2 and was determined to be airworthy condition.

Brian Zeigler 3784418 A&P