

SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
11-19-03	2302.	930.	REMOVED PROP FROM 732 W.P.	
3-12-04	2302.2	22	<p style="text-align: center;">Removed for fusht.</p> <p style="text-align: center;">MAINTENANCE RELEASE</p> <p style="text-align: center;">THE AIRCRAFT AIRFRAME, ENGINE, APPLIANCE OR COMPONENT HAS BEEN REPAIRED AND INSPECTED TO MEET THE REQUIREMENTS OF THE FAA AND IS APPROVED FOR RETURN TO SERVICE.</p> <p style="text-align: center;">DATE: 3-12-04</p> <p style="text-align: center;">13003</p> <p style="text-align: center;">Ruei K. Kuehner</p> <p style="text-align: center;">FAA REPAIR STATION NF2R029L</p>	

SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
5/12/07	Propeller S/N 776652 TSN 2307.2 TSO 2.2			
	This propeller has been serviced as per the 8130-3 tag dated <u>03/18/04</u> under Work Order <u>70579</u>			
	Aircraft Propeller Service, Inc. Wheeling, Illinois			
	CRS EY2R811K		JAA.5126	

J A AIR CENTER DuPage Airport/West Chicago, IL. 60185 P 10
Repair Station #NF2R029L PROPELLER LOG #1
Type CESSNA T210M TT 2304
N # 732WP TSMOH 2
S/N 21061835 REC. HR. METER 2304

PROPELLER MODEL D3A34C402/90DFA-10
PROPELLER S/N776652

Authorized Signatures

REINSTALLED THIS PROPELLER ON THE ABOVE AIRCRAFT AFTER
FLUSH BY AIRCRAFT PROPELLER SERVICE.

I CERTIFY THAT THIS PROPELLER WAS REPAIRED AND/OR INSPECTED
IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS APPROVED FOR
RETURN TO SERVICE. PERTINENT DETAILS ARE ON FILE AT THIS
REPAIR STATION UNDER W.O.# 13002 . DATE 5-4-04

J.A. AIR CENTER, DUPAGE AIRPORT, WEST CHICAGO, IL. 60185
FAA APPROVED REPAIR STATION #NF2R029L

BRUCE P. REBECHINI

INSPECTOR

J A AIR CENTER DuPage Airport/WestChicago, IL. 60185 P 7
 Repair Station #NF2R029L PROPELLER LOG #1
 Type CESSNA T210M TT 2543
 N # 732WP TSMOH 241
 S/N 21061835 REC. HR. METER 2543

PROPELLER MODEL D3A34C402/90DFA-10
 PROPELLER S/N776652

PROPELLER INSPECTION-
 INSPECTED AND SERVICED THIS MCCAULEY PROPELLER FOR AN
 ANNUAL INSPECTION.
 I CERTIFY THAT THIS PROPELLER WAS REPAIRED AND/OR INSPECTED
 IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS APPROVED FOR
 RETURN TO SERVICE. PERTINENT DETAILS ARE ON FILE AT THIS
 REPAIR STATION UNDER W.O.# 14778 . DATE 3-17-06
 J.A. AIR CENTER, DUPAGE AIRPORT, WEST CHICAGO, IL 60185
 FAA APPROVED REPAIR STATION #NF2R029L

*
 * 
 BRUCE P. REBECHINI INSPECTOR

Date

To

Signatures

J A AIR CENTER DuPage Airport/WestChicago, IL. 60185 P 1
 Repair Station #NF2R029L PROPELLER LOG #1
 Type CESSNA T210M TT 2720
 N # 732WP TSMOH 41B
 S/N 21061835 REC. HR. METER 2720

PROPELLER MODEL D3A34C402/90DFA-10
 PROPELLER S/N776652


PROPELLER BLADES NICKED-
 CLEANED, FILED AND REPAINTED PROPELLER AS REQUIRED.
 I CERTIFY THAT THIS PROPELLER WAS REPAIRED AND/OR INSPECTED
 IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS APPROVED FOR
 RETURN TO SERVICE. PERTINENT DETAILS ARE ON FILE AT THIS
 REPAIR STATION UNDER W.O.# 16384 . DATE APRIL 7, 2008.
 J.A. AIR CENTER, DUPAGE AIRPORT, WEST CHICAGO, IL 60185
 FAA APPROVED REPAIR STATION #NF2R029L

* *Bruce P. Rebecchini*
 * BRUCE P. REBECCHINI INSPECTOR

ed Signatures

5

Certifies that the work specified in Blocks 12/13 was carried out in accordance with EASA Part-145 Approval Number "EASA 145.00000".
 A1639-2 NUT
 MIL-T-83483 ANTI SIEZE
 New
 New
 6
 1

Date	T	J A AIR CENTER AURORA AIRPORT/SUGAR GROVE, IL 60554 P 1		Signatures
		Repair Station #NF2R029L		
		Type CESSNA	T210M	
		N # 732WP	PROPPELLER LOG #1	
		S/N 21061835	TT 2793	
			TSMOH 491	
			REC. HR. METER 2793	
			PROPPELLER MODEL D3A34C402/90DFA-10	
			PROPPELLER S/N776652	
SMALL NICKS ON THE PROPPELLER BLADE LEADING EDGES: DRESSED BLADES AS NEEDED TO REMOVE SMALL NICKS. PROPPELLER DEICE BOOT EDGE SEALANT DETERIORATED: REMOVED REMAINING LOOSE SEALANT AND MASKED AREA TO BE SEALED. APPLIED COAT OF CS3201-A 1/2 BLACK SEALANT. I CERTIFY THAT THIS PROPPELLER WAS REPAIRED AND/OR INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS ARE ON FILE AT THIS REPAIR STATION UNDER W.O.# 17130. DATE MARCH 27, 2009 J.A. AIR CENTER, AURORA AIRPORT, SUGAR GROVE, IL 60554 FAA APPROVED REPAIR STATION #NF2R029L *  * DONALD K. MORGAN INSPECTOR				

Repair Station #NF2R029L

Type CESSNA 441

N # 732WP

S/N 21061B35

PROPELLER LOG #1

TT 2858

TSMOH 536

REC. HR. METER 2858

PROPELLER MODEL D3A34C402/90DFA-10

PROPELLER S/N776652

PROPELLER DEICE BOOTS PULLING AWAY FROM BASE OF EACH
BLADE-

APPLIED CS3201 A 1/2 SEALANT TO STRAPS AT BASE OF BOOTS
TO PREVENT FURTHER DAMAGE. DEICE BOOTS FOUND TO BE
OK AT THIS TIME. APPLIED CS3201A1/2 SEALANT TO BOOT EDGES
THAT WERE COMING LOOSE.

SPINNER MOUNTING SCREWS GOUGING DEICE POWER STRAPS-
REPOSITIONED STRAPS AND APPLIED SEALANT TO CHAFFED AREA
FOR FURTHER PROTECTION.

I CERTIFY THAT THIS PROPELLER WAS REPAIRED AND/OR INSPECTED
IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS APPROVED FOR
RETURN TO SERVICE. PERTINENT DETAILS ARE ON FILE AT THIS

REPAIR STATION UNDER W.O.#17893 . DATE MARCH 1, 2010

J.A. AIR CENTER, AURORA AIRPORT, SUGAR GROVE, IL 60554

FAA APPROVED REPAIR STATION #NF2R029L

* *Bruce P. Rebeckint*

BRUCE P. REBECHINT

INSPECTOR

ed Signatures

7

Certifies that the work specified in Blocks 12/13 was carried out in accordance with EASA Part 145 and in respect to that
work the component is considered ready for release to service under EASA Part 145 Approval Number "EASA 145.0100".
A1639-2 NUT
MIL-T-83483 ANTI SIEZE
New
1
6
New

1. Approving National Aviation Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 20387	
4. Organization Name and Address: AIRCRAFT PROPELLER SERVICE, INC. 290 LARKIN DRIVE WHEELING, IL 60090		5. Work Order/Contract/Invoice Number: 99160 / 80B8340 w/attached pages 1 thru 1 Dated: 09/03/2010			
6. Item: 1	7. Description: McCAULEY PROPELLER ASSEMBLY	8. Part Number: D3A34C402/90DFA-10	9. Eligibility: N/A	10. Quantity: 1.00	11. Serial/Batch Number: 776652
					12. Status/Work: REPAIRED

13. Remarks:

REPAIRED per: MPC400 R: 2 (6/1/2007)

COMPLIED WITH:

AD: NONE

S/B: NONE

S/L: NONE

OTHER: N/A

	SERIAL #	TSN	TSO/TSMI
ASSEMBLY:	776652	2908.6	606.0
HUB:	776652	2908.6	606.0
BLADE 1:	B70244	2908.6	606.0
BLADE 2:	B70233	2908.6	606.0
BLADE 3:	B70253	2908.6	606.0

The next action required on this component is within SEE LAST OVERHAUL.

Full detail of the work specified in Block 12 is on file within this agency.

J A AIR CENTER DuPage Airport/West Chicago, IL 60185 P 1
 Repair Station #29029L PROPELLER LOG #1
 Type CESSNA 500 TT 2908.6
 N # 732WP TSMOH 606.0
 S/N 21061885 REC. HR. METER 2908.6

PROPELLER MODEL D3A34C402/90DFA-10

PROPELLER S/N776652

PROPELLER FLUSH AND ANNUAL INSPECTION-
 REMOVED THIS PROPELLER AND SENT TO AIRCRAFT PROPELLER
 SERVICE FOR FLUSH. REINSTALLED ON TS10-520-R(9B) S/N
 1003074.

I CERTIFY THAT THIS PROPELLER WAS REPAIRED AND/OR INSPECTED
 IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS APPROVED FOR
 RETURN TO SERVICE. PERTINENT DETAILS ARE ON FILE AT THIS
 REPAIR STATION UNDER W.O.# 18340. DATE OCTOBER 6, 2010
 J.A. AIR CENTER, AURORA AIRPORT, SUGAR GROVE, IL 60554
 FAA APPROVED REPAIR STATION SUPERVISOR

** Bruce B. Blanton*

BRUCE B. BLANTON INSPECTOR

Signatures

oving Na
tion Auth
AAU
nization

7. Des

P

emarks:

PAIRE

MPLIE

NONE

: NO

: NONI

HER: N 10

PROP MODEL
D3A34C40280DFA-10
PROP S/N 776652
REG NO N732WP
WORK ORDER
163-10-2011



J.A. Air Center

Repair Station No NF2R029L
43W730 US RT 30
Sugar Grove, Illinois 60554
Phone 630.584.3200

DATE 07 December, 2011
A/C TSN: 3020 9
PROP TT: 3020 9
TSPQH: 718 9
TACH: 3020 9

Prop Entries

(3) Completed an annual inspection on this propeller as per Cessna Model 210 and T210 Service Manual Inspection Chart for an annual inspection and McCauley service manual as a guide and AC 43 13-1B Chapter 9 ... (22) Dressed propeller leading edge nicks.

Maintenance Release

I certify the aircraft and/or component(s) on was repaired and/or inspected in accordance with an annual inspection, and current regulations of the Federal Aviation Administration and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station CRS NF2R029L under Work Order No. 163-10-2011. Dated 07 December, 2011

DATE 07 December, 2011

SIGNED

Bruce Rebecchini
Certified Repair Station No NF2R029L

Work Order: 163-10-2011

Printed by EBis 3 (datcomedia.com)

3 next action required on this component is within SEF LAST

PROP MODEL
D3A34C402/90DFA-10
PROP S/N: 776652
REG NO: N732WP
WORK ORDER
1201-12-2012



J.A. Air Center

Repair Station No. NF2R029L
43W730 US RT 30
Sugar Grove, Illinois 60554
Phone: 630 584 3200

DATE: 21 January, 2013
A/C TSN: 3051 9
PROP TT: 3051 9
TSPON: 749 9
TACH: 3051 9

D

Prop Entries

(3) Completed an annual inspection on this propeller as per Cessna Model 210 and T210 Service Manual Inspection Chart and McCauley service manual for an annual inspection as a guide and AC 43.13-1B Chapter 9... (24) Resealed Prop deice boot edges with CS3201 B1/2 sealant... (25) Installed 3 plastic tie wraps around base of prop blades inboard of de ice boot straps and secured with epoxy, and coated with ice shield conductive cement.

Maintenance Release

I certify the aircraft and/or component(s) on was repaired and/or inspected in accordance with an annual inspection, and current regulations of the Federal Aviation Administration and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station. CRS NF2R029L and EASA 145 5424 under Work Order No. 1201-12-2012, Dated 21 January, 2013.

DATE: 21 January, 2013

SIGNED:

Don Morgan

Work Order: 1201-12-2012

Don Morgan
Certified Repair Station No. NF2R029L

Printed by EBis 3 (datcomedia.com)

Signatures

Approving Name
Aviation Authority
FAA/US
Organization

PROP MODEL: D3A34C40290DFA-10
PROP S/N: 776652
REG NO: N732WP
WORK ORDER: 2189-12-2013



J.A. Air Center

Repair Station No. NF2R029L
43W730 US RT 30
Sugar Grove, Illinois 60554
Phone: 630 584 3200

DATE: 21 February
A/C TSN: 3
PROP TT: 3
TSPDH: 1
TACH: 3

Prop Entries

- 3 Completed an annual inspection on this propeller as per Cessna Model 210 and T210 Service Manual Inspection Chart and McCauley service manual for a annual inspection as a guide and AC 43.13-1B Chapter 9.

Maintenance Release

I certify the aircraft and/or component(s) on was repaired and/or inspected in accordance with an annual inspection, and current regulations of the Federal Aviation Administration and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station: CRS NF2R029L and EASA 145 5424 under Work Order No 2189-12-2013, Dated 21 February, 2014.

DATE: 21 February, 2014

SIGNED:

Don Morgan
Certified Repair Station No. NF2R029L

Work Order: 2189-12-2

Printed by EBis 3 (datcomedia.c)

Remarks:

PAIRED

COMPLIE

NO: NONE

3: NOI

NO: NONI

HER: 12

next action required on this component is within SEE LAST
REHAUL.

PROP MODEL D3A34C402/900FA-1D
PROP S/N 776652
REG NO N732WP
WORK ORDER 3805-01-2015



J.A. Air Center

Repair Station No. NF2R029L
43W730 US RT 30
Sugar Grove, Illinois 60554
Phone: 630.584.3200

DATE: 21 April, 2015
AC TSN: 3166.9
PROP TT: 3166.9
TSPOH: 864.9
TACH: 3166.9

Prop Entries

- 4 Completed an annual inspection on this propeller as per Cessna Model 210 and T210 Service Manual Inspection Chart and McCauley service manual for an annual inspection as a guide and AC 43.13-1B Chapter 9.

Maintenance Release

I certify the aircraft and/or component(s) on was repaired and/or inspected in accordance with an annual inspection, and current regulations of the Federal Aviation Administration and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station, CRS NF2R029L and EASA 145.5424 under Work Order No. 3805-01-2015, Dated 21 April, 2015.

DATE: 21 April, 2015

SIGNED:

Bruce Rebechini
Certified Repair Station No. NF2R029L

Work Order: 3805-01-2015

Printed by EBis 3 (datcomedia.com)

PROP S/N: 776652
REG NO: N732WP
WORK ORDER: 5066-02-2016

Repair Station No. NF2R029L
43W730 US RT 30
Sugar Grove, Illinois 60554
Phone: 630 584 3200

A/C TSN: 322
PROP TT: 322
TSPOH: 92
TACH: 322

Prop Entries

3 Removed this McCauley D3A34C402/90DFA-10 S/N 776652 with 3223.1 hours total time and 921.1 SMOH and sent to Aircraft Propeller Service for flush.

Maintenance Release

The aircraft, engine, appliance or component identified was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station CRS NF2R029L and EASA 145.5124 under Work Order No. 5066-02-2016, Dated 13 May, 2016.

DATE: 13 May, 2016

SIGNED:

Bruce Rebecchini
Certified Repair Station No. NF2R029L

Work Order: 5066-02-2016

Printed by EBis 3 (datcomedia)

Approving Name
Aviation Authority
FAAU
Organization

Item: 7. Description

1 P

Remarks:
EPAIREI

COMPLIE

D: NONE

/B: NO

/L: NONI 14

OTHER: 10

Propeller S/N
776652

TSN
3223.1

TSO
921.1

This propeller has been serviced as per the 8130-3 tag dated
6/14/2016 under Work Order 120632

Aircraft Propeller Service, LLC.
Lake Zurich, Illinois

CRS EY2R811K

EASA 145.5126

The next action required on this component is within SEE LAST
OVERHAUL.

Full detail of the work specified in Block 12 is on file within this agency.



APS

A Global Aerospace Partners Company

Aircraft Propeller Service, LLC
595 Telser Road
Lake Zurich, IL 60047
847-541-1133 Office
847-541-0176 Fax
CRS EY2R811K
EASA.145.5126

TD/INSP REPORT

Invoice #: 120632
Work Order #: 120632
Work Type: FLUSH
Serial #: 776652
Part Number: D3A34C402/90DFA-10
Date Printed: 6/14/2016
Page: 1

AIRCRAFT PROPELLER SERVICE, LLC

Invoice #: 120632

Customer: J.A. AIR CENTER, INC.

Page: 1

To: J.A. AIR CENTER, INC.
43W730 US ROUTE 30
SUGAR GROVE, IL 60554
USA

Ship To: J.A. AIR CENTER, INC.
43W730 US ROUTE 30
SUGAR GROVE, IL 60554
USA

Cust PO #: 60-8105

Entry Date: 6/14/2016

Terms: C.O.D

Code: 12570

Fax #: 630-466-4195

Contact: BRUCE, BRAD ZEMAN (OWNER)

Site: 1

Email: brebechini@jaair.com

Phone #: (630) 584-3200

1 FLUSH PROPELLER LABOR

2 GA ADDITIONAL PARTS REQUIRED

Parts	PN/Description	Discrepancy	Condition	Qty
	B-4733 GASKET	EXPENDABLE	NEW	1
	EC-36 2-1/4 Cap	EXPENDABLE	NEW	1
	A1637-16 LUBE 1/2OZ	EXPENDABLE	NEW	1
	A1639-2 NUT	EXPENDABLE	NEW	6
	A-1633-3 O-RING	EXPENDABLE	NEW	1
	A1633-12 O-RING	EXPENDABLE	NEW	1

1. Approving Civil Aviation Administration Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		OMB Control No. 2120-0018 01/12/2009	
4. Organization Name and Address: AIRCRAFT PROPELLER SERVICE, LLC 595 TELSER ROAD LAKE ZURICH, IL 60047 EY2R811K		3. Form Tracking Number: 554784			
		5. Work Order/Contract/Invoice Number: 120632 / 60-8105 w/attached pages 1 thru 1 Dated: 06/14/2016			
7. Description: McCAULEY PROPELLER ASSEMBLY	8. Part Number: D3A34C402/90DFA-10	9. Quantity: 1.00	10. Serial Number: 776652	11. Status/Work: REPAIRED	

Remarks:
 PAIRED per: SPM100 R: 6 (10/19/2015), MPC24 R: 2.2.2 (12/1/2015), MPC400 R: 4 (10/19/2015)

IMPLIED WITH:
 : NONE

ASSEMBLY:	SERIAL #	TSN	TSO/TSMI
	776652	3223.1	921.1

: SEE MPC24

: SEE MPC24

HER: NONE

next action required on this component is within SEE LAST
 ERHAUL.

Detail of the work specified in Block 11 is on file within this agency.

PROP MODEL D3A34C402/90DFA-10
PROP S/N 776652
REG NO N732WP
WORK ORDER 5066-02-2016



J.A. Air Center

Repair Station No. NF2R029L
43W730 US RT 30
Sugar Grove, Illinois 60554
Phone: 630.584.3200

DATE 24 June 2016
A/C TSN 3223.1
PROP TT 3223.1
TSPOH 921.1
TACH 3223.1

Prop Entries

- 3 Removed this McCauley D3A34C402/90DFA-10 S/N 776652 with 3223.1 hours total time and 921.1 SMOH and sent to Aircraft Propeller Service CRS No. EY2R811K for flush and repair ref 8130-3 No. 554784. Reinstalled the propeller once returned as per Cessna T210M Maintenance Manual and McCauley Service Manual.

Maintenance Release
I certify the aircraft and/or component(s) on was repaired and/or inspected in accordance with an annual inspection, and current regulations of the Federal Aviation Administration and was found
Airworthy for return to service. Pertinent details of the repair are on file at this repair station CRS NF2R029L and EASA 145 5424 under Work Order No. 5066-02-2016, Dated 24 June 2016

DATE: 24 June, 2016

SIGNED

Bruce Rebechini
Certified Repair Station No. NF2R029L

Work Order: 5066-02-2016

Printed by EBis 3 (datcomedia.com)

PROP MODEL

PROP MODEL: D3A34C402/90DFA-10
PROP S/N: 776652
REG NO: N732WP
WORK ORDER: 6558-05-2017



J.A. Air Center

Repair Station No: NF2R029L
43W730 US RT 30
Sugar Grove, Illinois 60554
Phone: 630 584 3200

DATE: 09 June, 2017
A/C TSN: 3243.2
PROP TT: 3243.2
TSPOH: 941.2
TACH: 3243.2

Prop Entries

- 3 Completed an Annual Inspection on this propeller as per Cessna Model 210 and T210 Service Manual Inspection Chart and McCauley Service Manual for an Annual Inspection as a guide and AC 43.13-1B, Chapter 9.

Maintenance Release

I certify the aircraft and/or component(s) on was repaired and/or inspected in accordance with an annual inspection, and current regulations of the Federal Aviation Administration and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station CRP-NF2R029L and EASA 145 5424 under Work Order No. 6558-05-2017, Dated 09 June, 2017.

DATE: 09 June, 2017

SIGNED:

Work Order: 6558-05-2017

Bruce Rebecchini
Certified Repair Station No: NF2R029L

Printed by EBis 3 (datamedia.com)
