



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
051218M	INSPECT FIRST AID KIT INSPECTION	KARR	MTH	04-Nov-2019		3		29-Feb-2020	3 m 22 d
			HRS	6780.1					
			LDG	5306					
052010B LEFT	INSPECT WINDSHIELD PRISM INSPECTION	KARR	MTH	16-Jan-2019		24		31-Jan-2021	14 m 24 d
			HRS	6610.2		300		6910.2	130.1
			LDG	5189					
052010C LEFT	INSPECT SIDE WINDOW PRISM INSPECTION	KARR	MTH	16-Jan-2019		24		31-Jan-2021	14 m 24 d
			HRS	6610.2		300		6910.2	130.1
			LDG	5189					
052600 CABIN	INSPECT MONTHLY FIRE EXT CK	KARR	DAYS	04-Nov-2019		30		04-Dec-2019	27 d
			HRS	6780.1					
			LDG	5306					
052600 COCKPIT	INSPECT MONTHLY FIRE EXT CK	KARR	DAYS	04-Nov-2019		30		04-Dec-2019	27 d
			HRS	6780.1					
			LDG	5306					
053201 LEFT	INSPECT EDDY CURRENT INSP MAIN WHEEL	KARR	MTH	17-Jun-2019		O/C			
			HRS	6694					
			LDG	5246					
053201 NOSE	INSPECT EDDY CURRENT INSP NOSE	GSO	MTH	12-Apr-2006		O/C			
			HRS	2324					
			LDG	1416					
053201 RIGHT	INSPECT EDDY CURRENT INSP MAIN WHEEL	KARR	MTH	02-Nov-2018		O/C			
			HRS	6515.1					
			LDG	5122					
053202 LEFT	NDT INSPECTION MAIN WHEEL		MTH	19-Jun-2017		O/C			
			HRS	5988.8					
			LDG	4716					
053401	INSPECTION AAIP AVIONICS	UNK	MTH	24-Jan-2014		24			
			HRS	4560.1					
			LDG	3606					
053490	INSPECT RVSM GMU TEST FLIGHT	FMY	MTH	23-Feb-2004		O/C			
053500	LIFE VEST INSPECTION FOR CUTS, TEARS OR DAMAGE TO THE PACKAGING OF THE VEST. (OP'S SPEC D104-2)	KARR	MTH	29-Aug-2019		3		30-Nov-2019	23 d
			HRS	6763.8					
			LDG	5296					
5-12-01 051201A	PHASE 1	KARR	MTH	16-Jan-2019		24		31-Jan-2021	14 m 24 d
			HRS	6610.2		300		6910.2	130.1
			LDG	5189					
5-12-02 051202A	PHASE 2	KARR	MTH	16-Jan-2019		24		31-Jan-2021	14 m 24 d
			HRS	6610.2		300		6910.2	130.1
			LDG	5189					
5-12-03 051203A	PHASE 3	KARR	MTH	16-Jan-2019		24		31-Jan-2021	14 m 24 d
			HRS	6610.2		300		6910.2	130.1
			LDG	5189					
5-12-04 051204A	PHASE 4	KARR	MTH	16-Jan-2019		24		31-Jan-2021	14 m 24 d
			HRS	6610.2		300		6910.2	130.1
			LDG	5189					
5-12-05 051205A	PHASE 5	KARR	MTH	08-May-2019		36		31-May-2022	30 m 24 d
			HRS	6629.1		1200		7829.1	1049
			LDG	5200					
5-12-0B	PHASE B	KARR	MTH	31-Jul-2019		150		6912.5	132.4
			HRS	6762.5					
			LDG	5293					



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-12 <i>051212</i>	PHASE 12	KARR		MTH 24-Sep-2018 HRS 6445.9 LDG 5079		600		7045.9	265.8
5-12-14 <i>051214</i>	PHASE 14	*CF		MTH 27-Sep-1998 HRS 0		10000		10000	3219.9
5-12-15 <i>051215</i>	PHASE 15	*CF		MTH 27-Sep-1998 HRS 0		10000		10000	3219.9
5-12-16 <i>051216</i>	PHASE 16	*CF		MTH 27-Sep-1998 HRS 0		10000		10000	3219.9
5-12-17 <i>051217</i>	PHASE 17	*CF		MTH 27-Sep-1998 HRS 0		10000		10000	3219.9
5-12-18 <i>051218</i>	PHASE 18	KARR		MTH 08-May-2019 HRS 6629.1 LDG 5200		12		31-May-2020	6 m 24 d
5-12-20	PHASE 20 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	UNK		MTH 04-Nov-2019 HRS		24			
A341005 <i>051220</i>	PERFORM STATIC PORT HEIGHT AND SLOPE CHECK (AIRPLANES CERTIFIED FOR RVSM): PHASE 20	KARR		MTH 04-Nov-2019 HRS 6780.1 LDG 5306		24		30-Nov-2021	24 m 23 d
B341001 LEFT <i>051220 : ADC</i>	CALIBRATION TEST AIR DATA COMPUTER (FAR 91.411): PHASE 20	KARR	7014700-920 98051854	MTH 04-Nov-2019		24		30-Nov-2021	24 m 23 d
B341001 RIGHT <i>051220 : ADC#2</i>	CALIBRATION TEST AIR DATA COMPUTER (FAR 91.411): PHASE 20	KARR	7014700-920 98051853	MTH 04-Nov-2019		24		30-Nov-2021	24 m 23 d
B341001 SECONDARY <i>051220 : ADU</i>	CALIBRATION TEST ADU (FAR 91.411): PHASE 20	KARR	27005-00-08 M001038	MTH 04-Nov-2019		24		30-Nov-2021	24 m 23 d
5-12-21	PHASE 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	UNK		MTH 08-May-2019 HRS		24			
A237003 <i>051221A : CVR</i>	INSPECT COCKPIT VOICE RECORDER BEACON : PHASE 21	KARR	DK120 ULB006047	MTH 08-May-2019 HRS 6629.1 LDG 5200		24		31-May-2021	18 m 24 d
B237004 <i>051221A : CVR</i>	OPERATIONAL TEST COCKPIT VOICE RECORDER BEACON : PHASE 21	KARR	DK120 ULB006047	MTH 08-May-2019 HRS 6629.1 LDG 5200		24		31-May-2021	18 m 24 d
B345001 LEFT <i>051221</i>	CALIBRATION CHECK TRANSPONDER (FAR 91.413): PHASE 21	KARR	066-01141-1101 13447	MTH 04-Nov-2019		24		30-Nov-2021	24 m 23 d
B345001 RIGHT <i>051221 : R</i>	CALIBRATION CHECK TRANSPONDER (FAR 91.413): PHASE 21	KARR	066-01141-1101 13602	MTH 04-Nov-2019		24		30-Nov-2021	24 m 23 d
5-12-22	PHASE 22 (NOT USED)	KLYH		MTH 06-Sep-2011 HRS 4020.8 LDG 3164		N/R			
5-12-23	PHASE 23 (NOT USED)	KLYH		MTH 30-Nov-2012 HRS 4382.9 LDG 3464		N/R			
5-12-34	PHASE 34 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	UNK		MTH 30-Jul-2019 HRS LDG		6			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
A262003 AFT 051234 : A	WEIGHT CHECK HALON FIRE EXTINGUISHER : PHASE 34	KARR	C352 B-02762508	MTH 30-Jul-2019		6		31-Jan-2020	2 m 24 d
A262003 FORWARD 051234 : F	WEIGHT CHECK HALON FIRE EXTINGUISHER : PHASE 34	KARR	C352 B-02762507	MTH 30-Jul-2019		6		31-Jan-2020	2 m 24 d
5-12-35 051235	PHASE 35	KARR		MTH 08-May-2019 HRS 6629.1 LDG 5200		6		30-Nov-2019	23 d
5-12-37 051237	PHASE 37	KARR		MTH 17-Dec-2014 HRS 4982.3 LDG 3932		5000		9982.3	3202.2
5-12-47	PHASE 47 (NOT USED)			MTH 27-Sep-1998 HRS 0 LDG 0		N/R			
5-12-48	PHASE 48 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 25-Mar-2016 HRS 5531.4 LDG 4341		72			
B262004 AFT 051248 : A	DETAILED INSPECTION HALON FIRE EXTINGUISHER : PHASE 48	UNK	C352 B-02762508	MTH 25-Mar-2016		72		31-Mar-2022	28 m 24 d
B262004 FORWARD 051248 : F	DETAILED INSPECTION HALON FIRE EXTINGUISHER : PHASE 48	UNK	C352 B-02762507	MTH 25-Mar-2016		72		31-Mar-2022	28 m 24 d
5-12-49 051249	PHASE 49	KARR		MTH 08-May-2019 HRS 6629.1 LDG 5200		36 1200		31-May-2022 7829.1	30 m 24 d 1049
5-12-51	PHASE 51 (NOT USED)			MTH 27-Sep-1998 HRS 0 LDG 0		N/R			
5-12-54	PHASE 54 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	UNK		MTH 08-May-2019 HRS LDG		6			
D243003 051254	LEAD ACID BATTERY CAPACITY CHECK: PHASE 54	KARR	RG-380E/44LA2 40854544	MTH 08-May-2019		6		30-Nov-2019	23 d
5-12-57 051257	PHASE 57	KARR		MTH 02-Nov-2018 HRS 6515.1 LDG 5122		12		30-Nov-2019	23 d
5-12-59	PHASE 59	KARR		MTH 08-May-2019 HRS 6629.1 LDG 5200		6		30-Nov-2019	23 d
5-12-60	PHASE 60			MTH ACH		500		1345.7	215.7
5-12-61	PHASE 61			MTH HRS		10000		10000	3219.9
5-12-62	PHASE 62			MTH 24-Feb-2015 HRS 5101.8 LDG 4015		N/A			
5-12-MA 0512MA	PHASE MA	*CF		MTH 27-Sep-1998 LDG 0		10000		10000	4694



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-MD <i>0512MD</i>	PHASE MD	UNK	MTH	03-Dec-2015					
			HRS	5438		1456		6894	113.9
			LDG	4268					
5-12-ME <i>0512ME</i>	PHASE ME	KARR	MTH	05-Jan-2018					
			HRS	6169.5		2523		8692.5	1912.4
			LDG	4854					
5-12-MF <i>0512MF</i>	PHASE MF	KLYH	MTH	08-Feb-2013					
			HRS	4440.2		4450		8890.2	2110.1
			LDG	3505					
5-12-MG <i>0512MG</i>	PHASE MG	KARR	MTH	17-Dec-2014					
			HRS	4982.3		5000		9982.3	3202.2
			LDG	3932					
5-12-MH <i>0512MH</i>	PHASE MH	UNK	MTH	05-Mar-2015					
			HRS	5107.2		5130		10237.2	3457.1
			LDG	4019					
5-12-MI <i>0512MI</i>	PHASE MI	KARR	MTH	22-Mar-2017					
			HRS	5901.3		5900		11801.3	5021.2
			LDG	4647					
5-12-MJ <i>0512MJ</i>	PHASE MJ	KARR	MTH	08-May-2019					
			HRS	6629.1		6725		13354.1	6574
			LDG	5200					
5-12-MK	PHASE MK	KARR	MTH	04-Nov-2019					
			HRS	6780.1		300		7080.1	300
			LDG	5306					
051252 E1	OIL FILTER CHANGE	KARR	MTH	04-Nov-2019		24		30-Nov-2021	24 m 23 d
			HRS	6780.1		900		(7623.2)7680.1	900
			LDG	5306					
051252 E2	OIL FILTER CHANGE	KARR	MTH	04-Nov-2019		24		30-Nov-2021	24 m 23 d
			HRS	6780.1		900		(7623.2)7680.1	900
			LDG	5306					
051255 E1	MINOR INSPECTION	KARR	MTH	04-Nov-2019		12		30-Nov-2020	12 m 23 d
			HRS	6780.1		600		(7323.2)7380.1	600
			LDG	5306					
051255 E2	MINOR INSPECTION	KARR	MTH	04-Nov-2019		12		30-Nov-2020	12 m 23 d
			HRS	6780.1		600		(7323.2)7380.1	600
			LDG	5306					
057120 E1	INSPECTION LOW UTILIZATION	KLYH	MTH	21-Oct-2011		120		31-Oct-2021	23 m 24 d
			HRS	4052.4					
			LDG	3204					
057120 E2	INSPECTION LOW UTILIZATION	KLYH	MTH	21-Oct-2011		120		31-Oct-2021	23 m 24 d
			HRS	4052.4					
			LDG	3204					
082001	INSPECT FAR 135 AIRCRAFT WEIGHT CHECK	KARR	MTH	08-May-2019		36		31-May-2022	30 m 24 d
			HRS	6629.1					
			LDG	5200					
129999	INSPECT AIRCRAFT SURVEY	GSO	MTH	21-Jul-2005		O/C			
			HRS	2169					
215012	REPLACE COMPRESSOR DRIVE MOTOR BRUSHES (COMPRESSOR MOTORS 1134104-1, -5 OR FWA1134104-1, -5)	KLYH	1134104-1	MTH	16-Jan-2013				
			937	HRS	4420.6				
				LDG	3488				
				ACH	845.7		500	1345.7	215.7
262003 AFT LEFT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KARR	AE13083-5	MTH	14-Feb-2018		96	28-Feb-2026	75 m 21 d
			AEN1-202						
262003 AFT RIGHT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KARR	AE13083-5	MTH	14-Feb-2018		96	28-Feb-2026	75 m 21 d
			AEN1-202						



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
262003 FORWARD LEFT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KARR		AE13083-5 SN-UNKNOWN	MTH 15-Dec-2016		96		31-Dec-2024	61 m 24 d
262003 FORWARD RIGHT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	KARR		AE13083-5 SN-UNKNOWN	MTH 15-Dec-2016		96		31-Dec-2024	61 m 24 d
B262002 AFT <i>051223 : A</i>	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER	UNK		30401102 15103B2	MTH 06-Mar-2015		60		31-Mar-2020	4 m 24 d
B262002 FORWARD <i>051223 : F</i>	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER	KARR		30401102 40215B1	MTH 03-Jul-2016		60		31-Jul-2021	20 m 24 d
B262003 AFT <i>051247 : A</i>	HYDROSTATIC TEST HALON FIRE EXTINGUISHER	UNK		C352 B-02762508	MTH 01-Dec-2015		144		31-Dec-2027	97 m 24 d
B262003 FORWARD <i>051247 : F</i>	HYDROSTATIC TEST HALON FIRE EXTINGUISHER	UNK		C352 B-02762507	MTH 01-Dec-2015		144		31-Dec-2027	97 m 24 d
B326003 <i>051222 : EMER</i>	HYDROSTATIC TEST PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE	KARR		212940-2 1986	MTH 17-Oct-2017		36		31-Oct-2020	11 m 24 d
B350005 <i>051222 : OXY</i>	PHASE 22 HYDROSTATIC TEST	KARR		176176-64 678453	MTH 17-Oct-2017		36		31-Oct-2020	11 m 24 d
710020 E1	PERFORMANCE RECOVERY WASH	KARR			MTH 24-Sep-2018 HRS 6445.9 LDG 5079		A/R			
710020 E2	PERFORMANCE RECOVERY WASH	KARR			MTH 24-Sep-2018 HRS 6445.9 LDG 5079		A/R			
720010 E1	OVERHAUL	KLYH			MTH 21-Oct-2011 HRS 4051.7 LDG 3200		4000		(7995.5)8051.7	1271.6
720010 E2	OVERHAUL	KLYH			MTH 21-Oct-2011 HRS 4051.7 LDG 3200		4000		(7995.5)8051.7	1271.6
720060 E1	BORESCOPE INSPECTION	KARR			MTH 19-Jun-2017 HRS 5988.8 LDG 4716		2000		(7932.1)7988.8	1208.7
720060 E2	BORESCOPE INSPECTION	KARR			MTH 19-Jun-2017 HRS 5988.8 LDG 4716		2000		(7932.1)7988.8	1208.7
731030 E1	INSTALL NEW FUEL FILTER ELEMENT	KARR			MTH 04-Nov-2019 HRS 6780.1 LDG 5306		24 900		30-Nov-2021 (7623.2)7680.1	24 m 23 d 900
731030 E2	INSTALL NEW FUEL FILTER ELEMENT	KARR			MTH 04-Nov-2019 HRS 6780.1 LDG 5306		24 900		30-Nov-2021 (7623.2)7680.1	24 m 23 d 900
731050 E1	FUEL NOZZLE - OVERHAUL OR REFURBISH				MTH 21-Oct-2011 HRS 4052.4 LDG 3204		4000		(7995.5)8052.4	1272.3
731050 E2	FUEL NOZZLE - OVERHAUL OR REFURBISH				MTH 21-Oct-2011 HRS 4052.4 LDG 3204		4000		(7995.5)8052.4	1272.3
731055 E1	FLOW DIVIDER - OVERHAUL OR REFURBISH			814900-6 F42053	MTH 21-Oct-2011 HRS 4052.4 LDG 3204		4000		(7995.5)8052.4	1272.3



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731055 E2	FLOW DIVIDER - OVERHAUL OR REFURBISH		814900-6 F57718	MTH 21-Oct-2011 HRS 4052.4 LDG 3204		4000		(7995.5)8052.4	1272.3
731100 E1	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	KARR		MTH 08-May-2019 HRS 6629.1 LDG 5200		900		(7472.2)7529.1	749
731100 E2	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	KARR		MTH 08-May-2019 HRS 6629.1 LDG 5200		900		(7472.2)7529.1	749
732010 E1	DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT, RECONNECT AND PERFORM ENGINE CHECKS REQUIRED FOLLOWING WIRING HARNESS REPLACEMENT	KARR		MTH 08-May-2019 HRS 6629.1 LDG 5200		900		(7472.2)7529.1	749
732010 E2	DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT, RECONNECT AND PERFORM ENGINE CHECKS REQUIRED FOLLOWING WIRING HARNESS REPLACEMENT	KARR		MTH 08-May-2019 HRS 6629.1 LDG 5200		900		(7472.2)7529.1	749
732050 E1	OVERHAUL - FUEL CONTROL UNIT AND PUMP		1012632-18 F50342	MTH 21-Oct-2011 HRS 4052.4 LDG 3204		4000		(7995.5)8052.4	1272.3
732050 E2	OVERHAUL - FUEL CONTROL UNIT AND PUMP		1012632-18 F57756	MTH 21-Oct-2011 HRS 4052.4 LDG 3204		4000		(7995.5)8052.4	1272.3
732051 E1	FUEL PUMP OVERHAUL			MTH 21-Oct-2011 HRS 4052.4 LDG 3204		4000		(7995.5)8052.4	1272.3
732051 E2	FUEL PUMP OVERHAUL			MTH 21-Oct-2011 HRS 4052.4 LDG 3204		4000		(7995.5)8052.4	1272.3
750030 E1	REPLACE INTERCOMPRESSOR BLEED VALVE SERVO VALVE			MTH 27-Sep-1998		-			
750030 E2	REPLACE INTERCOMPRESSOR BLEED VALVE SERVO VALVE			MTH 27-Sep-1998		-			
750050 E1	ANTI-ICING VALVE - OVERHAUL OR REFURBISH			MTH 21-Oct-2011 HRS 4052.4 LDG 3204		4000		(7995.5)8052.4	1272.3
750050 E2	ANTI-ICING VALVE - OVERHAUL OR REFURBISH			MTH 21-Oct-2011 HRS 4052.4 LDG 3204		4000		(7995.5)8052.4	1272.3
790020 E1	CHANGE OIL	KLYH		MTH 21-Oct-2011 HRS 4051.7 LDG 3200		A/R			
790020 E2	CHANGE OIL	KLYH		MTH 21-Oct-2011 HRS 4051.7 LDG 3200		A/R			
790050 E1	CHANGE OIL INTERVAL			MTH 27-Sep-1998		O/C			
790050 E2	CHANGE OIL INTERVAL			MTH 27-Sep-1998		O/C			
792005 E1	OVERHAUL OR REFURBISH FUEL OIL HEAT EXCHANGER FUEL TO OIL HEAT EXCHANGER		D2552-600B M14961	MTH 21-Oct-2011 HRS 4052.4 LDG 3204		4000		(7995.5)8052.4	1272.3



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
792005	OVERHAUL OR REFURBISH FUEL OIL HEAT EXCHANGER FUEL TO OIL HEAT EXCHANGER									
E2				D2552-600B	MTH	21-Oct-2011				
				M14074	HRS	4052.4	4000		(7995.5)8052.4	1272.3
					LDG	3204				



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
211002	EMERGENCY PRESSURE VALVE *CF			27441482-06 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
212004 OVERHEAD	CABIN FAN 9912323-2	KARR		BC61A901-2 2994A	MTH 17-Oct-2017 HRS 6075.9 LDG 4777		1000	0	7075.9	295.8
212006 COCKPIT	DEFOGGER FAN *CF	FMY		5703-4 0120	MTH 29-Apr-2005 HRS 2107		O/C	0		
212009	AIR FLOW ACTUATOR *CF			NYLC50466-2 1494	MTH 27-Sep-1998		O/C			
212010	DOOR ACTUATOR MOTOR 9910059-3 *CF			5A3032 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
213001 CABIN	PRESSURE INDICATOR 3001J73 *CF			C668511-0106 20719	MTH 27-Sep-1998		O/C			
213002	CABIN RATE CONTROLLER 9912409-6 *CF			52770-112 542	MTH 27-Sep-1998		O/C			
213007 LEFT	SECONDARY OUTFLOW VALVE 9912409-8 *CF			52772-112 413	MTH 27-Sep-1998		O/C			
213007 RIGHT	PRIMARY OUTFLOW VALVE 9912409-17 MCO			52771-338 K874	MTH 17-Jun-2004 HRS 1749		O/C	0		
213008	TOGGLE MANUAL VALVE 9912409-4 *CF			52773-001 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
213009 LEFT	FLOW CONTROL VALVE GSO			5268-00-1 101	MTH 05-Sep-1999 HRS 562		O/C	0		
213009 RIGHT	FLOW CONTROL VALVE GSO			5268-00-1 99	MTH 05-Sep-1999 HRS 562		O/C	0		
215000	ACM OVERHEAT SWITCH *CF			1173T0635 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
215001	REFRIGERATION PACKAGE ASSEMBLY 9912069-26 *CF			782343-2 9805183	MTH 27-Sep-1998		O/C			
215002	ACM 450 DEGREE SWITCH *CF			746833-1 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
215004	AIR CYCLE MACHINE *CF			775604-1 9805140	MTH 27-Sep-1998 HRS 0		5000	0	5000	-1780.1
RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.										Over Due
215005	BYPASS VALVE 9912069-1 *CF			754751-2 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
215007	B/A PRESSURE VALVE 9912294-1 LYH			BYLB50907 91	MTH 10-Feb-2010 HRS 3629		O/C	0		
215010	HEAT EXCHANGER 9912041-4 *CF			10663 1034	MTH 27-Sep-1998		O/C			
215014	AIR CONDITIONER PRESSURE SWITCH *CF			1250232-4 3300	MTH 27-Sep-1998		O/C			
215015	COMPRESSOR DRIVE MOTOR *CF			1134104-1 937	MTH 27-Sep-1998		O/C			
215016	AIR CONDITIONER COMPRESSOR KLYH			1134160-BSC 6552	MTH 18-Jul-2012 HRS 4246.4 LDG 3365		O/C	0 0		
215017	AIR CONDITIONER CONDENSER *CF			1134400-9 335	MTH 27-Sep-1998		O/C			
215022 AFT	EVAPORATOR ASSEMBLY *CF			1134240-3 367	MTH 27-Sep-1998		O/C			
215023 FORWARD	EVAPORATOR ASSEMBLY *CF			1134240-2 365	MTH 27-Sep-1998		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
215025	AIR CONDITIONER MONITOR- *CF			C35020A 2235	MTH 27-Sep-1998		O/C			
216002	TEMPERATURE CONTROL 9912069-22	UNK		754661-5 99064662	MTH 14-Jul-2016 HRS 5655.8 LDG 4448		O/C	3 0 0		
216003	DUCT TEMPERATURE SENSOR 9912069-14	*CF		754691-3 98035246	MTH 27-Sep-1998		O/C			
216011	OVERHEAT ACM SWITCH *CF			1173T42-1 2749	MTH 27-Sep-1998		O/C			
216013 LEFT	PRESSURE SWITCH LYH			1103P240-1 1545	MTH 11-Nov-2009 HRS 3580		O/C	0		
216013 RIGHT	PRESSURE SWITCH *CF			1103P240-2 858	MTH 27-Sep-1998		O/C			
216014	CABIN TEMPERATURE SENSOR GSO			1942T100-11 1470	MTH 03-Nov-2006 HRS 2429		O/C	0		
217001	WATER SEPARATOR 9912069-13	*CF		738386-3 9804105	MTH 27-Sep-1998		O/C			
221009	AUTOPILOT CONTROL PC-400	*CF		7003897-923 98041389	MTH 27-Sep-1998		O/C			
221010 AFT	AILERON SERVO SM-200	GSO		4006719-906 90095085	MTH 19-Sep-2005 HRS 2212		O/C	3333		
221010 FORWARD	ELEVATOR SERVO SM-200	ICT		4006719-904 97029273	MTH 09-Jan-2015 HRS 5027.9 LDG 3960		O/C			
221010 MIDDLE	RUDDER SERVO SM-200	*CF		4006719-906 98020387	MTH 27-Sep-1998		O/C			
231003	HF RECEIVER-EXCITER KTR-93	GSO		064-01015-0000 3888	MTH 26-Mar-1999 HRS 283		O/C	0		
231004	HF ANTENNA COUPLER KAC-952	GSO		064-01017-0001 4308	MTH 26-Mar-1999 HRS 283		O/C	0		
231005	HF CONTROL HEAD KFS-594	LYH		071-01274-0001 U4895	MTH 09-Feb-2007 HRS 2477		O/C	0		
232002 NO.2	COMM ANTENNA LYH			17-50-01 11399	MTH 10-Feb-2010 HRS 3629		O/C	0		
232003 NO.1	COMM ANTENNA *CF			VSF10-108-2 275	MTH 27-Sep-1998		O/C			
232010 NO. 1	COMM TRANSCEIVER KY-196B	GSO		064-01084-0201 0001155	MTH 17-Aug-2005 HRS 2187		O/C	1669		
232010 NO. 2	COMM TRANSCEIVER KY-196B	GSO		064-01084-0201 0001149	MTH 17-Aug-2005 HRS 2187		O/C	1669		
235001 LEFT	AUDIO AMPLIFIER S3100-63	LYH		5635-1 550	MTH 02-Aug-2011 HRS 4011.4 LDG 3157		O/C	0 0		
235001 RIGHT	AUDIO AMPLIFIER S3100-63	GSO	B	5636-1 327	MTH 27-Nov-2002 HRS 1412		O/C	1139		



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
237001	COCKPIT VOICE RECORDER A200S	KARR		S200-0012-00 01976	MTH 19-Jun-2017 HRS 5988.8 LDG 4716		O/C			
237002	COCKPIT VOICE RECORDER CONTROLLER *CF			S251-1120-00 702	MTH 27-Sep-1998		O/C			
237004	COCKPIT VOICE RECORDER BEACON 266-E0305-00	KARR		DK120 ULB006047	MTH 19-Jun-2017 HRS 5988.8 LDG 4716		O/C			
237004A	COCKPIT VOICE RECORDER BEACON BATTERY KARR			810-2007/K ULB006047	MTH 19-Jun-2017 HRS 5988.8 LDG 4716	2	72	0	31-Aug-2023	45 m 24 d
237017	COCKPIT VOICE RECORDER GRAVITY SWITCH *CF			6895D2-5-5 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
242001 LEFT	AC NO 1 INVERTER S3100-39	*CF		PC251-123E 9551	MTH 27-Sep-1998		O/C			
242001 RIGHT	AC NO 2 INVERTER S3100-39	GSO		PC251-123E 7133	MTH 26-Jan-2006 HRS 2267		O/C	0		
243003 LEFT	DC GENERATOR CONTROL BTL			51525-001F 96270	MTH 04-Mar-2005 HRS 2048		O/C	0		
243003 RIGHT	DC GENERATOR CONTROL GSO			51525-001F 95132	MTH 24-Mar-2000 HRS 847		O/C	0		
243004 LEFT	AMMETER MD130-6	*CF		C662501-0106 D98273	MTH 27-Sep-1998		O/C			
243004 RIGHT	AMMETER MD130-6	*CF		C662501-0106 D98268	MTH 27-Sep-1998		O/C			
243005	VOLTMETER A98638	*CF		C662502-0101 A98638	MTH 27-Sep-1998		O/C			
243007	BATTERY S3597-4	KARR		RG-380E/44LA2 40854544	MTH 08-May-2019 HRS 6629.1 LDG 5200		O/C	26 727.8		
243008	BATTERY TEMPERATURE MONITOR- *CF			1529-1-1 2744	MTH 27-Sep-1998		O/C			
243009	BATTERY TEMPERATURE GAGE GSO			1229-1 1967	MTH 12-Apr-2006 HRS 2324		O/C	0		
243010	BATTERY TEMPERATURE SENSOR S3597-7	GSO		TS-C1A2 40001350	MTH 11-Jan-2007 HRS 2460		O/C	0		
243014	BATTERY DISCONNECT RELAY *CF			A876K CL97021	MTH 27-Sep-1998		O/C			
245004	OVERVOLTAGE MONITOR- *CF			1645-1-3 1765	MTH 27-Sep-1998		O/C			
256001 LAVATORY	LIFE JACKET KSE-35L8	UNK		PO723E105P 150307620234	MTH 02-Jul-2015 HRS 5252.6 LDG 4133		60	1 0 0	30-Jun-2020	7 m 23 d
256001 NO. 10	LIFE JACKET KSE-35L8	UNK		PO723E105P 10071390482	MTH 02-Jul-2015 HRS 5252.6 LDG 4133		60	1 0 0	30-Jun-2020	7 m 23 d
256001 NO. 1	LIFE JACKET KSE-35L8	UNK		PO723E105P 10071390473	MTH 02-Jul-2015 HRS 5252.6 LDG 4133		60	1 0 0	30-Jun-2020	7 m 23 d



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
256001 NO. 2	LIFE JACKET KSE-35L8	UNK		PO723E105P 10071390139	MTH 02-Jul-2015 HRS 5252.6 LDG 4133		60	1 0 0	30-Jun-2020	7 m 23 d
256001 NO. 3	LIFE JACKET KSE-35L8	UNK		PO723E105P 10071390078	MTH 02-Jul-2015 HRS 5252.6 LDG 4133		60	1 0 0	30-Jun-2020	7 m 23 d
256001 NO. 4	LIFE JACKET KSE-35L8	UNK		PO723E105P 11041810094	MTH 02-Jul-2015 HRS 5252.6 LDG 4133		60	1 0 0	30-Jun-2020	7 m 23 d
256001 NO. 5	LIFE JACKET KSE-35L8	UNK		PO723E105P 10071390471	MTH 02-Jul-2015 HRS 5252.6 LDG 4133		60	1 0 0	30-Jun-2020	7 m 23 d
256001 NO. 6	LIFE JACKET KSE-35L8	UNK		PO723E105P 368708	MTH 02-Jul-2015 HRS 5252.6 LDG 4133		60	1 0 0	30-Jun-2020	7 m 23 d
256001 NO. 7	LIFE JACKET KSE-35L8	UNK		PO723E105P 948439	MTH 02-Jul-2015 HRS 5252.6 LDG 4133		60	1 0 0	30-Jun-2020	7 m 23 d
256001 NO. 8	LIFE JACKET KSE-35L8	UNK		PO723E105P 10071390474	MTH 02-Jul-2015 HRS 5252.6 LDG 4133		60	1 0 0	30-Jun-2020	7 m 23 d
256003	TOILET PUMP	*CF		17200-382 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
256010 344008	EMERGENCY LOCATOR TRANSMITTER	KARR		455-5015 210-04172	MTH 19-Nov-2013 HRS 4516.2 LDG 3577		O/C	0 0		
256014 344009	EMERGENCY LOCATOR ANTENNA	KARR		110-340 403263	MTH 19-Nov-2013 HRS 4516.2 LDG 3577		O/C	0 0		
256015 344010	ELT LOCATOR BEACON BATTERY PACK	KARR		23080-025-1 378456-017	MTH 02-Nov-2018 HRS 6515.1 LDG 5122		DUE DUE DUE DUE	0 0	31-Oct-2023	47 m 24 d
261001 LEFT	FIRE DETECTOR SENSOR	*CF		244-18882 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
261001 RIGHT	FIRE DETECTOR SENSOR	*CF		244-18882 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
261002 LEFT	FIRE DETECTOR CONTROL	*CF		377-02838 9812003	MTH 27-Sep-1998		O/C			
261002 RIGHT	FIRE DETECTOR CONTROL	*CF		377-02838 9812010	MTH 27-Sep-1998		O/C			
262001 AFT	ENGINE FIRE EXTINGUISHER	UNK		30401102 15103B2	MTH 06-Mar-2015 HRS 5107.2 LDG 4019		O/C	0 0 0		
262001 FORWARD	ENGINE FIRE EXTINGUISHER	KARR		30401102 40215B1	MTH 15-Dec-2016 HRS 5811.2 LDG 4573		O/C			
262002 AFT	HALON FIRE EXTINGUISHER	UNK		C352 B-02762508	MTH 25-Mar-2016 HRS 5531.4 LDG 4341		O/C	0 0 0		
262002 FORWARD	HALON FIRE EXTINGUISHER	UNK		C352 B-02762507	MTH 25-Mar-2016 HRS 5531.4 LDG 4341		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
262101 AFT LEFT 262003 : AL Manufacture Date: 31-Jan-2017	FIRE EXTINGUISHER CARTRIDGE KARR	KARR		AE13083-5 AEN1-202	MTH 14-Feb-2018 HRS 6219.7 LDG 4895		120		31-Jan-2027	86 m 24 d
262111 AFT RIGHT 262003 : AR Manufacture Date: 31-Jan-2017	FIRE EXTINGUISHER CARTRIDGE KARR	KARR		AE13083-5 AEN1-202	MTH 14-Feb-2018 HRS 6219.7 LDG 4895		120		31-Jan-2027	86 m 24 d
262201 FORWARD LEFT 262003 : FL Manufacture Date: 01-May-2016	FIRE EXTINGUISHER CARTRIDGE KARR	KARR		AE13083-5 SN-UNKNOWN	MTH 15-Dec-2016 HRS 5811.2 LDG 4573		120		31-May-2026	78 m 24 d
262211 FORWARD RIGHT 262003 : FR Manufacture Date: 01-May-2016	FIRE EXTINGUISHER CARTRIDGE 9912048 KARR	KARR		AE13083-5 SN-UNKNOWN	MTH 15-Dec-2016 HRS 5811.2 LDG 4573		120		31-May-2026	78 m 24 d
271001	AILERON TRIM TAB ACTUATOR *CF			5565450-90 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
272001	RUDDER TRIM TAB ACTUATOR *CF			5565450-76 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
273002	ELECTRIC ELEVATOR TRIM ACTUATOR *CF			44430-3725 T158	MTH 27-Sep-1998		O/C			
273003 LEFT	ELEVATOR TRIM TAB ACTUATOR *CF			5565450-95 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
273003 RIGHT	ELEVATOR TRIM TAB ACTUATOR *CF			5565450-92 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
275001 LEFT	FLAP MOTOR 9910055-4			FS30-5 1502	MTH 27-Sep-1998		O/C			
275001 RIGHT	FLAP MOTOR 9910055-4			FS30-5 1485	MTH 27-Sep-1998		O/C			
275002 LEFT	FLAP GEARBOX KARR	KARR		5565175-41 147	MTH 19-Jun-2017 HRS 5988.8 LDG 4716		6000	0	11988.8	5208.7
275002 RIGHT	FLAP GEARBOX LYH	LYH		5565175-41 421	MTH 09-Jan-2009 HRS 3399		6000	0	9399	2618.9
275003 LEFT	FLAP ASSEMBLY UNK	UNK		6525000-29 SN-UNKNOWN	MTH 25-Mar-2015 HRS 5531.4 LDG 4341		O/C	0 0 0		
276001 LEFT	SPEED BRAKES ACTUATOR 9912344-1 *CF			1535500-1 894	MTH 27-Sep-1998		O/C			
276001 RIGHT	SPEED BRAKES ACTUATOR 9912344-1 *CF			1535500-1 902	MTH 27-Sep-1998		O/C			
276002	SPEEDBRAKE CONTROL VALVE *CF			66720 1644	MTH 27-Sep-1998		O/C			
276003	SAFETY VALVE *CF			68930 676	MTH 27-Sep-1998		O/C			
276004	THERMAL RELIEF VALVE *CF			OAS5322-3-1700 608	MTH 27-Sep-1998		O/C			
282001 LEFT WING	FUEL BOOST PUMP 9912017-6 *CF			1C7-22 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
282001 RIGHT WING	FUEL BOOST PUMP 9912017-6 *CF			1C7-22 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
284001 LEFT	LOW FUEL SWITCH *CF			L15H-3 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
284001 RIGHT	LOW FUEL SWITCH *CF			L15H-3 SN-UNKNOWN	MTH 27-Sep-1998		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
284002	SIGNAL CONDITIONER 9912479-7	*CF		10598B01Y01 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
285001 LEFT	FUEL SHUTOFF VALVE 9912014-2	*CF		AV24B1325C-4 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
285001 RIGHT	FUEL SHUTOFF VALVE 9912014-2	*CF		AV24B1325C-4 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
285002 LEFT	FUEL CROSSFEED VALVE 9912014-1	*CF		AV24B1325C-3 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
285002 RIGHT	FUEL CROSSFEED VALVE 9912014-1	*CF		AV24B1325C-3 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
291001	HYDRAULIC RESERVOIR 9912506-1	KLYH		7459-3 300	MTH 30-Nov-2012 HRS 4382.9 LDG 3464		O/C			
291002 LEFT	ENGINE HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 2403	MTH 27-Sep-1998		O/C			
291002 RIGHT	ENGINE HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 2396	MTH 27-Sep-1998		O/C			
291004 LEFT	HYDRAULIC FIREWALL SHUTOFF VALVE *CF			AV24B1325C5 T18899	MTH 27-Sep-1998		O/C			
291004 RIGHT	HYDRAULIC FIREWALL SHUTOFF VALVE ICT			AV24B1325C5 T31017	MTH 01-Feb-1999 HRS 270		O/C	0		
291005 LEFT	CHECK VALVE FLOW SWITCH 9912194-3	*CF		3520020100-4 4215	MTH 27-Sep-1998		O/C			
291005 RIGHT	CHECK VALVE FLOW SWITCH 9912194-3	*CF		3520020100-4 4300	MTH 27-Sep-1998		O/C			
291006	RELIEF VALVE *CF			4614 1658A	MTH 27-Sep-1998		O/C			
291010	HYDRAULIC PRESSURE SWITCH GSO			1106P59 3415	MTH 04-Dec-2000 HRS 1104		O/C	0		
291012	BYPASS VALVE GSO			61510-1 2014A	MTH 26-Sep-2003 HRS 1585		O/C	0		
291021	SHUTTLE VALVE *CF			98120 455	MTH 27-Sep-1998		O/C			
301001 LEFT	WING DE-ICE BOOT GSO			25S-7D5059-09 MYC4TFO	MTH 03-Oct-2004 HRS 1885		O/C	0		
301002 RIGHT	WING DE-ICE BOOT GSO			25S-7D5059-10 MYC4TFO	MTH 03-Oct-2004 HRS 1885		O/C	0		
301003 LEFT	STABILIZER DE-ICE BOOT UNK			SMR5059-13 1066	MTH 21-Nov-2014 HRS 4939.6 LDG 3905		O/C	8 0 0		
301003 RIGHT	STABILIZER DE-ICE BOOT ICT			25S-7D5059-03 ML71640	MTH 17-Jun-2000 HRS 928		O/C	0		
301004 VERTICAL	FIN BOOT ICT			25S-7D5059-05 ML28200	MTH 17-Jun-2000 HRS 928		O/C	0		
301007 AFT	PRESSURE DE-ICE SWITCH *CF			1106P55 5890	MTH 27-Sep-1998		O/C			
301007 FORWARD	PRESSURE DE-ICE SWITCH XKF			1106P55 6730A	MTH 13-Nov-2002 HRS 1383		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301008 AFT	STABILIZER & FIN DE-ICE VALVE *CF			3D2353-06 N14750	MTH 27-Sep-1998		O/C			
301008 LEFT	WING DE-ICE VALVE *CF			3D2353-06 N14806	MTH 27-Sep-1998		O/C			
301008 RIGHT	WING DE-ICE VALVE *CF			3D2353-06 N14574	MTH 27-Sep-1998		O/C			
301010 LEFT	WING ANTI-ICE ASSEMBLY ICT			6528007-5 MI356903	MTH 17-Jun-2000 HRS 928		O/C	0		
301010 RIGHT	WING ANTI-ICE ASSEMBLY ICT			6528007-6 ML20880	MTH 17-Jun-2000 HRS 928		O/C	0		
301013 LEFT	TEMPERATURE CONTROLLER 9912106-1	GSO		3E1870-01 U3319	MTH 27-Mar-2001 HRS 1163		O/C	0		
301013 RIGHT	TEMPERATURE CONTROLLER 9912106-1	GSO		3E1870-01 U3289	MTH 27-Mar-2001 HRS 1163		O/C	0		
302003 LEFT	SOLENOID VALVE 9912402-12	*CF		1946-00-12 1070C	MTH 27-Sep-1998		O/C			
302003 RIGHT	SOLENOID VALVE 9912402-12	*CF		1946-00-12 1071C	MTH 27-Sep-1998		O/C			
302004 LEFT	TEMPERATURE SWITCH *CF			1173T0759 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
302004 RIGHT	TEMPERATURE SWITCH *CF			1173T0759 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
302005 LEFT	ANTI-ICE VALVE 31J2879-03	UNK		540-0406-3 1650	MTH 14-Jul-2016 HRS 5655.8 LDG 4448		O/C	5655.8 4448		
302005 RIGHT	ANTI-ICE VALVE 31J2879-03	UNK		540-0406-3 1673	MTH 14-Jul-2016 HRS 5655.8 LDG 4448		O/C	5655.8 4448		
303001 LEFT	HEATED PITOT TUBE *CF			PH502 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
303001 RIGHT	HEATED PITOT TUBE *CF			PH502 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
303001 STANDBY	HEATED PITOT TUBE			PH1100RW-RIGHT SN-UNKNOWN	MTH 27-Sep-1998		O/C			
304001	HOT AIR TEMPERATURE MONITOR- *CF			1169-1 2673	MTH 27-Sep-1998		O/C			
304005	TEMPERATURE CONTROL VALVE 9912085-1	*CF		27241287 6AP82	MTH 27-Sep-1998		O/C			
304006	TEMPERATURE CONTROLLER 9912085-6	*CF		1E58-1 1AP19	MTH 27-Sep-1998		O/C			
304007 CENTER	TEMPERATURE SENSOR 9912085-3	*CF		27221274 5AP195	MTH 27-Sep-1998		O/C			
304007 LEFT	TEMPERATURE SENSOR 9912085-3	*CF		27221274 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
304008	PRESSURE SWITCH *CF			1115P25 2995A	MTH 27-Sep-1998		O/C			
304009	WINDSHIELD REGULATOR VALVE 9912086-4	*CF		67410-2 3194	MTH 27-Sep-1998		O/C			
312001 LEFT	CLOCK LYH			M877A5V 19263	MTH 09-Jan-2009 HRS 3399		O/C	0		
312001 RIGHT	CLOCK *CF			M877A5V 8789	MTH 27-Sep-1998		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
313001	FLIGHT HOUR RECORDER 85071	*CF		C664503-0104 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
313003 LEFT	ACCELEROMETER AG-222	*CF		7000992 7896	MTH 27-Sep-1998		O/C			
313003 RIGHT	ACCELEROMETER AG-222	*CF		7000992 7914	MTH 27-Sep-1998		O/C			
321001 LEFT	MAIN LANDING GEAR ASSEMBLY *CF			6541410-1 50	MTH 27-Sep-1998		O/C			
321002 RIGHT	MAIN LANDING GEAR ASSEMBLY *CF			6541410-2 50	MTH 27-Sep-1998		O/C			
321003 LEFT	OLEO ASSEMBLY GSO			6541420-4 AC00090	MTH 26-Sep-2003 HRS 1585 LDG 847		41600	847	41600	36294
321004 RIGHT	OLEO ASSEMBLY GSO			6541420-4 AC00088	MTH 26-Sep-2003 HRS 1585 LDG 847		41600	847	41600	36294
321005 LEFT	OLEO UPPER CAP GSO			6541421-1 SN-UNKNOWN	MTH 05-Sep-1999 HRS 562 LDG 330		10400	0	10730	5424
321005 RIGHT	OLEO UPPER CAP GSO			6541421-1 SN-UNKNOWN	MTH 05-Sep-1999 HRS 562 LDG 330		10400	0	10730	5424
321006 LEFT	OUTER BEARING ASSEMBLY GSO			6541425-6 SN-UNKNOWN	MTH 05-Sep-1999 HRS 562 LDG 330		27600	0	27930	22624
321006 RIGHT	OUTER BEARING ASSEMBLY GSO			6541425-6 SN-UNKNOWN	MTH 05-Sep-1999 HRS 562 LDG 330		27600	0	27930	22624
321007 LEFT MAIN GEAR	TRUNNION *CF			6541460-1 SN-UNKNOWN	MTH 27-Sep-1998 LDG 0		41600	0	41600	36294
321007 RIGHT MAIN GEAR	TRUNNION *CF			6541460-2 SN-UNKNOWN	MTH 27-Sep-1998 LDG 0		41600	0	41600	36294
321008 LEFT	TRAILING LINK ASSEMBLY *CF			6541435-1 SN-UNKNOWN	MTH 27-Sep-1998 LDG 0		41600	0	41600	36294
321008 RIGHT	TRAILING LINK ASSEMBLY *CF			6541435-2 SN-UNKNOWN	MTH 27-Sep-1998 LDG 0		41600	0	41600	36294
322001 NOSE	LANDING GEAR ASSEMBLY *CF			6642000-49 49	MTH 27-Sep-1998 LDG 0		23900	0	23900	18594
322002 NOSE	SHIMMY DAMPER LYH			5543001-11 222-11	MTH 18-Feb-2011 HRS 3901.1 LDG 3038		O/C	0 0 0		
322003 NOSE LANDING GEAR	FORK AND PISTON ASSEMBLY *CF			6642000-3 NSN	MTH 27-Sep-1998 LDG 0		13800	0	13800	8494
322004 NOSE LANDING GEAR	FORK *CF			5542300-2 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
323001 LEFT	MAIN LANDING GEAR ACTUATOR 9912465-5	UNK		1547800-5 0473B	MTH 25-Mar-2016 HRS 5531.4 LDG 4341		41600	5558	40383	35077
323002 RIGHT	MAIN LANDING GEAR ACTUATOR 9912465-6	*CF		1547800-6 127	MTH 27-Sep-1998 LDG 0		41600	0	41600	36294
323003 NOSE LANDING GEAR	ACTUATOR 9912485-4	GSO		1548500-9 925	MTH 21-Jul-2005 HRS 2169 LDG 1270		23900	0	25170	19864
323004 LEFT	GEAR UPLOCK ACTUATOR *CF			5527504-3 319	MTH 27-Sep-1998		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
323004 NOSE	GEAR UPLOCK ACTUATOR *CF			5527504-2 2580	MTH 27-Sep-1998		O/C			
323004 RIGHT	GEAR UPLOCK ACTUATOR *CF			5527504-3 326	MTH 27-Sep-1998		O/C			
323005	EMERGENCY DUMP VALVE *CF			OAS5319-1 677	MTH 27-Sep-1998		O/C			
323006	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 9912103-3	UNK		212940-2 1986	MTH 06-Oct-2014 HRS 4885.7 LDG 3849		288		31-Mar-2022	28 m 24 d
Manufacture Date: 31-Mar-1998										
323007	GEAR CONTROL VALVE *CF			66710 902	MTH 27-Sep-1998		O/C			
323008	PISTON WELD ASSEMBLY *CF			6642100-2 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
323019	EMERGENCY AIR BOTTLE GAGE *CF			2341128 64987A	MTH 27-Sep-1998		O/C	0		
324001 LEFT	MAIN WHEEL 9912469-5	KARR		3-1562 0797	MTH 17-Jun-2019 HRS 6694 LDG 5246		O/C	41 1177.1 920		
324001 RIGHT	MAIN WHEEL 9912469-5	KARR		3-1562 0166	MTH 05-Jan-2018 HRS 6169.5 LDG 4854		O/C			
324002 NOSE	WHEEL	UNK		3-1418 5977	MTH 29-Jan-2016 HRS 5516.9 LDG 4326		O/C	0 0 0		
324003 LEFT <i>324003T : LTR</i>	BRAKE 9912469-7	KARR		2-1588-1 0392	MTH 02-Nov-2018 HRS 6515.1 LDG 5122		O/C	0 0		
324004 RIGHT <i>324004T : RTR</i>	BRAKE 9912469-7	KARR		2-1588-1 0656	MTH 02-Nov-2018 HRS 6515.1 LDG 5122		O/C	0 0		
324005 LEFT <i>324005T : LTR</i>	MAIN TIRE 9912467-2	KARR		229K48-2 91412701	MTH 17-Jun-2019 HRS 6694 LDG 5246		O/C	0 0		
324005 RIGHT <i>324005T : RTR</i>	MAIN TIRE 9912467-2	KARR		229K48-2 81912815	MTH 02-Nov-2018 HRS 6515.1 LDG 5122		O/C	0 0		
324006 NOSE	TIRE	KARR		184F13-5 81012861	MTH 16-Jan-2019 HRS 6610.2 LDG 5189		O/C	0 0		
324011 INBOARD	(CO-PILOT SIDE) MASTER BRAKE CYLINDER 9912050-11	*CF		95367-9 1448	MTH 27-Sep-1998		O/C			
324011 OUTBOARD	(PILOT SIDE) MASTER BRAKE CYLINDER 9912050-11	*CF		95367-9 1442	MTH 27-Sep-1998		O/C			
324012 INBOARD	(PILOT SIDE) MASTER BRAKE CYLINDER 9912050-12	*CF		95367-10 1902	MTH 27-Sep-1998		O/C			
324012 OUTBOARD	(COPILOT SIDE) MASTER BRAKE CYLINDER 9912050-12	*CF		95367-10 1925	MTH 27-Sep-1998		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324013	PARKING BRAKE VALVE 9912388-2	*CF		95905 463A	MTH 27-Sep-1998		O/C			
324014	EMERGENCY AIR BRAKE VALVE GSO			895232-0875 V362	MTH 03-Nov-2006 HRS 2429		O/C	0		
324019	POWER BRAKE PUMP 9912166-3	*CF		640931 5144	MTH 27-Sep-1998		O/C			
324020	BRAKE CONTROL BOX 9912305-16	LYH		142-015-1 335	MTH 24-Jun-2011 HRS 3985.8 LDG 3133		O/C	0 0 0		
324021	POWER BRAKE VALVE 9912305-12	*CF		38-707-3 1037	MTH 27-Sep-1998		O/C			
324023	HYDRAULIC ACCUMULATOR *CF			57C57652 1068	MTH 27-Sep-1998		O/C			
324024 LEFT	WHEEL TRANSDUCER 9912305-2	*CF		40-955 3673	MTH 27-Sep-1998		O/C			
324024 RIGHT	WHEEL TRANSDUCER 9912305-2	*CF		40-955 4032	MTH 27-Sep-1998		O/C			
324025 HIGH	PRESSURE SWITCH 38-581501	*CF		1206P27 2696	MTH 27-Sep-1998		O/C			
324025 LOW	PRESSURE SWITCH 9912163-1	GSO		1206P25 2922	MTH 26-Sep-2003 HRS 1585 LDG 847		O/C	0		
324026	POWER BRAKE MOTOR ASSEMBLY *CF			MP50B1 1069	MTH 27-Sep-1998		O/C			
324027	FAULT DISPLAY UNIT 9912305-9	*CF		42-92750 272A	MTH 27-Sep-1998		O/C			
324028 LEFT	SHUTTLE VALVE *CF			211-111 2142	MTH 27-Sep-1998		O/C			
324028 RIGHT	SHUTTLE VALVE *CF			211-111 2127	MTH 27-Sep-1998		O/C			
325001	NOSE STEERING BUNGEE *CF			5565624-19 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
326002 LEFT	MAIN GEAR UP&LOCKED SWITCH *CF			65-430087 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
326002 RIGHT	MAIN GEAR UP&LOCKED SWITCH *CF			65-430087 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
326003 LEFT	MAIN GEAR DOWN&LOCK SWITCH *CF			1EN329R SN-UNKNOWN	MTH 27-Sep-1998		O/C			
326003 RIGHT	MAIN GEAR DOWN&LOCK SWITCH *CF			1EN329R SN-UNKNOWN	MTH 27-Sep-1998		O/C			
326004	NOSE GEAR DOWN&LOCK SWITCH *CF			1EN329R SN-UNKNOWN	MTH 27-Sep-1998		O/C			
326005	NOSE GEAR UP&LOCKED SWITCH *CF			65-430087 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
331001	ANNUNCIATOR PANEL 9912471-1	*CF		938-1-1 160	MTH 27-Sep-1998		O/C			
331002 CENTER	5 VOLT DIMMER KARR			273-1 1399	MTH 15-Dec-2016 HRS 5811.2 LDG 4573		O/C			
331002 LEFT	5 VOLT DIMMER *CF			273-1 5519	MTH 27-Sep-1998		O/C			
331002 RIGHT	5 VOLT DIMMER *CF			273-1 5547	MTH 27-Sep-1998		O/C			
331011	ELECTRICAL PANEL INVERTER *CF			EM2044-1 2277	MTH 27-Sep-1998		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
332001	POWER UNIT LIGHTING			AL-750PS	MTH 27-Sep-1998		O/C			
LEFT AFT		*CF		3509						
332001	POWER UNIT LIGHTING			AL-750PS	MTH 03-Oct-2004		O/C			
LEFT CENTER AFT		GSO		22458	HRS 1885			0		
332001	POWER UNIT LIGHTING			AL-750PS	MTH 03-Oct-2004		O/C			
LEFT CENTER FORWARD		GSO		22459	HRS 1885			0		
332001	POWER UNIT LIGHTING			AL-750PS	MTH 27-Sep-1998		O/C			
LEFT FORWARD		*CF		3507						
332001	POWER UNIT LIGHTING			AL-750PS	MTH 20-Jun-2003		O/C			
RIGHT AFT		HEF		21813	HRS 1569			0		
332001	POWER UNIT LIGHTING			AL-750PS	MTH 17-Dec-1998		O/C			
RIGHT CENTER AFT		ICT		4735	HRS 185			0		
332001	POWER UNIT LIGHTING			AL-750PS	MTH 10-Feb-2010		O/C			
RIGHT CENTER FORWARD		LYH		24252	HRS 3629			0		
332001	POWER UNIT LIGHTING			AL-750PS	MTH 27-Jun-2014		O/C	0		
RIGHT FORWARD		UNK		26199	HRS 4778.8			0		
					LDG 3747			0		
334002	BEACON LIGHT ASSEMBLY			30-2140-5	MTH 11-Aug-2009		O/C			
		LYH		1755	HRS 3507			0		
334003	STROBE POWER SUPPLY			01-0790101-04	MTH 27-Sep-1998		O/C			
LEFT		*CF		426						
334003	STROBE POWER SUPPLY			01-0790101-04	MTH 29-Aug-2016		O/C	0		
RIGHT		KARR		01793	HRS 5713.4			0		
					LDG 4493			0		
335001	EMERGENCY BATTERY PACK			CBS28-1	MTH 08-May-2019		O/C	0		
		KARR		005506	HRS 6629.1			0		
					LDG 5200					
341005	MACH WARNING SWITCH			D37C15	MTH 07-Mar-1999		O/C			
		ICT		1573	HRS 272			0		
341010	ANGLE OF ATTACK INDICATOR			C12705-1	MTH 27-Sep-1998		O/C			
		*CF		151						
341014	ANGLE OF ATTACK INDEXER			C12763-1	MTH 27-Sep-1998		O/C			
		*CF		156						
341024	TEMPERATURE PROBE			102DB1AG	MTH 27-Sep-1998		O/C			
		*CF		A17562						
341025	ANGLE OF ATTACK COMPUTER			C12706-1	MTH 27-Sep-1998		O/C			
		*CF		179						
341026	STICK SHAKER CONTROL			201	MTH 27-Sep-1998		O/C			
		*CF		2121						
341036	BAROMETRIC PRESS SWITCH			GB300NA161	MTH 03-Nov-2006		O/C			
NO. 1	9910095-6	GSO		0531148	HRS 2429			0		
341036	BAROMETRIC PRESS SWITCH			GBC300-140	MTH 27-Sep-1998		O/C			
NO. 2		*CF		9802246						
341037	PRESSURE SWITCH			P24031	MTH 27-Sep-1998		O/C			
	9912057-5	*CF		1853						
341038	OAT INDICATOR			C307FCL	MTH 27-Sep-1998		O/C			
		*CF		A3995						



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342001	MAGNETIC COMPASS	KLYH		C660501-0301 SN-UNKNOWN	MTH 02-Feb-2012 HRS 4122 LDG 3258		O/C	0 0		
342042 LEFT	MODE SELECTOR MS-560	GSO		7018341-803 98031141	MTH 27-Mar-2001 HRS 1163		O/C		1163	
342042 RIGHT	MODE SELECTOR MS-560	LYH		7018341-803 01041890	MTH 03-Jun-2009 HRS 3490		O/C		2662	
342043 LEFT	VERTICAL GYRO VG-14A	*CF		7000622-901 98058558	MTH 27-Sep-1998		O/C			
342043 RIGHT	VERTICAL GYRO VG-14A	*CF		7000622-901 98058539	MTH 27-Sep-1998		O/C			
342044	RATE GYRO RG-204	*CF		7007453-903 98034577	MTH 27-Sep-1998		O/C			
342048 LEFT	AIR DATA COMPUTER AZ-850	GSO		7014700-920 98051854	MTH 24-Mar-2000 HRS 847		O/C		847	
342048 RIGHT	AIR DATA COMPUTER AZ-850	GSO		7014700-920 98051853	MTH 24-Mar-2000 HRS 847		O/C		847	
342049 LEFT	DIRECTIONAL GYRO C-14D	*CF		4020577-3 98046456	MTH 27-Sep-1998		O/C			
342049 RIGHT	DIRECTIONAL GYRO C-14D	LYH		4020577-3 80121904	MTH 19-Jan-2008 HRS 3042		O/C		2989	
342050 LEFT	FLUX VALVE FX-220	*CF		2594484 98052839	MTH 27-Sep-1998		O/C			
342050 RIGHT	FLUX VALVE FX-220	*CF		2594484 98052843	MTH 27-Sep-1998		O/C			
342052	REMOTE COMPENSATOR CS-412	*CF		2593379-1 98042598	MTH 27-Sep-1998		O/C			
342054 STANDBY	HSI INDICATOR	*CF		520-3150-004 17081	MTH 27-Sep-1998		O/C			
342063	REMOTE CONTROL HEADING INDICATOR RI-553	*CF		7016954-907 97110638	MTH 27-Sep-1998		O/C			
342064	STANDBY BATTERY PACK PS-855A	KARR		501-1712-01 80075	MTH 07-Aug-2018 HRS 6405.5 LDG 5041		O/C			
342078 LEFT	AVIONICS COMPUTER IC-600	KARR		7017000-80129 96100863	MTH 08-May-2019 HRS 6629.1 LDG 5200		O/C			
342078 RIGHT	AVIONICS COMPUTER IC-600	GSO		7017000-81129 98041621	MTH 03-Nov-2006 HRS 2429		O/C	0		
342079 NO. 1	DISPLAY CONTROL DC-550	*CF		7016986-723 98041490	MTH 27-Sep-1998		O/C			
342079 NO. 2	DISPLAY CONTROL DC-550	*CF		7016986-723 98041492	MTH 27-Sep-1998		O/C			
342080 MFD 1	FLIGHT DISPLAY BEZEL BL-871	UNK		7014332-841 06057955	MTH 14-Jul-2016 HRS 5655.8 LDG 4448		O/C			
342080 NO. 1	FLIGHT DISPLAY BEZEL BL-870	*CF		7014331-931 98031343	MTH 27-Sep-1998		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342080 NO. 2	FLIGHT DISPLAY BEZEL BL-870	GSO		7014331-931 01074032	MTH 11-Jan-2007 HRS 2460		O/C	2206		
342081 CENTER	PRIMARY FLIGHT DISPLAY DU-870	LYH		7014300-901 0810H704	MTH 14-Aug-2009 HRS 3510		O/C	0		
342081 NO. 1	PRIMARY FLIGHT DISPLAY DU-870	GSO		7014300-901 97062172	MTH 26-Sep-2003 HRS 1585		O/C	0		
342081 NO. 2	PRIMARY FLIGHT DISPLAY DU-870	LYH		7014300-901 01069431	MTH 26-Aug-2010 HRS 3773.8 LDG 2923		O/C			
342083 SECONDARY	ADU	KSAT		27005-00-08 M001038	MTH 15-Apr-2014 HRS 4674.2 LDG 3675		O/C	6		
342084	SECONDARY FLIGHT DISPLAY UNK			33507-10-02 M001442	MTH 30-Apr-2015 HRS 5191.6 LDG 4085		O/C	0 0 0		
344004	RADAR RECEIVER/TRANSMITTER WU-660	LYH		7021450-601 05065680	MTH 09-Jul-2007 HRS 2743		O/C	0		
344022	RADIO ALTIMETER RECEIVER/TRANSMITTER ALT-55	*CF		622-2855-011 11467	MTH 27-Sep-1998		O/C			
344023 AFT	RADIO ALTIMETER ANTENNA 437X-1B	*CF		622-0954-001 6645	MTH 27-Sep-1998		O/C			
344023 FORWARD	RADIO ALTIMETER ANTENNA 437X-1B	*CF		622-0954-001 6642	MTH 27-Sep-1998		O/C			
344024	GPWS/EGPWS COMPUTER KARR			965-1199-005EX 3516	MTH 23-May-2018 HRS 6335.7 LDG 4982		O/C	0 0		
344027	STORMSCOPE PROCESSOR WX-1000	GSO		78-8051-9160-4 FXP01200041	MTH 30-Aug-2002 HRS 1312		O/C	0		
344028	STORMSCOPE DISPLAY WX-1000			78-8060-5900-9 SN-UNKNOWN	MTH 11-Oct-1999 HRS 578		O/C	0		
344029	STORMSCOPE ANTENNA WX-1000E			78-8051-9200-8 SN-UNKNOWN	MTH 11-Oct-1999 HRS 578		O/C	0		
344034	RADAR CONTROLLER WC-660	GSO		7008471-667 97103094	MTH 05-Sep-1999 HRS 562		O/C	738		
344050	SKYWATCH ANTENNA			805-10890-001 SN-UNKNOWN	MTH 11-Oct-1999 HRS 578		O/C	0		
345004 AFT BOTTOM	TRANSPONDER ANTENNA 85226	ICT		DMNI50-2-2 70443	MTH 07-Mar-1999 HRS 272		O/C	0		
345004 FORWARD BOTTOM	TRANSPONDER ANTENNA 85226	GSO		DMNI50-2-2 103394	MTH 03-Nov-2006 HRS 2429		O/C	0		
345007 LEFT	DME ANTENNA 85226	*CF		DMNI50-2-2 67026	MTH 27-Sep-1998		O/C			
345007 RIGHT	DME ANTENNA 85226	*CF		DMNI50-2-2 67036	MTH 27-Sep-1998		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345010 LEFT	NAV ANTENNA CI120-200G/S-L	GSO		CI120-200 1011866	MTH 27-Mar-2001 HRS 1163		O/C	0		
345010 RIGHT	NAV ANTENNA CI120-200G/S-L	GSO		CI120-200 1011865	MTH 27-Mar-2001 HRS 1163		O/C	0		
345011 LEFT	ADF RECEIVER KR-87	*CF		066-01072-0006 68434	MTH 27-Sep-1998		O/C			
345014 LEFT	ADF LOOP ANTENNA KA-44B	*CF		071-01234-0002 67258	MTH 27-Sep-1998		O/C			
345017	MARKER BEACON ANTENNA *CF			31-10-01 2842	MTH 27-Sep-1998		O/C			
345018	GLIDE SLOPE ANTENNA ICT			RGS1048 A6774	MTH 17-Jun-2000 HRS 928		O/C	0		
345031 LEFT	MARKER BEACON RECEIVER KMR-675	*CF		066-01044-0001 1044	MTH 27-Sep-1998		O/C			
345031 RIGHT	MARKER BEACON RECEIVER KMR-675	*CF		066-01044-0001 1045	MTH 27-Sep-1998		O/C			
345032 NO. 1	NAV RECEIVER KN-53	GSO		066-01067-0004 U71604	MTH 23-Dec-2002 HRS 1442		O/C	30		
345032 NO. 2	NAV RECEIVER KN-53	PDK		066-01067-0004 83274	MTH 23-May-2003 HRS 1543		O/C	0		
345034 LEFT	TRANSPONDER KT-70	KARR		066-01141-1101 13447	MTH 30-Sep-2016 HRS 5737.4 LDG 4514		O/C			
345034 RIGHT	TRANSPONDER KT-70	KARR		066-01141-1101 13602	MTH 30-Sep-2016 HRS 5737.4 LDG 4514		O/C			
345035 NO. 1	DME INDICATOR KDI-572	*CF		066-01069-0015 1123	MTH 27-Sep-1998		O/C			
345035 NO. 2	DME INDICATOR KDI-572	*CF		066-01069-0015 1079	MTH 27-Sep-1998		O/C			
345036 NO. 1	DME INTERROGATOR DM-441B	IAD		066-01107-0012 30128	MTH 08-Jul-2002 HRS 1307		O/C	66		
345036 NO. 2	DME INTERROGATOR DM-441B	GSO		066-01107-0012 10208	MTH 03-Jul-2002 HRS 1306		O/C	1209		
345084	GNS-X/GNS-XLS FMS CDU GNS-XLS S3100-185	GSO		17960-0102-0101 2692	MTH 24-Sep-2006 HRS 2404		O/C	3269		
345108	VOR CONVERTER KN-40	*CF		066-01130-0701 11140	MTH 27-Sep-1998		O/C			
345118 LEFT	GPS ANTENNA KA-92	GSO		071-01553-0200 26537	MTH 09-Dec-1999 HRS 701		O/C	0		
345118 RIGHT	GPS ANTENNA KA-92			071-01553-0200 28295	MTH 11-Oct-1999 HRS 578		O/C	0		
345129	MULTIFUNCTION DISPLAY CONTROLLER MC-800	IAD		7007062-939 98031859	MTH 27-Jun-2002 HRS 1304		O/C	1295		



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345132	GPS RECEIVER SENSOR UNK			066-04031-2121 82239	MTH 21-Nov-2014 HRS 4939.6 LDG 3905		O/C			
346007	SKYWATCH TRAFFIC ADVISORY COMPUTER TRC497	IAD		805-10800-001 SKY01900936	MTH 03-May-2000 HRS 906		O/C	0		
346011 LEFT	FMS 1 CONFIGURATION MODULE *CF			17680-01 9866	MTH 27-Sep-1998		O/C			
346019	MOVING MAP DISPLAY --			7000-30-15 170733	MTH 17-Mar-2000 HRS 846		O/C	0		
346039	FDR-ARINC CONVERTER -- *CF			1226-1-1 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
351004 COPILOT	OXYGEN MASK KARR			MLD20-506 B122261	MTH 11-Oct-2018 HRS 6476 LDG 5099		72	0	31-Oct-2024	59 m 24 d
351004 PILOT	OXYGEN MASK KARR			MLD20-506 B123836	MTH 20-Feb-2018 HRS 6227.1 LDG 4899		72	0	29-Feb-2024	51 m 22 d
351005	OXYGEN REGULATOR GSO			172170-01 1529	MTH 21-Jul-1999 HRS 518		O/C	0		
351006	OXYGEN CYLINDER ZC369-64	UNK		176176-64 678453	MTH 06-Oct-2014 HRS 4885.7 LDG 3849		288	186	30-Apr-2023	41 m 23 d
Manufacture Date: 30-Apr-1999										
361001	DOOR SEAL VALVE BTL			MJV3 SN-UNKNOWN	MTH 18-Jul-2004 HRS 1786		O/C	0		
361003	DEICE BOOT REGULATOR 9912043-2	*CF		38E85-5C B2565	MTH 27-Sep-1998		O/C			
361008 LEFT	PNEUMATIC B/A VALVE *CF			1553-00-18 1795	MTH 27-Sep-1998		O/C			
361008 RIGHT	PNEUMATIC B/A VALVE *CF			1553-00-18 1801	MTH 27-Sep-1998		O/C			
521001	CABIN DOOR SEAL 9912075-4	*CF		S15501-4 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
531001 LEFT	TRUNNION SUPPORT FITTING *CF			6613056-3 SN-UNKNOWN	MTH 27-Sep-1998 LDG 0		12200	0	12200	6894
531001 RIGHT	TRUNNION SUPPORT FITTING *CF			6613056-4 SN-UNKNOWN	MTH 27-Sep-1998 LDG 0		12200	0	12200	6894
531002	ACTUATOR SUPPORT FITTING *CF			6511105-1 SN-UNKNOWN	MTH 27-Sep-1998 LDG 0		23900	0	23900	18594
561001 LEFT	WINDSHIELD ASSY, (LH) 9912064-15	ICT		E149000-101 4815	MTH 01-Feb-1999 HRS 270		O/C	270		
561001 RIGHT 561002 : R	WINDSHIELD ASSY, (RH) 9912064-16	ICT		E149000-102 4658	MTH 01-Feb-1999 HRS 270		O/C	270		
561003	FOUL WEATHER WINDOW GSO			5511275-202 462	MTH 27-Nov-2002 HRS 1412		O/C	0		
561005 LEFT INBOARD	FLIGHT COMPARTMENT WINDOW ICT			5511285-5 11499	MTH 01-Feb-1999 HRS 270		O/C	0		
561005 LEFT OUTBOARD	FLIGHT COMPARTMENT WINDOW *CF			5511285-3 SN-UNKNOWN	MTH 27-Sep-1998		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
561005 RIGHT INBOARD	FLIGHT COMPARTMENT WINDOW ICT			5511285-6 1298	MTH 01-Feb-1999 HRS 270		O/C	0		
561005 RIGHT OUTBOARD	FLIGHT COMPARTMENT WINDOW LYH			5511285-200 10-11-08	MTH 11-Aug-2009 HRS 3507		O/C	0		
562001 LEFT NO. 1	MAIN DOOR WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
562001 LEFT NO. 2	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
562001 LEFT NO. 3	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
562001 LEFT NO. 4	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
562001 LEFT NO. 5	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
562001 LEFT NO. 6	CABIN WINDOW 9912207-8	*CF		5591005-5 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
562001 RIGHT NO. 1	EMERGENCY DOOR WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
562001 RIGHT NO. 2	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
562001 RIGHT NO. 3	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
562001 RIGHT NO. 4	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
562001 RIGHT NO. 5	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
562001 RIGHT NO. 6	CABIN WINDOW 9912207-8	*CF		5591005-5 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
572001 LEFT FORWARD	TRUNNION ATTACH FITTING *CF			6522460-5 SN-UNKNOWN	MTH 27-Sep-1998 LDG 0		41600	0	41600	36294
572002 RIGHT FORWARD	TRUNNION ATTACH FITTING *CF			6522460-6 SN-UNKNOWN	MTH 27-Sep-1998 LDG 0		41600	0	41600	36294
574001 LEFT AFT	TRUNNION ATTACH FITTING *CF			6522465-1 SN-UNKNOWN	MTH 27-Sep-1998 LDG 0		41600	0	41600	36294
574002 RIGHT AFT	TRUNNION ATTACH FITTING *CF			6522465-2 SN-UNKNOWN	MTH 27-Sep-1998 LDG 0		41600	0	41600	36294
574003 LEFT	SIDE BRACE FITTING *CF			6521435-1 SN-UNKNOWN	MTH 27-Sep-1998 LDG 0		41600	0	41600	36294
574004 RIGHT	SIDE BRACE FITTING *CF			6521435-2 SN-UNKNOWN	MTH 27-Sep-1998 LDG 0		41600	0	41600	36294
712001 LEFT ENGINE	REAR (AFT) ISOLATOR MOUNT 9912477-2	*CF		LM449SA6 SN-UNKNOWN	MTH 27-Sep-1998 HRS 0		8000	0	8000	1219.9
712001 RIGHT ENGINE	REAR (AFT) ISOLATOR MOUNT 9912477-2	KLYH		LM449SA6 LK0285	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		8000	0	12051.7	5271.6
712002 LEFT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT 9912477-1	*CF		LM449SA4 SN-UNKNOWN	MTH 27-Sep-1998 HRS 0		8000	0	8000	1219.9
712002 LEFT ENGINE FORWARD TOP	ISOLATOR MOUNT 9912477-1	*CF		LM449SA4 SN-UNKNOWN	MTH 27-Sep-1998 HRS 0		8000	0	8000	1219.9
712002 RIGHT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT 9912477-1	KLYH		LM449SA7 LK0162	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		8000	0	12051.7	5271.6



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
712002 RIGHT ENGINE FORWARD TOP	ISOLATOR MOUNT 9912477-1	KLYH		LM449SA7 LK0374	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		8000	0	12051.7	5271.6
712005	ENGINE VIBRATION MONITOR- 9912519-2	GSO		2789 080431	MTH 17-Aug-2005 HRS 2187		O/C	0		
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE 9912448-1	KLYH		PW530A DA0101	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		E/C	3995.5		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE 9912448-1	KLYH		PW530A DA0107	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		E/C	3995.5		
722001 E1	OIL PUMP	*CF		30J1498-01 28A003	MTH 27-Sep-1998		O/C			
722001 E2	OIL PUMP	*CF		30J1498-01 27A992	MTH 27-Sep-1998		O/C			
723001 E1	FAN	*CF		31J2907-01 1L623	MTH 27-Sep-1998		O/C			
723001 E2	FAN	*CF		31J2907-01 1L628	MTH 27-Sep-1998		O/C			
723010 E1	LP COMPRESSOR FAN ROTOR UNK			30J1541-01 43B025	MTH 30-Sep-2011 HRS 4051.2 LDG 3199		15000	3995 3139	(15000)15060	9754
723010 E2	LP COMPRESSOR FAN ROTOR UNK			30J1541-01 43B049	MTH 07-Oct-2011 HRS 4051.2 LDG 3199		15000	3995 3139	(15000)15060	9754
723030 E1	1ST-STAGE HP COMPRESSOR ROTOR UNK			30J1391 54B669	MTH 30-Sep-2011 HRS 4051.2 LDG 3199		13500	3995 3139	(13500)13560	8254
723030 E2	1ST-STAGE HP COMPRESSOR ROTOR UNK			30J1391 55B432	MTH 07-Oct-2011 HRS 4051.2 LDG 3199		13500	3995 3139	(13500)13560	8254
723040 E1	2ND-STAGE HP COMPRESSOR ROTOR UNK			30J2082-01 54B659	MTH 30-Sep-2011 HRS 4051.2 LDG 3199		13500	3995 3139	(13500)13560	8254
723040 E2	2ND-STAGE HP COMPRESSOR ROTOR UNK			30J2082-01 55B510	MTH 07-Oct-2011 HRS 4051.2 LDG 3199		13500	3995 3139	(13500)13560	8254
723060 E1	CENTRIFUGAL IMPELLER UNK			30J1450-01 1H927	MTH 30-Sep-2011 HRS 4051.2 LDG 3199		13500	3995 3139	(13500)13560	8254
723060 E2	CENTRIFUGAL IMPELLER UNK			30J1450-01 1H966	MTH 07-Oct-2011 HRS 4051.2 LDG 3199		13500	3995 3139	(13500)13560	8254
724001 E1	COMBUSTION LINER *CF			30J1929-01 1M638	MTH 27-Sep-1998		O/C			
724001 E2	COMBUSTION LINER *CF			30J1929-01 4M631	MTH 27-Sep-1998		O/C			
724707 E1	HIGH TURBINE BLADES *CF			31J2498-01 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
724707 E2	HIGH TURBINE BLADES *CF			31J2498-01 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
724710 E1	MAGNETIC CHIP COLLECTOR 31J2558-01 *CF			1003161.05 LB0180	MTH 27-Sep-1998		O/C			
724710 E2	MAGNETIC CHIP COLLECTOR 31J2558-01 *CF			1003161.05 LB0226	MTH 27-Sep-1998		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725010 E1	1ST-STAGE TURBINE DISK UNK			30J1401 A000088F	MTH 30-Sep-2011 HRS 4051.2 LDG 3199			3995 3139	(12000)12060	6754
725010 E2	1ST-STAGE TURBINE DISK UNK			30J1401 A0000DN9	MTH 07-Oct-2011 HRS 4051.2 LDG 3199		12000	3995 3139	(12000)12060	6754
725020 E1	2ND-STAGE TURBINE DISK UNK			30H1226 92A167	MTH 30-Sep-2011 HRS 4051.2 LDG 3199		13500	3995 3139	(13500)13560	8254
725020 E2	2ND-STAGE TURBINE DISK UNK			30H1226 92A168	MTH 07-Oct-2011 HRS 4051.2 LDG 3199		13500	3995 3139	(13500)13560	8254
725030 E1	3RD-STAGE TURBINE DISK UNK			30H1309 92A359	MTH 30-Sep-2011 HRS 4051.2 LDG 3199		13500	3995 3139	(13500)13560	8254
725030 E2	3RD-STAGE TURBINE DISK UNK			30H1309 92A376	MTH 07-Oct-2011 HRS 4051.2 LDG 3199		13500	3995 3139	(13500)13560	8254
731001 LEFT <i>731004 : L</i>	LOW FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
731001 RIGHT <i>731004 : R</i>	LOW FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
732002	ENGINE SYNCRONIZATION CONTROL *CF			213693E 12066965	MTH 27-Sep-1998		O/C			
732003	ENGINE SYNCRONIZATION ACTUATOR *CF			5485-066 11950728	MTH 27-Sep-1998		O/C			
732005	FUEL QUANTITY/FUEL FLOW INDICATOR 9912450-3 *CF			10603N01M01 9804553	MTH 27-Sep-1998		O/C			
733003 LEFT	FUEL FLOW TRANSMITTER 9914413-1 *CF			9-231-28 L7215	MTH 27-Sep-1998		O/C			
733003 RIGHT	FUEL FLOW TRANSMITTER 9914413-1 KARR			9-231-28 L6267	MTH 30-Mar-2018 HRS 6283.6 LDG 4940		O/C	0 0		
731002 E1	FLOW DIVIDER 31J1529-06 *CF			814900-6 F42053	MTH 27-Sep-1998		O/C			
731002 E2	FLOW DIVIDER 31J1529-06 LYH			814900-6 F57718	MTH 03-Apr-2009 HRS 3509.9		O/C	0		
731005 E1	BLEED CONTROL VALVE 31J2814-03 *CF			816950-4-005 98020965	MTH 27-Sep-1998		O/C			
731005 E2	BLEED CONTROL VALVE 31J2814-03 *CF			816950-4-005 98019121	MTH 27-Sep-1998		O/C			
732001 E1	(FCU) FUEL CONTROL UNIT -- UNK			1012632-18 F50342	MTH 06-Jul-2015 HRS 5252.6 LDG 4133		O/C	2 0 0		
732001 E2	(FCU) FUEL CONTROL UNIT -- UNK			1012632-18 F57756	MTH 06-Jul-2015 HRS 5252.6 LDG 4133		O/C	2 0 0		
741001 E1	IGNITION EXCITER 31J2807-03 *CF			9049835-3 NN98080082	MTH 27-Sep-1998		O/C			
741001 E2	IGNITION EXCITER 31J2807-03 *CF			9049835-3 NN97310120	MTH 27-Sep-1998		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
742001 E1 INNER	IGNITOR	KARR		502600-1 NNA18360031	MTH 02-Nov-2018 HRS 6515.1 LDG 5122		O/C	0 0		
742001 E1 OUTER	IGNITOR	KARR		502600-1 NNA18390140	MTH 02-Nov-2018 HRS 6515.1 LDG 5122		O/C	0 0		
742001 E2 INNER	IGNITOR	KARR		502600-1 NNA18390143	MTH 02-Nov-2018 HRS 6515.1 LDG 5122		O/C	0 0		
742001 E2 OUTER	IGNITOR	KARR		502600-1 NNA18390234	MTH 02-Nov-2018 HRS 6515.1 LDG 5122		O/C	0 0		
742002 E1	LONG IGNITOR LEAD 31J1908-08	FMY		9059150-8 SN-UNKNOWN	MTH 13-Feb-2004 HRS 1672.9		O/C	0		
742002 E2	LONG IGNITOR LEAD 31J1908-08	FMY		9059150-8 SN-UNKNOWN	MTH 13-Feb-2004 HRS 1672.9		O/C	0		
742003 E1	SHORT IGNITOR LEAD 31J1908-07	FMY		9059150-7 SN-UNKNOWN	MTH 13-Feb-2004 HRS 1672.9		O/C	0		
742003 E2	SHORT IGNITOR LEAD 31J1908-07	FMY		9059150-7 SN-UNKNOWN	MTH 13-Feb-2004 HRS 1672.9		O/C	0		
751003 E1	BLEED VALVE	GSO		31J2547-01 25A778	MTH 03-Nov-2006 HRS 2485.9		O/C	2429		
751003 E2	BLEED VALVE	GSO		31J2547-01 27A884	MTH 03-Nov-2006 HRS 2485.9		O/C	2429		
751004 E1	INTERCOMPRESSOR BLEED VALVE SERVO VALVE	GSO		31J2857-04 TR1425	MTH 11-Jan-2007 HRS 2516.9		O/C	0		
751004 E2	INTERCOMPRESSOR BLEED VALVE SERVO VALVE	GSO		31J2857-03 TR0210	MTH 03-Nov-2006 HRS 2485.9		O/C	2429		
751005 E1	LINEAR VAR. DIFFERENTIAL TRANSFORMER	*CF		GM9237-2 1185	MTH 27-Sep-1998		O/C			
751005 E2	LINEAR VAR. DIFFERENTIAL TRANSFORMER	*CF		GM9237-2 1226	MTH 27-Sep-1998		O/C			
761005	SOLENOID ASSEMBLY	UNK		183238-001 SN-UNKNOWN	MTH 14-Jul-2016 HRS 5655.8 LDG 4448		O/C	2 0 0		
771004	N1 SPEED/ITT TEMP INDICATOR 9912450-4	KARR		10601N02M00 01060693A	MTH 08-May-2019 HRS 6629.1 LDG 5200		O/C	0 0		
773001 LEFT	ENGINE ACCELEROMETER *CF			6222SM15 15166	MTH 27-Sep-1998		O/C			
773001 RIGHT	ENGINE ACCELEROMETER *CF			6222SM15 15257	MTH 27-Sep-1998		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
771005 E1	N1 MONOPOLE	GSO		31J2614-01 CH302	MTH 31-Jul-2004 HRS 1857.9		O/C	0		
771005 E2	N1 MONOPOLE	GSO		31J2614-01 CH291	MTH 31-Jul-2004 HRS 1857.9		O/C	1801		
771006 E1	N2 MONOPOLE	*CF		31J1596-01 CH193	MTH 27-Sep-1998		O/C			
771006 E2	N2 MONOPOLE	*CF		31J1596-01 CH195	MTH 27-Sep-1998		O/C			
783001 LEFT	THRUST REVERSER ASSEMBLY	MKE		53ND-78002-3 105	MTH 30-Apr-2014 HRS 4691.7 LDG 3686		O/C	3686		
783001 RIGHT	THRUST REVERSER ASSEMBLY	MKE		53ND-78002-4 104	MTH 30-Apr-2014 HRS 4691.7 LDG 3686		O/C	3686		
783002 LEFT	CONTROL VALVE	LYH		65680 3771	MTH 07-Feb-2008 HRS 3059 LDG 2167		O/C	0		
783002 RIGHT	CONTROL VALVE	*CF		65680 2564	MTH 27-Sep-1998		O/C			
783003 LEFT	THREE WAY VALVE	*CF		13027-4 3322	MTH 27-Sep-1998		O/C			
783003 RIGHT	THREE WAY VALVE	*CF		13027-4 3354	MTH 27-Sep-1998		O/C			
783005 LEFT UPPER	THRUST REVERSER DOOR ASSEMBLY	*CF		53ND-78003-3 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783005 RIGHT UPPER	THRUST REVERSER DOOR ASSEMBLY	*CF		53ND-78003-3 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783006 LEFT LOWER	THRUST REVERSER DOOR ASSEMBLY	*CF		53ND-78004-3 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783006 RIGHT LOWER	THRUST REVERSER DOOR ASSEMBLY	*CF		53ND-78004-3 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783007 LEFT	THRUST REVERSER MECH ASSEMBLY	*CF		53ND-78100-1 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783007 RIGHT	THRUST REVERSER MECH ASSEMBLY	*CF		53ND-78100-2 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783008 LEFT	THRUST REVERSER MECH ASSEMBLY	*CF		53ND-78100-3 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783008 RIGHT	THRUST REVERSER MECH ASSEMBLY	*CF		53ND-78100-4 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783009 LEFT	THRUST REVERSER FAN DUCT	*CF		53ND-78200-5 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783009 RIGHT	THRUST REVERSER FAN DUCT	*CF		53ND-78200-7 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR	*CF		53ND-78207-1 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR	*CF		53ND-78207-3 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR	*CF		53ND-78207-1 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR	*CF		53ND-78207-3 SN-UNKNOWN	MTH 27-Sep-1998		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
783101 LEFT INBOARD	STOW LIMIT SWITCH	LYH		53ND78304-1 NSN	MTH 27-Feb-2008 HRS 3076 LDG 2183		O/C		0	
783101 LEFT OUTBOARD	STOW LIMIT SWITCH	*CF		53ND78304-1 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783101 RIGHT INBOARD	STOW LIMIT SWITCH	*CF		53ND78304-1 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783101 RIGHT OUTBOARD	STOW LIMIT SWITCH	*CF		53ND78304-1 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
783102 LEFT	DEPLOY LIMIT SWITCH	LYH		53ND78304-3 NSN	MTH 27-Feb-2008 HRS 3076 LDG 2183		O/C		0	
783102 RIGHT	DEPLOY LIMIT SWITCH	*CF		53ND78304-3 SN-UNKNOWN	MTH 27-Sep-1998		O/C			
793002 LEFT	OIL TEMPERATURE TRANSMITTER	LYH		102-00083 2447	MTH 16-Jul-2011 HRS 3999.8 LDG 3144		O/C			
793002 RIGHT	OIL TEMPERATURE TRANSMITTER	LYH		102-00083 06125	MTH 18-Jul-2011 HRS 4002.3 LDG 3146		O/C	0	0	0
793004 LEFT	OIL PRESSURE TRANSMITTER	GSO		APTE-237D-1000- 250D 683410195	MTH 03-Oct-2004 HRS 1885		O/C	0		
793004 RIGHT	OIL PRESSURE TRANSMITTER	GSO		APTE-237C-1000- 250D 604411126	MTH 20-Sep-2005 HRS 2212		O/C	2212		
793006 LEFT	LOW OIL PRESSURE SWITCH	GSO		1153P0098 176	MTH 31-Jul-2004 HRS 1801		O/C	0		
793006 RIGHT	LOW OIL PRESSURE SWITCH	GSO		1153P0098 177	MTH 31-Jul-2004 HRS 1801		O/C	1801		
793007	N2/OIL PRESSURE/OIL TEMPERATURE INDICATOR	LYH		10602N01M00 B513A	MTH 28-Aug-2007 HRS 2839		O/C	0		
792002 E1	FUEL OIL HEAT EXCHANGER	*CF		D2552-600B M14961	MTH 27-Sep-1998		O/C			
792002 E2	FUEL OIL HEAT EXCHANGER	*CF		D2552-600B M14074	MTH 27-Sep-1998		O/C			
800010 LEFT <i>243001 : L</i>	STARTER GENERATOR	KARR		23080-025 95409	MTH 27-Aug-2018 HRS 6432.2 LDG 5064		1000	0	7432.2	652.1
800010 RIGHT <i>243001 : R</i>	STARTER GENERATOR	KARR		23080-025-1 98717	MTH 02-Nov-2018 HRS 6515.1 LDG 5122		1000	0	7515.1	735



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 R01)			RECOMMENDED			-			
	MOC :									
SL 550-03-02 R01	SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013)			INFORMATIONAL			-			
	MOC :									
SL 550-99-05 R07	CESCOM PRICING			INFORMATIONAL			-			
	MOC :									
SL 550-99-08	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 550-99-09	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R02)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R01)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			MTH RECOMMENDED			-			
	MOC :									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 R01)			INFORMATIONAL			-			
	MOC :									
SL 550-20-05	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
	MOC :									
SB 550-21-45 21SB-45 : 550	ACM BYPASS VALVE RELOCATION GSO			RECOMMENDED	MTH 29-Aug-2000 HRS 1005		-			Complete
	MOC : COMPLIED WITH									
SB 550-21-46 21SB-46 : 550	FLOOD COOLING DIODE REPLACEMENT GSO			RECOMMENDED	MTH 27-Mar-2001 HRS 1163		-			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 550-21-47 21SB-47 : 550	COCKPIT SIDE WINDOW DEFOG SYSTEM MODIFICATION OPTIONAL			MTH			-			
MOC :										
SB 550-21-49 21SB-49 : 550	CABIN FAN AND DEFOG BLOWER WIRING IMPROVEMENT DISCRETIONARY			MTH			-			
MOC :										
SB 550-21-50 21SB-50 : 550	RAM AIR DUCT IMPROVEMENT DISCRETIONARY			MTH			-			
MOC :										
SB 550-21-51 21SB-51 : 550	AIR CONDITIONING - DEFOG BLOWER BONDING JUMPER KARR RECOMMENDED			MTH 30-Oct-2013 HRS 4512.8 LDG 3575			1158			
MOC : DEFERRED - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 550-21-52 21SB-52 : 550	AIR CONDITIONING - CABIN ALTITUDE BAROMETRIC SWITCH IMPROVEMENT OPTIONAL			MTH			A/R			
MOC :										
SB 550-21-57 21SB-57 : 550	AIR CONDITIONING - TEMPERATURE CONTROLLER IMPROVEMENT OPTIONAL			MTH			A/R			
MOC :										
SB 550-21-58 R01	AIR CONDITIONING - PRESSURIZATION SYSTEM PLUMBING IMPROVEMENT KARR RECOMMENDED			MTH 30-Oct-2013 HRS 4512.8 LDG 3575			A/R			
MOC : DEFERRED - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT INFORMATIONAL						-			
MOC :										
SL CIL-21-02 R01	AIR CONDITIONING - ENVIRONMENTAL HOUR METER INSTALLATION UNK MANDATORY			MTH 19-Feb-2015 HRS 5089.4 LDG 4008			-			Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH OPERATIONAL CHECK SATISFACTORY.										
SL 550-21-27 R01 21SL-27 : 550R1	RAM AIR INLET DRAIN LINE INSPECTION FMY RECOMMENDED			MTH HRS			324			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB 550-23-22 23SB-22 : 550	ALLIEDSIGNAL 8.33 KHZ COMMUNICATION RADIO INSTALLATION GSO OPTIONAL			MTH 25-Jul-1999 HRS 518			-			Complete
MOC : COMPLIED WITH										
SB 550-23-23 R02 23SB-23 : 550R2	COMMUNICATIONS - COCKPIT SPEAKER MUTE SWITCH OPTIONAL			MTH			A/R			
MOC :										
SB 550-23-25 23SB-25 : 550	COM 1 COAX CABLE ROUTING INSPECTION GSO RECOMMENDED			MTH 05-Sep-1999 HRS 562			-			Complete
MOC : COMPLIED WITH										
SB 550-23-26 23SB-26 : 550	COMM 1 AND COMM2 WIRING MODIFICATION OPTIONAL			MTH			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 550-23-29 23SB-29 : 550	HONEYWELL KY-196A/B DUAL VHF COMMUNICATION SYSTEM UPGRADE	GSO	RECOMMENDED	MTH 26-Sep-2003 HRS 1585		-			Complete
MOC : COMPLIED WITH									
SB 550-23-32 23SB-32 : 550	COMMUNICATIONS - FIN TIP COMM ANTENNA IMPROVEMENT		OPTIONAL	MTH			A/R		
MOC :									
SL 550-23-28 23SL-28 : 550	TRANSMITTAL OF AIRSHOW SERVICE BULLETIN 920720-1 AIRSHOW 400 DIGITAL INTERFACE UNIT	GSO	RECOMMENDED	MTH 09-Dec-1999 HRS 701		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
SL 550-23-29 23SL-29 : 550	TRANSMITTAL OF ALLIEDSIGNAL BENDIX/KING SERVICE BULLETIN KY 196A-9 - KY 196A VHF COMM TRANSCEIVER	GSO	RECOMMENDED	MTH 24-Mar-2000 HRS 847		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
SL 550-23-30 23SL-30 : 550	TRANSMITTAL OF ALLIEDSIGNAL BENDIX/KING SB KY 196B-2 - KY 196B VHF COMM TRANSCEIVER	GSO	RECOMMENDED	MTH 24-Mar-2000 HRS 847		-			Complete
MOC : COMPLIED WITH									
SL 550-23-31 R01 23SL-31 : 550R1	COMMUNICATIONS - AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE	GSO	RECOMMENDED	MTH 26-Sep-2003 HRS 1585		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
SB 550-24-30 R01 24SB-30 : 550R1	CIRCUIT BREAKER TERMINAL SCREW LENGTH INSPECTION/REPLACEMENT	GSO	RECOMMENDED	MTH 26-Sep-2003 HRS 1585		-			Complete
MOC : COMPLIED WITH									
SB 550-24-30 24SB-30 : 550	CIRCUIT BREAKER TERMINAL SCREW LENGTH INSPECTION/REPLACEMENT (SUPERSEDED BY 550-24-30 R01)	GSO		MTH 09-Dec-1999 HRS 701			A/R		Complete
MOC : COMPLIED WITH									
SB 550-24-36 24SB-36 : 550	CIRCUIT BREAKER INSULATOR INSTALLATION	GSO	RECOMMENDED	MTH 27-Mar-2001 HRS 1163		-			Complete
MOC : COMPLIED WITH									
SB 550-24-37 R03 24SB-37 : 550R3	ELECTRICAL POWER - MAIN POWER WIRE ANCHOR IMPROVEMENT	FMY	RECOMMENDED	MTH HRS				241	
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									
SB 550-24-38 24SB-38 : 550	SEALED LEAD ACID BATTERY INSTALLATION	GSO	OPTIONAL	MTH 18-Nov-2003 HRS 1586		-			Complete
MOC : COMPLIED WITH									
SB 550-24-39 24SB-39 : 550	TAILCONE WIRE BUNDLE ASSEMBLY ROUTING IMPROVEMENT	GSO	MANDATORY	MTH 26-Sep-2003 HRS 1585		-			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 550-24-40 R02 <i>24SB-40 : 550R2</i>	ELECTRICAL POWER - CIRCUIT BREAKER AMPERAGE INCREASE FOR MEGGITT SECONDARY FLIGHT DISPLAY		OPTIONAL MTH			-			
MOC :									
SL 550-24-16 R01	AFT J-BOX BUS BAR AND WASHER INSPECTION (SUPERSEDED BY SL550-24-16 R02)	KLYH	MANDATORY MTH	21-Oct-2011		A/R			Complete
HRS 4051.7 LDG 3200									
MOC : COMPLIED WITH - COMPLIED WITH CESSNA SL550-24-16 R1 AFT J-BOX BUS BAR AND WASHER INSPECTION (EFF. DATE: APRIL 25, 2011). UPON INSPECTION, FOUND STEEL WASHERS UNDER THE CURRENT LIMITERS. REMOVED INCORRECT WASHERS AND REPLACED WITH NEW WASHERS P/N'S: S1450-5B14-187 AND 76236-1 IN ACCORDANCE WITH CESSNA SL550-24-16 R1.									
SL 550-24-16 R3	AFT J-BOX BUS BAR AND WASHER INSPECTION	UNK	MANDATORY MTH	03-Apr-2014		-			Complete
HRS 4650.8 LDG 3661									
MOC : COMPLIED WITH									
SB 550-25-40 <i>25SB-40 : 550</i>	PASSENGER SEAT ARMREST MODIFICATION		OPTIONAL MTH			A/R			
MOC :									
SB 550-25-43 R01 <i>25SB-43 : 550R1</i>	EQUIPMENT/FURNISHINGS - GLARESHIELD LEATHER STRIP INSTALLATION		OPTIONAL MTH			-			
MOC :									
SB 550-25-44 R01 <i>25SB-44 : 550R1</i>	EQUIPMENT/FURNISHINGS - ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) (SUPERSEDED BY 550-25-44 R02)		SUPERSEDED MTH			A/R			
MOC :									
SB 550-25-44 R03	EQUIPMENT/FURNISHINGS - ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)		OPTIONAL MTH			A/R			
MOC :									
SB 550-25-45 R01 <i>25SB-45 : 550R1</i>	EQUIPMENT/FURNISHINGS - TOILET TRAY AND PAD INSTALLATION		OPTIONAL MTH			A/R			
MOC : - SERVICE BULLETIN ON HOLD.									
SL 550-25-12 <i>25SL-12 : 550</i>	EQUIPMENT/FURNISHINGS - CABIN SYSTEMS AIRSHOW 400 DIGITAL INTERFACE UNIT (DIU) 920040 SERVICE BULLETIN 920040-44-01 SAVE MAIN CPU CMOS SETUP SETTINGS TO FLASH MEMORY		OPTIONAL MTH			A/R			
MOC :									
SL 550-25-14 <i>25SL-14 : 550</i>	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARYBUCKLE PLASTIC HANDLE	LYH	MANDATORY MTH	10-Feb-2010		A/R			Complete
HRS 3629									
MOC : COMPLIED WITH									
SB 550-26-04 <i>26SB-04 : 550</i>	FIRE DETECT CLAMP REPLACEMENT	GSO	RECOMMENDED MTH	09-Dec-1999		-			Complete
HRS 701									
MOC : COMPLIED WITH									
SB 550-26-05 <i>26SB-05 : 550</i>	FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION	GSO	MANDATORY MTH	21-Jul-2005		A/R			Complete
HRS 2169									
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL 550-26-02 26ASL02 : 550	FIRE PROTECTION - TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 - THERMISTORS DETECTORS	LYH	MANDATORY	MTH 04-Mar-2008 HRS 3091		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.									
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING	UNK	MANDATORY	MTH 08-Jul-2016 HRS 5655.8 LDG 4448		-			Complete
MOC : COMPLIED WITH - ALL CATRIDGES ARE GOOD									
SB 550-27-20 27SB-20 : 550	AILERON FASTENER INSPECTION/INSTALLATION (SUPERSEDED BY 550-27-20 R01)	GSO	MANDATORY	MTH 09-Dec-1999 HRS 701		A/R			Complete
MOC : COMPLIED WITH									
SB 550-27-21 27SB-21 : 550	TRIM TAB ACTUATOR GREASE FITTING INSTALLATION		OPTIONAL	MTH		-			
MOC :									
SB 550-27-22 R02 27SB-22 : 550R2	FLIGHT CONTROLS - STEEP APPROACH CERTIFICATION		OPTIONAL	MTH		-			
MOC :									
SL 550-27-10 27SL-10 : 550	ELEVATOR ELECTRIC TRIM TAB ACTUATOR MOUNT INSPECTION	GSO	RECOMMENDED	MTH 26-Sep-2003 HRS 1585		-			Complete
MOC : COMPLIED WITH									
SL 550-27-11 27SL-11 : 550	AILERON CABLE TURNBUCKLE CLEARANCE (SUPERSEDED BY SL550-27-11 R01)	GSO	MANDATORY	MTH 23-Dec-2002 HRS 1442		A/R			Complete
MOC : COMPLIED WITH									
SL 550-27-12 27SL-12 : 550	ELEVATOR TORQUE TUBE INSPECTION	GSO	MANDATORY	MTH 23-Dec-2002 HRS 1442		-			Complete
MOC : COMPLIED WITH									
SL 550-27-14 27SL-14 : 550	FLIGHT CONTROLS - RUDDER PEDAL SUPPORT INSPECTION	LYH	RECOMMENDED	MTH 10-Feb-2010 HRS 3629		A/R			Complete
MOC : COMPLIED WITH									
SB 550-28-07 R01 28SB-07 : 550R1	FUEL - CERTIFICATION OF JET B FUEL USE		OPTIONAL	MTH		-			
MOC :									
SB 550-28-09 28SB-09 : 550	RIGHT FUEL PROBE REPLACEMENT		MANDATORY	MTH 01-Feb-1999 HRS 270		-			Complete
MOC : COMPLIED WITH									
SB 550-28-11 28SB-11 : 550	MOTIVE FLOW FUEL TUBE REPLACEMENT (SUPERSEDED BY 550-28-11 R01)	GSO	MANDATORY	MTH 27-Mar-2001 HRS 1163		A/R			Complete
MOC : COMPLIED WITH									
SB 550-28-12 28SB-12 : 550	TANK BRACKET AND CLAMP INSTALLATION/INSPECTION	GSO	RECOMMENDED	MTH 27-Mar-2001 HRS 1163		-			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 550-28-13 R01 <i>28SB-13 : 550R1</i>	FUEL - WING FUEL TANK DRAIN INSTALLATION AND FUEL PROBE BRACKET INSPECTION (SUPERSEDED BY 550-28-13 R02)	GSO		SUPERSEDED	MTH 23-Dec-2002 HRS 1442		A/R			Complete
MOC : COMPLIED WITH										
SB 550-28-15 <i>28SB-15 : 550</i>	FUEL - WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT (SUPERSEDED BY 550-28-15 R01)	MCO		MANDATORY	MTH 09-Mar-2004 HRS 1646		A/R			Complete
MOC : COMPLIED WITH										
SB 550-28-16 R01	FUEL - FUEL CHECK VALVE MODIFICATION	KLYH		RECOMMENDED	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB550-28-16 R1 FUEL CHECK VALVE MODIFICATION IAW CESSNA 550B SB550-28-16R1. LEAK CHECK OKAY THIS TIME AND DATE.										
SB 550-29-11 <i>29SB-11 : 550</i>	HYDRAULIC LINE IMPROVEMENT	GSO		MANDATORY	MTH 29-Aug-2000 HRS 1005		-			Complete
MOC : COMPLIED WITH										
SB 550-29-12 R01 <i>29SB-12 : 550R1</i>	HYDRAULIC POWER - LANDING GEAR RETURN LINE CHECK VALVE REPLACEMENT	GSO		MANDATORY	MTH 23-Dec-2002 HRS 1442		A/R			Complete
MOC : COMPLIED WITH										
ASL 550-29-11 R01 <i>29ASL11 : 550R1</i>	HYDRAULIC POWER - TAILCONE HYDRAULIC TUBE INSPECTION (SUPERSEDED BY ASL550-29-11 R02)	GSO		MANDATORY	MTH 26-Sep-2003 HRS 1585		A/R			Complete
MOC : COMPLIED WITH										
ASL 550-29-11 R02 <i>29ASL11 : 550R2</i>	HYDRAULIC POWER - TAILCONE HYDRAULIC TUBE INSPECTION (SUPERSEDED BY ASL550-29-11 R03)	MCO		MANDATORY	MTH 30-Dec-2004 HRS 1984		A/R			Complete
MOC : COMPLIED WITH										
ASL 550-29-11 R04 <i>29ASL11 : 550R4</i>	HYDRAULIC POWER - TAILCONE HYDRAULIC TUBE INSPECTION	GSO		MANDATORY	MTH 11-Aug-2005 HRS 2181		-			Complete
MOC : COMPLIED WITH										
ASL 550-29-11 <i>29ASL11 : 550</i>	HYDRAULIC POWER - TAILCONE HYDRAULIC TUBE INSPECTION (SUPERSEDED BY ASL550-29-11 R01)	GSO		SUPERSEDED	MTH 30-Aug-2002 HRS 1312		A/R			Complete
MOC : COMPLIED WITH										
SL 550-29-12 <i>29SL-12 : 550</i>	HYDRAULIC LINE SUPPORT HARDWARE INSPECTION	GSO		MANDATORY	MTH 26-Sep-2003 HRS 1585		-			Complete
MOC : COMPLIED WITH										
SL 550-29-13 <i>29SL-13 : 550</i>	HYDRAULIC TUBE INSPECTION AND CLAMP ATTACHMENT (SUPERSEDED BY SL550-29-13 R01)	MCO		MANDATORY	MTH 18-May-2004 HRS 1721		A/R			Complete
MOC : COMPLIED WITH										
SL 550-29-15 <i>29SL-15 : 550</i>	HYDRAULIC POWER - HYDRAULIC FIREWALL SHUTOFF VALVE INSPECTION	LYH		MANDATORY	MTH 10-Feb-2010 HRS 3629		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 550-30-04 30SB-04 : 550	WINDSHIELD ANTI-ICE BLEED AIR SWITCH INSPECTION/REPLACEMENT	GSO	MANDATORY	MTH 30-Aug-2002 HRS 1312		-			Complete
MOC : COMPLIED WITH									
SB 550-30-05 30SB-05 : 550	ANTI-ICE WING LEADING EDGE INSTALLATION, FASTENER CHANGE	ICT	MANDATORY	MTH 11-Apr-2002 HRS 1271		A/R			Complete
MOC : COMPLIED WITH									
SB 550-30-06 30SB-06 : 550	ELECTRIC HEATED LEADING EDGE RESISTOR IMPROVEMENT		OPTIONAL	MTH		-			
MOC :									
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			-			
MOC :									
SL 550-30-05 30SL-05 : 550	WING ANTI-ICE TEMPERATURE CONTROLLER REPLACEMENT	GSO	RECOMMENDED	MTH 27-Mar-2001 HRS 1163		-			Complete
MOC : COMPLIED WITH									
SB 550-31-06 R01 31SB-06 : 550R1	INDICATING/RECORDING SYSTEMS - INADVERTENT POWER BRAKE LOW PRESSURE ANNUNCIATION	GSO	RECOMMENDED	MTH 26-Sep-2003 HRS 1585		-			Complete
MOC : COMPLIED WITH									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION		INFORMATIONAL			-			
MOC :									
SB 550-32-35 32SB-35 : 550	LANDING GEAR - MAIN LANDING GEAR OLEO MODIFICATION (SUPERSEDED BY 550-32-35 R01)	GSO	SUPERSEDED	MTH 05-Sep-1999 HRS 562		A/R			Complete
MOC : COMPLIED WITH									
SB 550-32-39 32SB-39 : 550	MAIN LANDING GEAR SCUFF PROTECTION MODIFICATION	GSO	RECOMMENDED	MTH 27-Mar-2001 HRS 1163		-			Complete
MOC : COMPLIED WITH - SERVICE INFORMATION ITEM COMPLIED WITH PREVIOUSLY. DATE AND OR HOURS UNKNOWN.									
SB 550-32-40 R03 32SB-40 : 550R3	LANDING GEAR ON GROUND OPERATION AND MODIFICATION	GSO	RECOMMENDED	MTH 26-Sep-2003 HRS 1585		-			Complete
MOC : COMPLIED WITH									
SB 550-32-43 32SB-43 : 550	MAIN LANDING GEAR WIRE BUNDLE ANCHOR IMPROVEMENT	GSO	RECOMMENDED	MTH 27-Mar-2001 HRS 1163		OPEN OPEN OPEN			Complete
MOC : COMPLIED WITH									
SB 550-32-46 R01 32SB-46 : 550R1	BRAKE LOW PRESSURE NON-CANCELABLE MASTER CAUTION IMPROVEMENT (SUPERSEDED BY 550-32-46 R02)	GSO	RECOMMENDED	MTH 26-Sep-2003 HRS 1585		A/R			Complete
MOC : COMPLIED WITH									
SB 550-32-48 R03 32SB-48 : 550R3	LANDING GEAR - NLG ACTUATOR REPLACEMENT	GSO	MANDATORY	MTH 21-Jul-2005 HRS 2169		-			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 550-32-50 R01 32SB-50 : 550R1	LANDING GEAR - PARKING BRAKE CABLE REPLACEMENT OPTIONAL			MTH			A/R			
MOC :										
SB 550-32-52 32SB-52 : 550	LANDING GEAR-BRAKE HYDRAULIC PACK FILTER BOWL REPLACEMENT	GSO		RECOMMENDED	MTH 03-Nov-2006 HRS 2429		A/R			Complete
MOC : COMPLIED WITH										
ASL 550-32-85 32ASL85 : 550	LANDING GEAR-MAIN LANDING GEAR TIRE INSPECTION	LYH		MANDATORY	MTH 01-Aug-2008 HRS 3274 LDG 2389		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL INFORMATIONAL						-			
MOC :										
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION	UNK		RECOMMENDED	MTH 02-Jul-2015 HRS 5252.6 LDG 4133		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SERVICE LETTER CIL-32-03 BY INSPECTION OF THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET INSTALLATION,NO DEFECTS NOTED										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION INFORMATIONAL						-			
MOC :										
SL 550-32-30 32SL-30 : 550	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1588-32-1, INTRODUCTION OF NEW PREFORMED PACKINGS	MCO		RECOMMENDED	MTH 09-Mar-2004 HRS 1646		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.										
SL 550-32-74 32SL-74 : 550	GEAR EMERGENCY BRACKET SPACER INSPECTION/INSTALLATION (SUPERSEDED BY SL550-32-74 R01)	GSO		RECOMMENDED	MTH 27-Mar-2001 HRS 1163		-			Complete
MOC : COMPLIED WITH										
SL 550-32-77 32SL-77 : 550	NOSE LANDING GEAR ACTUATOR UNLOCK PRESS TEST (SUPERSEDED BY SL550-32-77 R01)	GSO		MANDATORY	MTH 26-Sep-2003 HRS 1585		A/R			Complete
MOC : COMPLIED WITH										
SL 550-32-79 R01 32SL-79 : 550R1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION OPTIONAL			MTH			O/C			
MOC :										
SL 550-32-83 32SL-83 : 550	HYDRAULIC LINE INSPECTION/REPLACEMENT	LYH		RECOMMENDED	MTH 04-Mar-2008 HRS 3091		A/R			Complete
MOC : COMPLIED WITH										
SL 550-32-84 32SL-84 : 550	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE LETTER 2056	LYH		RECOMMENDED	MTH 10-Feb-2010 HRS 3629		A/R			Complete
MOC : COMPLIED WITH										
SL 550-32-86 R01 LEFT	TRAILING LINK FORWARD BORE CORROSION PROTECTION	KARR		RECOMMENDED	MTH 30-Oct-2013 HRS 4512.8 LDG 3575		-			
MOC : DEFERRED - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 550-32-86 R01 RIGHT	TRAILING LINK FORWARD BORE CORROSION PROTECTION	KARR	RECOMMENDED	MTH 30-Oct-2013 HRS 4512.8 LDG 3575		-			
MOC : DEFERRED - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL 550-32-87 32SL-87 : 550	LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION	KLYH	MANDATORY	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL550-32-87 DURING LANDING GEAR OPERATIONAL CHECKS. OPERATIONAL CHECKS GOOD, NO FURTHER ACTION IS REQUIRED.									
SL 550-32-88 R01	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1588-32-3, REPLACEMENT OF BLEEDER SCREWS AND BLEEDER FITTINGS WITH BLEEDER PLUGS		RECOMMENDED			-			
MOC : DECLINED									
SB 550-33-24 33SB-24 : 550	WING TIP LANDING LIGHT ASSEMBLY 250W LAMP INSTALLATION		OPTIONAL	MTH		-			
MOC :									
SB 550-33-26 33SB-26 : 550	G-SWITCH MOUNTING IMPROVEMENT	GSO	RECOMMENDED	MTH 05-Sep-1999 HRS 562		-			Complete
MOC : COMPLIED WITH									
SB 550-33-29 33SB-29 : 550	LED TAIL POSITION LITE REPLAC		OPTIONAL	MTH		A/R			
MOC :									
SB 550-33-31 33SB-31 : 550	CHART LIGHT MODIFICATION		OPTIONAL	MTH		-			
MOC :									
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY		INFORMATIONAL			-			
MOC :									
SB 550-34-101 34SB-101 : 550	NAVIGATION - UNIVERSLA AVIONICS UNS-1CSP UPGRADE TO UNS-1CSP+ WITH SOFTWARE CONTROL NUMBER (SCN) 802.2		OPTIONAL	MTH		A/R			
MOC :									
SB 550-34-104 R01 34SB-104 : 550R1	HONEYWELL PRIMUS 1000 PHASE III SOFTWARE UPGRADE	GSO	RECOMMENDED	MTH 03-Nov-2006 HRS 2429		A/R			Complete
MOC : COMPLIED WITH									
SB 550-34-107 34SB-107 : 550	RUNWAY AWARENESS AND ADVISORY SYSTEM (RAAS) AUDIO INHIBIT SWITCH INSTALLATION		OPTIONAL	MTH		A/R			
MOC :									
SB 550-34-111 R01 34SB-111 : 550	NAVIGATION - GNS-XLS SOFTWARE MOD 8 UPGRADE		DISCRETIONARY			A/R			
MOC :									
SB 550-34-111 34SB-111 : 550	NAVIGATION - GNS-XLS SOFTWARE MOD 8 UPGRADE (SUPERSEDED BY 550-34-111 R01)		DISCRETIONARY	MTH		A/R			N/A
MOC : NOT APPLICABLE - SUPERSEDED SUPERSEDED BY 550-34-111 REV1									
SB 550-34-112 R01 34SB-112 : 550R1	NAVIGATION - MEGGITT MARK II SECONDARY FLIGHT DISPLAY INDICATOR AND AIR DATA UNIT INSTALLATION (SUPERSEDED BY 550-34-112 R02)		OPTIONAL	MTH		A/R			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 550-34-112 R02	NAVIGATION - MEGGITT MARK I SECONDARY FLIGHT DISPLAY INDICATOR AND AIR DATA UNIT REPLACEMENT OR MARK II SECONDARY FLIGHT DISPLAY INDICATOR REPLACEMENT (SUPERSEDED BY 550-34-112 R03)			OPTIONAL			-			
MOC :										
SB 550-34-112 R03	NAVIGATION - MEGGITT MARK I SECONDARY FLIGHT DISPLAY INDICATOR AND AIR DATA UNIT REPLACEMENT OR MARK II SECONDARY FLIGHT DISPLAY INDICATOR REPLACEMENT			OPTIONAL			-			
MOC :										
SB 550-34-115 R01	INSTALLATION OF SCN 802.8 FOR UNS-1 FMS (SUPERSEDED BY 550-34-115 R02)			RECOMMENDED			-			
MOC :										
SB 550-34-115 R02	INSTALLATION OF SCN 802.8 FOR UNS-1 FMS	KARR		RECOMMENDED	MTH 30-Oct-2013 HRS 4512.8 LDG 3575		-			
MOC : DEFERRED - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 550-34-115	INSTALLATION OF SCN 802.8 FOR UNS-1 FMS (SUPERSEDED BY 550-34-115 R01)			RECOMMENDED			-			
MOC :										
SB 550-34-116 R01	NAVIGATION - UNIVERSAL SOLID STATE TRANSFER UNIT (SSDTU) UPGRADE			OPTIONAL			-			
MOC :										
SB 550-34-116	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE			OPTIONAL			A/R			
MOC :										
SB 550-34-117 R01	NAVIGATION - UNIVERSAL FMS WAAS UNS-1LW UPGRADE			OPTIONAL			-			
MOC :										
SB 550-34-117	NAVIGATION - UNIVERSAL FMS WAAS UNS-1LW UPGRADE (SUPERSEDED BY 550-34-117 R01)			OPTIONAL			-			
MOC :										
SB 550-34-118	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE			OPTIONAL			-			
MOC :										
SB 550-34-64 R01 <i>34SB-64 : 550R1</i>	NAVIGATION - MEGGITT SECONDARY FLIGHT DISPLAY IMPROVEMENTS	GSO		RECOMMENDED	MTH 05-Sep-1999 HRS 562		-			Complete
MOC : COMPLIED WITH										
SB 550-34-70 R01 <i>34SB-70 : 550R1</i>	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION	MCO		OPTIONAL	MTH 09-Mar-2004 HRS 1646		-			Complete
MOC : COMPLIED WITH										
SB 550-34-70 <i>34SB-70 : 550</i>	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION (SUPERSEDED BY 550-34-70 R01)	GSO		OPTIONAL	MTH 05-Sep-1999 HRS 562		A/R			Complete
MOC : COMPLIED WITH										
SB 550-34-71 <i>34SB-71 : 550</i>	HONEYWELL PRIMUS 1000 PHASE II SOFTWARE UPGRADE (SUPERSEDED BY 550-34-71 R01)	GSO		RECOMMENDED	MTH 27-Mar-2001 HRS 1163		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 550-34-73 <i>34SB-73 : 550</i>	GNS-X/L S SOFTWARE MOD 4 UPGRADE	GSO		RECOMMENDED	MTH 22-Jun-1999 HRS 451		-			Complete
MOC : COMPLIED WITH										
SB 550-34-74 <i>34SB-74 : 550</i>	TCAS II SOFTWARE CHANGE 7 UPGRADE			OPTIONAL	MTH		-			
MOC :										
SB 550-34-76 <i>34SB-76 : 550</i>	NAVIGATION - UNS-1K 603.4 SOFTWARE UPGRADE (SUPERSEDED BY 550-34-76 R01)	GSO		RECOMMENDED	MTH 29-Aug-2000 HRS 1005		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB 550-34-80 <i>34SB-80 : 550</i>	GNS-XLS FMS MOD 6 SOFTWARE UPGRADE (SUPERSEDED BY 550-34-80 R01)	ICT		RECOMMENDED	MTH 11-Apr-2002 HRS 1271		A/R			Complete
MOC : COMPLIED WITH										
SB 550-34-81 <i>34SB-81 : 550</i>	UNIVERSAL AVIONICS UNS-1K FLIGHT MANAGEMENT SYSTEM FLAT PANEL CONTROL DISPLAY UNIT UPGRADE TO MOD 8	GSO		MANDATORY	MTH 30-Aug-2002 HRS 1312		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB 550-34-85 R02 <i>34SB-85 : 550R2</i>	NAVIGATION - TCAS RAIN COVER INSTALLATION	GSO		RECOMMENDED	MTH 26-Sep-2003 HRS 1585		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB 550-34-88 R01 <i>34SB-88 : 550R1</i>	NAVIGATION - MARK VIII TERRAIN AWARENESS & WARNING SYSTEM (TAWS) INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 550-34-89 R01 <i>34SB-89 : 550R1</i>	NAVIGATION - MARK VII TERRAIN AWARENESS & WARNING SYSTEM (TAWS) INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 550-34-90 <i>34SB-90 : 550</i>	5 AMP-HOUR STANDBY GYRO BATTERY INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 550-34-91 R01 <i>34SB-91 : 550R1</i>	NAVIGATION - HONEYWELL TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE			OPTIONAL	MTH		A/R			
MOC :										
SB 550-34-92 R03 <i>34SB-92 : 550R3</i>	NAVIGATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) II AND MST-67A TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE			OPTIONAL	MTH		A/R			
MOC : - SERVICE BULLETIN ON HOLD.										
SB 550-34-98 R01 <i>34SB-98 : 550R1</i>	NAVIGATION - HONEYWELL MARK VII EGPWS SOFTWARE UPDATE TO VERSION -219-219			OPTIONAL	MTH		-			
MOC :										
SB 550-34-99 <i>34SB-99 : 550</i>	RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) INSTALLATION			OPTIONAL	MTH		-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASL 550-34-34 34SLA34 : 550	KLN 89B, 90B AND KLN 900 GPS INSTRUMENT LANDING SYSTEM APPROACH RESTRICTIONS	ICT	MANDATORY	MTH 28-Oct-1998 HRS 37		-			Complete
MOC : COMPLIED WITH									
ASL 550-34-38 34ASL38 : 550	FLAP PANEL CONTROL DISPLAY UNIT INVERTER CIRCUITRY INTEGRITY TEST	ICT	MANDATORY	MTH 04-May-2002 HRS 1271		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
SL CIL-34-01	NAVIGATION - TRANSMIT UNIVERSAL AVIONICS ALERT SERVICE BULLETIN 3XXX.()-34-3508		INFORMATIONAL			-			
MOC :									
SL CIL-34-03 R01	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGHVOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY (SUPERSEDED BY CIL-34-03 R02)					-			
MOC :									
SL CIL-34-03 R02	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY					-			
MOC :									
SL CIL-34-03	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY (SUPERSEDED BY CIL-34-03 R01)					-			
MOC :									
SL 550-34-41 34SL-41 : 550	INSPECT FOR PRESENCE OF VENDOR SPECIFIC COMPONENTS AND REPLACE AS REQUIRED	FMY	RECOMMENDED	MTH		12			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									
SL 550-34-45 34SL-45 : 550	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014700-34-0040	GSO	RECOMMENDED	MTH 11-Aug-2005 HRS 2181		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
SL 550-34-51 34SL-51 : 550	TRANSMITTAL OF HONEYWELL SOFTWARE BULLETIN SWB TPU 67A-SW8		DISCRETIONARY	MTH		-			
MOC :									
SL 550-34-57	NAVIGATION - TRANSMITTAL OF HONEYWELL SWB MST 67A-SW5	UNK	RECOMMENDED	MTH 08-Jul-2016 HRS 5655.8 LDG 4448		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED ON AIRCRAFT									
SB 550-35-03 R04 35SB-03 : 550R4	OXYGEN - EROS OXYGEN MASK INSTALLATION		OPTIONAL	MTH		A/R			
MOC :									
SB 550-35-06 R01 35SB-06 : 550R1	EROS MLD20-506 OXYGEN MASK INSTALLATION	GSO	OPTIONAL	MTH 03-Nov-2006 HRS 2429		A/R			Complete
MOC : COMPLIED WITH									
SB 550-35-08 35SB-08 : 550	EROS MLD20-510 OXYGEN MASK INSTALLATION		OPTIONAL	MTH		A/R			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	UNK		MANDATORY	MTH 29-Jan-2016 DAYS 5516.9 HRS 4326 LDG		-			N/A
MOC : NOT APPLICABLE - P/N AND S/N MASKS ARE NOT LISTED AS AFFECTED,N/A DUE TO INSTALLED MASKS P/N										
SL 550-35-08	OXYGEN - OXYGEN BOTTLE INSPECTION			INFORMATIONAL	MTH		A/R			
MOC :										
SL 550-35-09 R01	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL550-35-09 R02)			MANDATORY			-			
MOC :										
SL 550-35-09 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	KARR		MANDATORY	MTH 30-Oct-2013 HRS 4512.8 LDG 3575		-			N/A
MOC : NOT APPLICABLE - THIS SERVICE BULLETIN IS NOT APPLICABLE TO THIS AIRCRAFT DUE TO THE SERIAL NUMBERS NOT BEING INCLUDED IN AFFECTED UNITS.										
SL 550-35-09	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL550-35-09 R01)			MANDATORY			-			
MOC :										
SB 550-36-05 36SB-05 : 550	DOOR SEAL VALVE REPLACEMENT AND WATER TRAP INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 550-36-08 R01 36SB-08 : 550R1	BLEED AIR TUBE REPLACEMENT	GSO		RECOMMENDED	MTH 03-Nov-2006 HRS 2429		-			Complete
MOC : COMPLIED WITH - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 550-36-09 R01 36SB-09 : 550R1	TAILCONE PNEUMATIC TUBE IMPROVEMENT			DISCRETIONARY	MTH		-			
MOC :										
SL 550-36-03 36SL-03 : 550	PNEUMATIC - ENGINE BLEED AIR COUPLING SAFETY WIRE ADDICTION (SUPERSEDED BY SL550-36-03 R01)	GSO		RECOMMENDED	MTH 26-Sep-2003 HRS 1585		A/R			Complete
MOC : COMPLIED WITH										
SB 550-52-30 52SB-30 : 550	RTM CABIN DOOR STEP ASSEMBLY INSTALLATION	GSO		RECOMMENDED	MTH 05-Sep-1999 HRS 562		-			Complete
MOC : COMPLIED WITH										
SB 550-52-33 R01 52SB-33 : 550R1	DOORS - RAIN GUTTER FASTENER INSPECTION/REPLACEMENT	GSO		RECOMMENDED	MTH 26-Sep-2003 HRS 1585		-			Complete
MOC : COMPLIED WITH										
SB 550-52-35 52SB-35 : 550	MODIFICATION OF THE COMPOSITE STEP RATE CONTROL ATTACHMENTS	ICT		RECOMMENDED	MTH 11-Apr-2002 HRS 1271		-			Complete
MOC : COMPLIED WITH										
SB 550-52-36 R01 52SB-36 : 550R1	DOORS - ENTRY DOOR CABLE REPLACEMENT	GSO		RECOMMENDED	MTH 18-Nov-2003 HRS 1586		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 550-52-37 52SB-37 : 550	CABIN ENTRANCE DOOR THRESHOLD STEP CLOSEOUT IMPROVEMENT	GSO	RECOMMENDED	MTH 26-Sep-2003 HRS 1585		-			Complete
MOC : COMPLIED WITH									
SB 550-52-38 R01 52SB-38 : 550R1	DOORS - IMPROVEMENT FOR THE CABIN ENTRY STEPS OPTIONAL			MTH		A/R			
MOC :									
SB 550-52-39 52SB-39 : 550	DOORS - WIDE DOOR MODIFICATION		OPTIONAL	MTH		A/R			
MOC :									
ASL 550-52-04 52ASL04 : 550	DOORS - EMERGENCY DOOR INSPECTION	LYH	MANDATORY	MTH 04-Mar-2008 HRS 3091		A/R			N/A
MOC : NOT APPLICABLE - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.									
ASL 550-52-05 R01	DOORS - EMERGENCY EXIT INSPECTION	KLYH	MANDATORY	DAYS 21-Oct-2011 HRS 4051.7 LDG 3200		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH ASL550-52-05 R1 (EFF DATE MAY 16, 2011) BY REMOVING EMERGENCY EXIT DOOR, INSPECTING DOOR SEAL, APPLYING LAYER OF PETROLEUM JELLY TO THE SEAL, AND REINSTALLING DOOR IAW ASL550-52-05 R1. NO FURTHER ACTION IS REQUIRED.									
SB 550-53-31 53SB-31 : 550	FUSELAGE MOISTURE DRAIN INSTALLATION		OPTIONAL	MTH		-			
MOC :									
SB 550-53-32 R02 53SB-32 : 550R2	FUSELAGE - NOSE WHEEL STEERING BRACKET REPLACEMENT	GSO	MANDATORY	MTH 27-Mar-2001 HRS 1163		A/R			Complete
MOC : COMPLIED WITH									
SB 550-53-32 53SB-32 : 550	FUSELAGE - NOSE WHEEL STEERING BRACKET REPLACEMENT (SUPERSEDED BY 550-53-32 R01)	GSO	MANDATORY	MTH 09-Dec-1999 HRS 701		A/R			Complete
MOC : COMPLIED WITH									
SB 550-53-33 53SB-33 : 550	ENGINE CARRY THRU BEAM BRACKET INSTALLATION	GSO	MANDATORY	MTH 27-Mar-2001 HRS 1163		A/R			Complete
MOC : COMPLIED WITH									
SB 550-53-34 53SB-34 : 550	FLOORBOARD IMPROVEMENT		OPTIONAL	MTH		-			
MOC :									
SB 550-53-35 53SB-35 : 550	TAILCONE RIVET INSPECTION/INSTALLATION	GSO	RECOMMENDED	MTH 26-Sep-2003 HRS 1585		-			Complete
MOC : COMPLIED WITH									
SB 550-53-37 53SB-37 : 550	WHEEL WELL BOX/SKIN GAP IMPROVEMENT		OPTIONAL	MTH		-			
MOC :									
SL 550-53-06 53SL-06 : 550	DORSAL FIN VANE INSPECTION	GSO	RECOMMENDED	MTH 12-Apr-2006 HRS 2324		-			Complete
MOC : COMPLIED WITH									
SL 550-53-07 53SL-07 : 550	INTERCOSTAL DRAIN PATH INSPECTION (SUPERSEDED BY SL550-53-07 R01)	GSO	RECOMMENDED	MTH 12-Apr-2006 HRS 2324		-			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 550-54-07 <i>54SB-07 : 550</i>	NACELLES/PYLONS - NACELLE APRON MODIFICATION (SUPERSEDED BY 550-54-07 R01)	ICT		RECOMMENDED	MTH 17-Jun-2000 HRS 928		A/R			Complete
MOC : COMPLIED WITH										
SB 550-54-08 R02 <i>54SB-08 : 550R2</i>	NACELLE OIL DOOR HINGE IMPROVEMENT	GSO		RECOMMENDED	MTH 26-Sep-2003 HRS 1585		-			Complete
MOC : COMPLIED WITH										
SB 550-54-09 R01	NACELLES/PYLONS - OIL DOOR IMPROVEMENT			RECOMMENDED			-			
MOC :										
SB 550-54-09 <i>54SB-09 : 550</i>	NACELLES/PYLONS - OIL DOOR IMPROVEMENT (SUPERSEDED BY 550-54-09 R01)	KLYH		RECOMMENDED	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		-			
MOC : DEFERRED - CUSTOMER REQUEST NO ACTION TAKEN AT THIS TIME. NO FURTHER ACTION REQUIRED.										
SB 550-56-02 <i>56SB-02 : 550</i>	WINDOWS - COPILOT SIDE WINDOW REPAIR (SUPERSEDED BY 550-56-02 R01)	GSO		MANDATORY	MTH 27-Mar-2001 HRS 1163		A/R			Complete
MOC : COMPLIED WITH										
ASL 550-56-03 <i>56ASL03 : 550</i>	REQUIRED PRISM INSPECTION FOR COPILOT SIDE WINDOW	GSO		RECOMMENDED	MTH 27-Mar-2001 HRS 1163 LDG 595		A/R			Complete
MOC : COMPLIED WITH										
SB 550-57-09 <i>57SB-09 : 550</i>	WHEEL WELL STRUCTURE IMPROVEMENTS	GSO		RECOMMENDED	MTH 24-Mar-2000 HRS 847		-			Complete
MOC : COMPLIED WITH										
SB 550-57-10 R01 <i>57SB-10 : 550R1</i>	WING RIVET INSPECTION	GSO		MANDATORY	MTH 03-Nov-2006 HRS 2429		A/R			Complete
MOC : COMPLIED WITH										
SB 550-71-05 <i>71SB-05 : 550</i>	ENGINE DRAIN LINE MODFICATION	MCO		RECOMMENDED	MTH 09-Mar-2004 HRS 1646		-			Complete
MOC : COMPLIED WITH										
SB 550-71-07 LH	ACCOMPLISH POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION LH ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION			OPTIONAL			-			
MOC :										
SB 550-71-07 RT ENG	ACCOMPLISH POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION RH ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION			OPTIONAL			-			
MOC :										
SB 550-71-07	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION			OPTIONAL			-			
MOC :										
SL 550-71-08 <i>71SL-08 : 550</i>	LOWER ENGINE COWLING DRAIN HOLE INSTALLATION	GSO		SUPERSEDED	MTH 09-Dec-1999 HRS 701		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 550-71-10 R01 <i>71SL-10 : 550R1</i>	ENGINE ELECTRICAL GROUND STUD INSPECTION	MCO	RECOMMENDED	MTH 18-May-2004 HRS 1721		-			Complete
MOC : COMPLIED WITH									
SL 550-71-11 R02 <i>71SL-11 : 550R2</i>	POWER PLANT - ENGINE WIRE BUNDLE INSPECTION	LYH	RECOMMENDED	MTH 10-Feb-2010 HRS 3629		A/R			Complete
MOC : COMPLIED WITH									
SL 550-71-11 <i>71SL-11 : 550</i>	POWER PLANT - ENGINE WIRE BUNDLE INSPECTION (SUPERSEDED BY SL550-71-11 R01)	GSO	RECOMMENDED	MTH 03-Nov-2006 HRS 2429		-			Complete
MOC : COMPLIED WITH									
ASL 550-72-29 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO - VALVE - INSPECTION/REPLACEMENT OF	KLYH	MANDATORY	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		A/R			Complete
MOC : COMPLIED WITH - CESSNA ASL550-72-29 WAS ACCOMPLISHED IN ACCORDANCE WITH PRATT & WHITNEY SERVICE BULLETIN PW500-72-30420R2 ON LH ENGINE, S/N: PCE-DA0101, AT ENGINE OVERHAUL BY PRATT & WHITNEY, CRS# LM1R301K, UNDER SALES ORDER NO. 169907.									
ASL 550-72-29 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE-INSPECTION/REPLACEMENT OF	KLYH	MANDATORY	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		A/R			Complete
MOC : COMPLIED WITH - CESSNA ASL550-72-29 WAS ACCOMPLISHED IN ACCORDANCE WITH PRATT & WHITNEY SERVICE BULLETIN PW500-72-30420R2 ON RH ENGINE, S/N: PCE-DA0107, AT ENGINE OVERHAUL BY PRATT & WHITNEY, CRS# LM1R301K, UNDER SALES ORDER NO. 169918.									
SL 550-72-18 <i>72SL-18 : 550</i>	TRANSMITTAL OF P&WC SB PW500-72-30048, TURBOFAN ENGINE, IGNITION EXCITER - REPLACEMENT OF IGNITION EXCITER TO IGNITER CABLE	ICT	RECOMMENDED	MTH 01-Feb-1999 HRS 270		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.									
SL 550-72-19 <i>72SL-19 : 550</i>	TRANSMITTAL OF P&WC SB PW500-72-30058R1, TURBOFAN ENGINE FAN INLET CASE ABRADABLE - INSPECTION OF	ICT	RECOMMENDED	MTH 01-Feb-1999 HRS 270		A/R			Complete
MOC : COMPLIED WITH									
SL 550-72-20 R01 <i>72SL-20 : 550R1</i>	TRANSMITTAL OF P&WC SERVICE BULLETIN PW500-72-30063, TURBOFAN ENGINE SECOND STAGE HP COMPRESSOR ROTOR CLEARANCE - BOROSCOPE	ICT	RECOMMENDED	MTH 01-Feb-1999 HRS 270		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.									
SL 550-72-21 <i>72SL-21 : 550</i>	TRANSMIT P&WC SB PW500-72-30044, TURBOFAN ENGINE COMPRESSOR STATOR (2 STG.) ASSEMBLY - REPLACEMENT/MODIFICATION OF	ICT	RECOMMENDED	MTH 01-Feb-1999 HRS 270		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.									
SL 550-72-23 <i>72SL-23 : 550</i>	REPLACEMENT/MODIFICATION OF TURBOFAN ENGINE FUEL CONTROL UNIT	GSO	RECOMMENDED	MTH 26-Mar-1999 HRS 283		-			Complete
MOC : COMPLIED WITH									
SL 550-72-25 <i>72SL-25 : 550</i>	TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30217, INSPECTION OF TURBOFAN ENGINE FUEL TUBE	GSO	RECOMMENDED	MTH 30-Aug-2002 HRS 1312		-			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 550-72-28 LEFT ENGINE 72SL-28 : L	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT REPLACEMENT,MODIFICATION OF	KLYH	MANDATORY	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		6			Complete
MOC : COMPLIED WITH									
SL 550-72-28 RIGHT ENGINE 72SL-28 : R	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT - REPLACEMENT/MODIFICATION OF	KLYH	MANDATORY	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		6			Complete
MOC : COMPLIED WITH - COMPLIED WITH CESSNA SL550-72-28 ON RH ENGINE, S/N: PCE-DA0107. AN OVERHAULED RH FCU, S/N: F40029, WAS INSTALLED ON 03/12/09 AND IS POST SERVICE BULLETIN 30390. P&W SERVICE BULLETIN PW500-72-30409R6 NOT APPLICABLE, NO FURTHER ACTION REQUIRED.									
SB PW500-72-30044 R03 E1	REPLACEMENT/MODIFICATION OF COMPRESSOR STATOR (2 STG.) ASSEMBLY CATEGORY 6					-			
MOC :									
SB PW500-72-30044 R03 E2	REPLACEMENT/MODIFICATION OF COMPRESSOR STATOR (2 STG.) ASSEMBLY CATEGORY 6					-			
MOC :									
SB PW500-72-30075 R01 E1	REPLACEMENT OF MOUNTING HARDWARE CATEGORY 8					-			
MOC :									
SB PW500-72-30075 R01 E2	REPLACEMENT OF MOUNTING HARDWARE CATEGORY 8					-			
MOC :									
SB PW500-72-30131 R02 E1	REPLACEMENT OF COLD START VALVE ASSEMBLY CATEGORY 3					A/R			
MOC :									
SB PW500-72-30131 R02 E2	REPLACEMENT OF COLD START VALVE ASSEMBLY CATEGORY 3					A/R			
MOC :									
SB PW500-72-30156 R01 E1	REPLACEMENT OF ANTI-ICING VALVE CATEGORY 7					-			
MOC :									
SB PW500-72-30156 R01 E2	REPLACEMENT OF ANTI-ICING VALVE CATEGORY 7					-			
MOC :									
SB PW500-72-30158 R01 E1	REPLACEMENT OF HIGH PRESSURE COMPRESSOR SHAFT CATEGORY 7					-			
MOC :									
SB PW500-72-30158 R01 E2	REPLACEMENT OF HIGH PRESSURE COMPRESSOR SHAFT CATEGORY 7					-			
MOC :									
SB PW500-72-30176 R02 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY CATEGORY 7					-			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30176 R02 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30202 R01 E1	INTRODUCTION OF RE-PROFILED GRAFOIL GASKETS (SUPRESEDED BY PW500-72-30202 R02)			CATEGORY 5			-			
MOC :										
SB PW500-72-30202 R01 E2	INTRODUCTION OF RE-PROFILED GRAFOIL GASKETS (SUPRESEDED BY PW500-72-30202 R02)			CATEGORY 5			-			
MOC :										
SB PW500-72-30202 R02 E1	INTRODUCTION OF RE-PROFILED GRAFOIL GASKETS			CATEGORY 5			-			
MOC :										
SB PW500-72-30202 R02 E2	INTRODUCTION OF RE-PROFILED GRAFOIL GASKETS			CATEGORY 5			-			
MOC :										
SB PW500-72-30207 R01 E1	REPLACEMENT OF FUEL NOZZLES			CATEGORY 7			-			
MOC :										
SB PW500-72-30207 R01 E2	REPLACEMENT OF FUEL NOZZLES			CATEGORY 7			-			
MOC :										
SB PW500-72-30217 R03 E1	INSPECTION OF FUEL TUBE KARR			CATEGORY 3	MTH 24-Aug-2018 HRS 6427.7 LDG 5061		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB PW500-72-30217- R03 - NO. 1 ENGINE - INSPECTION OF THE FUEL TUBE, SERVICE BULLETIN. NO DEFECTS NOTED.										
SB PW500-72-30217 R03 E2	INSPECTION OF FUEL TUBE KARR			CATEGORY 3	MTH 24-Aug-2018 HRS 6427.7 LDG 5061		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB PW500-72-30217- R03 - NO. 2 ENGINE - INSPECTION OF THE FUEL TUBE, SERVICE BULLETIN. NO DEFECTS NOTED.										
SB PW500-72-30261 R03 E1	INTRODUCTION OF FUEL PRESSURE TUBE REPLACEMENT AND ATTENUATOR KARR			CATEGORY 3	MTH 29-Aug-2019 HRS 6763.8 LDG 5296		-			Complete
MOC : COMPLIED WITH - INSPECTED NO. 1 ENGINE PER PW500-72-30261 R03. FOUND P&WC SB. NO. 30261 PREVIOUSLY COMPLIED WITH. UPDATED RECORDS WITH REVISED SB. NO ISSUES NOTED.										
SB PW500-72-30261 R03 E2	INTRODUCTION OF FUEL PRESSURE TUBE REPLACEMENT AND ATTENUATOR KARR			CATEGORY 3	MTH 29-Aug-2019 HRS 6763.8 LDG 5296		-			Complete
MOC : COMPLIED WITH - INSPECTED NO. 2 ENGINE PER PW500-72-30261 R03. FOUND P&WC SB. NO. 30261 PREVIOUSLY COMPLIED WITH. UPDATED RECORDS WITH REVISED SB. NO ISSUES NOTED.										
SB PW500-72-30263 R01 E1	REPLACEMENT OF MODEL APPLICATION STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL (SUPERSEDED BY PW500-72-30263 R02)			CATEGORY 8			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30263 R01 E2	REPLACEMENT OF MODEL APPLICATION STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL (SUPERSEDED BY PW500-72-30263 R02)			CATEGORY 8			-			
	MOC :									
SB PW500-72-30263 R02 E1	REPLACEMENT OF STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL			CATEGORY 8			-			
	MOC :									
SB PW500-72-30263 R02 E2	REPLACEMENT OF STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL			CATEGORY 8			-			
	MOC :									
SB PW500-72-30269 R01 E1	REPLACEMENT OF GAS GENERATOR DIFFUSER SET AND NO. 4 BEARING			CATEGORY 7			-			
	MOC :									
SB PW500-72-30269 R01 E2	REPLACEMENT OF GAS GENERATOR DIFFUSER SET AND NO. 4 BEARING			CATEGORY 7			-			
	MOC :									
SB PW500-72-30282 R01 E1	REPLACEMENT OF FUEL NOZZLE PREFORMED PACKINGS			CATEGORY 6			-			
	MOC :									
SB PW500-72-30282 R01 E2	REPLACEMENT OF FUEL NOZZLE PREFORMED PACKINGS			CATEGORY 6			-			
	MOC :									
SB PW500-72-30309 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30309 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30325 R02 E1	REPLACEMENT OF OIL-PUMP PLAIN SEAL (SUPERSEDED BY PW500-72-30325 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30325 R02 E2	REPLACEMENT OF OIL-PUMP PLAIN SEAL (SUPERSEDED BY PW500-72-30325 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30325 R03 E1	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30325 R03 E2	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6			-			
	MOC :									
SB PW500-72-30336 R01 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30336 R01 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 7			-			
MOC :										
SB PW500-72-30343 R06 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			-			
MOC :										
SB PW500-72-30343 R06 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			-			
MOC :										
SB PW500-72-30344 R01 E1	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS			CATEGORY 7			-			
MOC :										
SB PW500-72-30344 R01 E2	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS			CATEGORY 7			-			
MOC :										
SB PW500-72-30346 R01 E1	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30346 R01 E2	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30351 R02 E1	INTRODUCTION OF TURBINE EXHAUST CASE REINFORCEMENT RING			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30351 R02 E2	INTRODUCTION OF TURBINE EXHAUST CASE REINFORCEMENT RING			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30372 R02 E1	REVERT TO FUEL NOZZLES OF A PRIOR CONFIGURATION (SUPERSEDED BY PW500-72-30372 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30372 R02 E2	REVERT TO FUEL NOZZLES OF A PRIOR CONFIGURATION (SUPERSEDED BY PW500-72-30372 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30372 R03 E1	REVERT TO FUEL NOZZLES OF A PRIOR CONFIGURATION			CATEGORY 6			-			
MOC :										
SB PW500-72-30372 R03 E2	REVERT TO FUEL NOZZLES OF A PRIOR CONFIGURATION			CATEGORY 6			-			
MOC :										
SB PW500-72-30376 R01 E1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR (SUPERSEDED BY PW500-72-30376 R02)			CATEGORY 7			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30376 R01 E2	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR (SUPERSEDED BY PW500-72-30376 R02)			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30376 R02 E1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			-			
MOC :										
SB PW500-72-30376 R02 E2	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			-			
MOC :										
SB PW500-72-30381 R02 E1	REPLACEMENT OF FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING	KLYH		CATEGORY 3	MTH 21-Oct-2011 HRS 4052.4 LDG 3204		-			Complete
MOC : COMPLIED WITH - PRATT & WHITNEY SERVICE BULLETIN PW500-72-30381R2 ON LH ENGINE, S/N: PCE-DA0101, WAS ACCOMPLISHED AT ENGINE OVERHAUL BY PRATT & WHITNEY, CRS# LM1R301K, UNDER SALESORDER NO. 169907.										
SB PW500-72-30381 R02 E2	REPLACEMENT OF FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING	KLYH		CATEGORY 3	MTH 21-Oct-2011 HRS 4052.4 LDG 3204		-			Complete
MOC : COMPLIED WITH - PRATT & WHITNEY SERVICE BULLETIN PW500-72-30381R2 ON RH ENGINE, S/N: PCE-DA0107, WAS ACCOMPLISHED AT ENGINE OVERHAUL BY PRATT & WHITNEY, CRS# LM1R301K, UNDER SALESORDER NO. 169918.										
SB PW500-72-30387 R02 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY(SUPERSEDED BY PW500-72-30387 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R02 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY(SUPERSEDED BY PW500-72-30387 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R03 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R04)			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R03 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R04)			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R04 E1	REPLACEMENT / MODIFICATION OF REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R05)			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R04 E2	REPLACEMENT / MODIFICATION OF REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R05)			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R05 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R06)			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R05 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R06)			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30387 R06 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30387 R06 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30395 E1	REPLACEMENT OF BOLTS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30395 E2	REPLACEMENT OF BOLTS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30400 R02 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R03)			RECOMMENDED			A/R			
	MOC :									
SB PW500-72-30400 R02 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R03)			RECOMMENDED			A/R			
	MOC :									
SB PW500-72-30400 R03 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30400 R03 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30400 R04 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
	MOC :									
SB PW500-72-30400 R04 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
	MOC :									
SB PW500-72-30403 R02 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES (SUPERSEDED BY PW500-72-30403 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30403 R02 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES (SUPERSEDED BY PW500-72-30403 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30403 R03 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
	MOC :									
SB PW500-72-30403 R03 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30403 R04 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
	MOC :									
SB PW500-72-30403 R04 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
	MOC :									
SB PW500-72-30405 R02 E1	REPLACEMENT OF FUEL NOZZLE MANIFOLD (SUPERSEDED BY PW500-72-30405 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30405 R02 E2	REPLACEMENT OF FUEL NOZZLE MANIFOLD (SUPERSEDED BY PW500-72-30405 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30405 R04 E1	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
	MOC :									
SB PW500-72-30405 R04 E2	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
	MOC :									
SB PW500-72-30405 R3 E1	REPLACEMENT OF - FUEL NOZZLE MANIFOLD			RECOMMENDED			-			
	MOC :									
SB PW500-72-30405 R3 E2	REPLACEMENT OF - FUEL NOZZLE MANIFOLD			RECOMMENDED			-			
	MOC :									
SB PW500-72-30409 R08 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R09)			CATEGORY 3			-			
	MOC :									
SB PW500-72-30409 R08 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R09)			CATEGORY 3			-			
	MOC :									
SB PW500-72-30409 R09 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R10)			CATEGORY 3			-			
	MOC :									
SB PW500-72-30409 R09 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R10)			CATEGORY 3			-			
	MOC :									
SB PW500-72-30409 R10 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	UNK		CATEGORY 3	MTH 24-Nov-2015		-			N/A
	MOC :									
SB PW500-72-30409 R10 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	UNK		CATEGORY 3	MTH 24-Nov-2015		-			N/A
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30415 R01 E1	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R02)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R01 E2	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R02)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R02 E1	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R02 E2	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R03 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 R03 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	MOC :									
SB PW500-72-30415 E1	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R01)			RECOMMENDED			A/R			
	MOC :									
SB PW500-72-30415 E2	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R01)			RECOMMENDED			A/R			
	MOC :									
SB PW500-72-30416 R01 E1	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 10			-			
	MOC :									
SB PW500-72-30416 R01 E2	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 10			-			
	MOC :									
SB PW500-72-30420 R03 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R04)			CATEGORY 3			-			
	MOC :									
SB PW500-72-30420 R03 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R04)			CATEGORY 3			-			
	MOC :									
SB PW500-72-30420 R04 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-3042 R05)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30420 R04 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-3042 R05)			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30420 R05 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
	MOC :									
SB PW500-72-30420 R05 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
	MOC :									
SB PW500-72-30423 R01 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30423 R01 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30423 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30423 R01)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30423 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30423 R01)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30428 R02 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R02 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R03 E1	REPLACEMENT OF - FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R03 E2	REPLACEMENT OF - FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R04 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R05)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R04 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R05)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R05 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R05 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R06 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30428 R06 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
MOC :										
SB PW500-72-30442 R01 E1	REPLACEMENT/MODIFICATION OF TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R02)			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30442 R01 E2	REPLACEMENT/MODIFICATION OF TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R02)			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30442 R02 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 R02 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 R03 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R04)			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 R03 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R04)			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 E1	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW500-72-30442 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30442 E2	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW500-72-30442 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30446 R01 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY (SUPERSEDED BY PW500-72-30446 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30446 R01 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY (SUPERSEDED BY PW500-72-30446 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30446 R02 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30446 R02 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30446 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY (SUPERSEDED BY PW500-72-30446 R01)						-			
MOC :										
SB PW500-72-30446 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY (SUPERSEDED BY PW500-72-30446 R01)						-			
MOC :										
SB PW500-72-30447 R01 E1	NEW COATING MODIFICATION OF GAS GENERATOR CASE			CATEGORY 6			-			
MOC :										
SB PW500-72-30447 R01 E2	NEW COATING MODIFICATION OF GAS GENERATOR CASE			CATEGORY 6			-			
MOC :										
SB PW500-72-30447 E1	NEW COATING MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY PW500-72-30447 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30447 E2	NEW COATING MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY PW500-72-30447 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30453 R01 E1	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30453 R01 E2	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30453 R02 E1	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30453 R02 E2	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30453 R03 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30453 R03 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30453 E1	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R01)			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30453 E2	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R01 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R01 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R02 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R02 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R03 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R04)			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R03 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R04)			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R05 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R05 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30455 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30465 R01 E1	REPLACEMENT OF FUEL MANIFOLD TUBES (SUPERSEDED BY PW500-72-30465 R02)			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30465 R01 E2	REPLACEMENT OF FUEL MANIFOLD TUBES (SUPERSEDED BY PW500-72-30465 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 R02 E1	REPLACEMENT OF FUEL MANIFOLD TUBES			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 R02 E2	REPLACEMENT OF FUEL MANIFOLD TUBES			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 E1	REPLACEMENT OF FUEL MANIFOLD TUBES (SUPERSEDED BY PW500-72-30465 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 E2	REPLACEMENT OF FUEL MANIFOLD TUBES (SUPERSEDED BY PW500-72-30465 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30471 E1	CONVERSION OF PW530A BUILD SPECIFICATION 1154 TO BUILD SPECIFICATION 862			CATEGORY 8			-			
	MOC :									
SB PW500-72-30471 E2	CONVERSION OF PW530A BUILD SPECIFICATION 1154 TO BUILD SPECIFICATION 862			CATEGORY 8			-			
	MOC :									
SB PW500-72-30472 R01 E1	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30472 R01 E2	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30472 E1	REPLACEMENT OF N1 AND N2 SPEED SENSORS (SUPERSEDED BY PW500-72-30472 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30472 E2	REPLACEMENT OF N1 AND N2 SPEED SENSORS (SUPERSEDED BY PW500-72-30472 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30476 E1	REPLACEMENT OF N2 SPEED SENSOR			CATEGORY 7			-			
	MOC :									
SB PW500-72-30476 E2	REPLACEMENT OF N2 SPEED SENSOR			CATEGORY 7			-			
	MOC :									
SB PW500-72-30485 R01 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE (SUPERSEDED BY PW500-72-30485 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30485 R01 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE (SUPERSEDED BY PW500-72-30485 R02)			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30485 R02 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
MOC :										
SB PW500-72-30485 R02 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
MOC :										
SB PW500-72-30490 E1	INSPECTION/REPLACEMENT OF FUEL PRESSURE TUBE INSTALLATION	UNK		CATEGORY 3	MTH 03-Apr-2014 HRS 4651 LDG 3664		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY, NOT INSTALLED										
SB PW500-72-30490 E2	INSPECTION/REPLACEMENT OF FUEL PRESSURE TUBE INSTALLATION	UNK		CATEGORY 3	MTH 03-Apr-2014 HRS 4651 LDG 3664		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY, NOT INSTALLED										
SB PW500-72-30493 E1	REPLACEMENT OF TEMPERATURE SENSORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30493 E2	REPLACEMENT OF TEMPERATURE SENSORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30500 E1	REPLACEMENT OF PREFORMED PACKING			CATEGORY 7			-			
MOC :										
SB PW500-72-30500 E2	REPLACEMENT OF PREFORMED PACKING			CATEGORY 7			-			
MOC :										
SB PW500-72-30501 E1	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS			CATEGORY 3			-			
MOC :										
SB PW500-72-30501 E2	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS			CATEGORY 3			-			
MOC :										
SB PW500-72-30504 R01 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30504 R01 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30504 R02 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
MOC :										
SB PW500-72-30504 R02 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30504 R03 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
MOC :										
SB PW500-72-30504 R03 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
MOC :										
SB PW500-72-30504 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30504 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30505 R01 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R02)	UNK		CATEGORY 3	MTH 30-Apr-2015 HRS 5191.8 LDG 4087		-			Complete
MOC : COMPLIED WITH - ENGINE TIME: 5134.9, CYLES: 4023, COMPLIED WITH CAMP CARD SB PW500-72-30505 R1 P&WC S B. NO 30505 NO.1 ENGINE REPLACEMENT OF BLEED OFF VALVE GASKETS REPLACED TWO GASKET (P/N 30J3779-01 AND 30J3780) AND FIVE NUTS (P/N ST3032-09).										
SB PW500-72-30505 R01 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R02)	UNK		CATEGORY 3	MTH 30-Apr-2015 HRS 5191.8 LDG 4087		-			Complete
MOC : COMPLIED WITH - ENGINE TIME: 5134.9, CYLES: 4023, COMPLIED WITH CAMP CARD SB PW500-72-30505 R1 P&WC S B. NO 30505 NO.2 ENGINE REPLACEMENT OF BLEED OFF VALVE GASKETS REPLACED TWO GASKET (P/N 30J3779-01 AND 30J3780) AND FIVE NUTS (P/N ST3032-09).										
SB PW500-72-30505 R02 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3			-			
MOC :										
SB PW500-72-30505 R02 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3			-			
MOC :										
SB PW500-72-30506 R01 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30506 R01 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30506 R02 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
MOC :										
SB PW500-72-30506 R02 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
MOC :										
SB PW500-72-30506 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R01)			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30506 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30511 R01 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 R01 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS (SUPERSEDED BY PW500-72-30511 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS (SUPERSEDED BY PW500-72-30511 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30512 R02 E1	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R03)	UNK		CATEGORY 3	MTH 06-Jul-2015 HRS 5252.8 LDG 4135		-			Complete
MOC : COMPLIED WITH - REMOVED FUEL CONTROL P/N:101263-10,S/N:F43915.INSTALLED OVERHAULED P/N:1012632-18,S/N:F50342 FROM HAMILTON SUNSTRAND CRS#SI3R842L REFERENCE 8130-3 DATED MAY 12,2015 WORK DONE IN ACCORDANCE WITH SB PW500-72-30512 R2.										
SB PW500-72-30512 R02 E2	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R03)	UNK		CATEGORY 3	MTH 06-Jul-2015 HRS 5252.8 LDG 4135		-			Complete
MOC : COMPLIED WITH - REMOVED FUEL CONTROL P/N:1012632-2,S/N:F40029.INSTALLED OVERHAULED P/N:1012632-18,S/N:F57756 FROM HAMILTON SUNSTRAND CRS#SI3R842L REFERENCE 8130-3 DATED MAY 12,2015 WORK DONE IN ACCORDANCE WITH SB PW500-72-30512 R2.										
SB PW500-72-30512 R03 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 3	MTH		-			
MOC :										
SB PW500-72-30512 R03 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 3	MTH		-			
MOC :										
SB PW500-72-30516 R01 E1	REPLACEMENT OF HP TURBINE SEAL RINGS (SUPERSEDED BY PW500-72-30516 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30516 R01 E2	REPLACEMENT OF HP TURBINE SEAL RINGS (SUPERSEDED BY PW500-72-30516 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30516 R02 E1	REPLACEMENT OF HP TURBINE SEAL RINGS			CATEGORY 7			-			
MOC :										
SB PW500-72-30516 R02 E2	REPLACEMENT OF HP TURBINE SEAL RINGS			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30517 R01 E1	DELETION OF IGNITER FLANGE GASKETS			CATEGORY 6			-			
MOC :										
SB PW500-72-30517 R01 E2	DELETION OF IGNITER FLANGE GASKETS			CATEGORY 6			-			
MOC :										
SB PW500-72-30517 E1	DELETION OF IGNITER FLANGE GASKETS (SUPERSEDED BY PW500-72-30517 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30517 E2	DELETION OF IGNITER FLANGE GASKETS (SUPERSEDED BY PW500-72-30517 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30522 R01 E1	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30522 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30522 R01 E2	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30522 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30522 R02 E1	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY SB PW500-72-30529 R01)			CATEGORY 10			-			
MOC :										
SB PW500-72-30522 R02 E2	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY SB PW500-72-30529 R01)			CATEGORY 10			-			
MOC :										
SB PW500-72-30522 E1	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30522 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30522 E2	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30522 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30527 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
MOC :										
SB PW500-72-30527 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
MOC :										
SB PW500-72-30529 R01 E1	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30529 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30529 R01 E2	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30529 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30529 R02 E1	REPLACEMENT OF IGNITER CABLES			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30529 R02 E2	REPLACEMENT OF IGNITER CABLES			CATEGORY 7			-			
	MOC :									
SB PW500-72-30529 E1	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30529 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30529 E2	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30529 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30533 R01 E1	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30533 R01 E2	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30533 E1	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30533 E2	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30535 R01 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30535 R01 E2	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30535 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER (SUPERSEDED BY PW500-72-30535 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30535 E2	REPLACEMENT OF ENGINE SHIPPING CONTAINER (SUPERSEDED BY PW500-72-30535 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30543 R01 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30543 R01 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30545 R01 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT						-			
	MOC :									
SB PW500-72-30545 R01 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT						-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30545 R02 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 6			-			
MOC :										
SB PW500-72-30545 R02 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3			-			
MOC :										
SB PW500-72-30545 R03 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT						-			
MOC :										
SB PW500-72-30545 R03 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT						-			
MOC :										
SB PW500-72-30545 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3			-			
MOC :										
SB PW500-72-30545 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3			-			
MOC :										
SB PW500-72-30545 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3			-			
MOC :										
SB PW500-72-30545 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3			-			
MOC :										
SB PW500-72-30548 R01 E1	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7			-			
MOC :										
SB PW500-72-30548 R01 E2	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7			-			
MOC :										
SB PW500-72-30548 R02 E1	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7			-			
MOC :										
SB PW500-72-30548 R02 E2	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7			-			
MOC :										
SB PW500-72-30548 E1	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7			-			
MOC :										
SB PW500-72-30548 E2	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7			-			
MOC :										
ASB PW500-72-A30421 R02 E1	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE			CATEGORY 3			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASB PW500-72- A30421 R02 E2	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE			CATEGORY 3			-			
MOC :										
SB 550-73-05 73SB-05 : 550	ENGINE HYDRAULIC LINE CLAMP INSTALLATION	MCO		RECOMMENDED	MTH 09-Mar-2004 HRS 1646		-			Complete
MOC : COMPLIED WITH										
SL 550-73-02 73SL-02 : 550	TRANSMITTAL OF P&WC SB PW500-72-A30108, REV. 2, TURBOFAN ENGINE DECAL TEST	GSO		RECOMMENDED	MTH 09-Dec-1999 HRS 701		-			Complete
MOC : COMPLIED WITH										
SL 550-73-03 73SL-03 : 550	TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-30122 REPLACEMENT OF TURBOFAN ENGINE FUEL TUBE	ICT		RECOMMENDED	MTH 17-Jun-2000 HRS 928		-			Complete
MOC : COMPLIED WITH										
SL 550-73-04 73SL-04 : 550	TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN 30249 TURBOFAN ENGINE FUEL MANIFOLD - INSPECTION/REPLACEMENT OF AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) A03008	MCO		RECOMMENDED	MTH 09-Mar-2004 HRS 1646		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.										
SL 550-73-07 73SL-07 : 550	ENGINE FUEL AND CONTROL - TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN 30307 TURBOFAN ENGINE HFC UNIT RATIO SETSCREW ADJUSTMENT AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) 1001503	GSO		MANDATORY	MTH 11-Jan-2007 HRS 2460		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.										
SL 550-73-08 LEFT ENGINE 73SL-08 : E1**L	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30381R2, FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE/FAIRING/REPLACEMENT OF	KLYH		RECOMMENDED	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		12 300			Complete
MOC : COMPLIED WITH - CESSNA SL550-73-08 WAS ACCOMPLISHED IN ACCORDANCE WITH PRATT & WHITNEY SERVICE BULLETIN PW500-72-30381R2 ON LH ENGINE, S/N: PCE-DA0101, AT ENGINE OVERHAUL BY PRATT & WHITNEY, CRS# LM1R301K, UNDER SALES ORDER NO. 169907.										
SL 550-73-08 RIGHT ENGINE 73SL-08 : E2**R	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30381R2, FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE/FAIRING/REPLACEMENT OF	KLYH		RECOMMENDED	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		12 300			Complete
MOC : COMPLIED WITH - CESSNA SL550-73-08 WAS ACCOMPLISHED IN ACCORDANCE WITH PRATT & WHITNEY SERVICE BULLETIN PW500-72-30381R2 ON RH ENGINE, S/N: PCE-DA0107, AT ENGINE OVERHAUL BY PRATT & WHITNEY, CRS# LM1R301K, UNDER SALES ORDER NO. 169918.										
SB PW500-72- 30390 R05 E1	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R08)			CATEGORY 10			-			
MOC :										
SB PW500-72- 30390 R05 E2	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R08)			CATEGORY 10			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30409 R06 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R07)	KLYH	CATEGORY 3	MTH 21-Oct-2011 HRS 4052.4 LDG 3204		-			Complete
MOC : COMPLIED WITH - P&W SERVICE BULLETIN PW500-72-30409R6 WAS ACCOMPLISHED AT OVERHAUL ON LH ENGINE S/N: PCE-DA0101 BY PRATT & WHITNEY, CRS# LM1R301K, UNDER SALES ORDER 169907.									
SB PW500-72-30409 R06 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R07)	KLYH	CATEGORY 3	MTH 21-Oct-2011 HRS 4052.4 LDG 3204		-			N/A
MOC : NOT APPLICABLE - AN OVERHAULLED RH FCU, S/N: F40029, WAS INSTALLED ON 03/12/09 ON RH ENGINE S/N: PCE-DA0107 AND IS POST SERVICE BULLETIN 30390. P&W SERVICE BULLETIN PW500-72-30409R6 NOTAPPLICABLE, NO FURTHER ACTION REQUIRED.									
SB 550-74-02 74SB-02 : 550	RF FILTER REMOVAL	GSO	RECOMMENDED	MTH 27-Mar-2001 HRS 1163		-			Complete
MOC : COMPLIED WITH									
SB PW500-72-30266 R01 E1	REPLACEMENT/MODIFICATION OF IGNITION EXCITER		CATEGORY 7				A/R		
MOC :									
SB PW500-72-30266 R01 E2	REPLACEMENT/MODIFICATION OF IGNITION EXCITER		CATEGORY 7				A/R		
MOC :									
SB PW500-72-30343 R05 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE (SUPERSEDED BY PW500-72-30343 R06)		CATEGORY 7				A/R		
MOC :									
SB PW500-72-30343 R05 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE (SUPERSEDED BY PW500-72-30343 R06)		CATEGORY 7				A/R		
MOC :									
SB PW500-72-30420 R02 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R03)	KLYH	CATEGORY 3	MTH 21-Oct-2011 HRS 4052.4 LDG 3204		-			Complete
MOC : COMPLIED WITH - PRATT & WHITNEY SERVICE BULLETIN PW500-72-30420R2 WAS ACCOMPLISHED ON LH ENGINE, S/N: PCE-DA0101, AT ENGINE OVERHAUL BY PRATT & WHITNEY, CRS# LM1R301K, UNDER SALESORDER NO. 169907.									
SB PW500-72-30420 R02 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R03)	KLYH	CATEGORY 3	MTH 21-Oct-2011 HRS 4052.4 LDG 3204		-			Complete
MOC : COMPLIED WITH - PRATT & WHITNEY SERVICE BULLETIN PW500-72-30420R2 WAS ACCOMPLISHED ON RH ENGINE, S/N: PCE-DA0107, AT ENGINE OVERHAUL BY PRATT & WHITNEY, CRS# LM1R301K, UNDER SALESORDER NO. 169918.									
ASB PW500-72-A30421 R01 E1	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R02)	KLYH	CATEGORY 3	MTH 21-Oct-2011 HRS 4052.4 LDG 3204		-			N/A
MOC : NOT APPLICABLE - PRATT & WHITNEY SERVICE BULLETIN PW500-72-30421R1 NOT APPLICABLE DUE TO MOD STATUS OF LH ENGINE, S/N: PCE-DA0101.									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASB PW500-72-A30421 R01 E2	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R02)	KLYH		CATEGORY 3	MTH 21-Oct-2011 HRS 4052.4 LDG 3204		-			N/A
MOC : NOT APPLICABLE - PRATT & WHITNEY SERVICE BULLETIN PW500-72-30421R1 NOT APPLICABLE DUE TO MOD STATUS OF RH ENGINE, S/N: PCE-DA0107.										
ASB PW500-72-A30421 E1	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R01)	LYH		CATEGORY 3	MTH 09-Sep-2010 HRS 3845.8 LDG 2996		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2010-18-09 PREVENT LOSS OF POWER. FOUND THAT AD DOES NOT APPLY DUE TO THE P/N: 31J2857-03 SERVO VALVE PERFORMED IAW PRATT AND WHITNEY SB A30421, SB 30343R4 AND SB 30404R1. AD 2010-18-09 IS TERMINATED DUE TO THE CONFIGURATION AND NO FURTHER ACTION REQUIRED AT THIS TIME AND DATE.										
ASB PW500-72-A30421 E2	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R01)	LYH		CATEGORY 3	MTH 09-Sep-2010 HRS 3845.8 LDG 2996		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2010-18-09 PREVENT LOSS OF POWER. FOUND THAT AD DOES NOT APPLY DUE TO THE P/N: 31J2857-03 SERVO VALVE PERFORMED IAW PRATT AND WHITNEY SB A30421, SB 30343R4 AND SB 30404R1. AD 2010-18-09 IS TERMINATED DUE TO THE CONFIGURATION AND NO FURTHER ACTION REQUIRED AT THIS TIME AND DATE.										
SB 550-76-05 R01 76SB-05 : 550R1	THRUST REVERSER MAXIMUM THRUST SETTING	GSO		RECOMMENDED	MTH 03-Nov-2006 HRS 2429		-			Complete
MOC : COMPLIED WITH										
SL 550-76-04 76SL-04 : 550	ENGINE THROTTLE FRICTION BLOCK INSPECTION	GSO		MANDATORY	MTH 02-Jun-1999 HRS 393			A/R		Complete
MOC : COMPLIED WITH										
SB 550-78-04 78SB-04 : 550	THRUST REVERSER THROTTLE STOP SOLENOID GROUND IMPROVEMENT			OPTIONAL	MTH		-			
MOC :										
SL 550-78-10 78SL-10 : 550	TRANSMITTAL OF THE NORDAM GROUP SB CIT BY 78-1 EXHAUST - THRUST REVERSER - LOWER DOOR - ADDITION OF DRAIN HOLE	GSO		RECOMMENDED	MTH 05-Sep-1999 HRS 562		-			Complete
MOC : COMPLIED WITH										
SB 550-80-05 80SB-05 : 550	STARTER GENERATOR POWER CABLE SLEEVING INSTALLATION	MCO		MANDATORY	MTH 09-Mar-2004 HRS 1646		-			Complete
MOC : COMPLIED WITH										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1995-22-01 33AD-04 : 550	APPLIANCE AD - AEROSPACE LIGHTING POWER UNIT	ICT	MANDATORY	MTH 28-Sep-1998 HRS 11		A/R			Complete
MOC : COMPLIED WITH									
FAA 1998-25-10 25AD-11 : 550	APPLIANCE AD - AIRCRAFT BELTS, INC.	ICT	MANDATORY	MTH 03-Mar-1999 HRS 272		A/R			Complete
MOC : COMPLIED WITH									
FAA 1999-08-21 35AD-07 : 550	APPLIANCE AD - PURITAN-BENNETT AERO SYSTEM C	GSO	MANDATORY	MTH 22-Jun-1999 HRS 451		A/R			Complete
MOC : COMPLIED WITH									
FAA 2001-23-17 34AD-26 : 550	APPLIANCE AD - GARMIN INTERNATIONAL GNS 430	ICT	MANDATORY	MTH 11-Apr-2002 HRS 1271		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2004-08-15 34AD-14 : 550	APPLIANCE AD - TAWS 8000 TERRAIN AWARENESS	GSO	MANDATORY	MTH 03-Oct-2004 HRS 1885		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2006-04-10 26AD-06 : 550	INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPLICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS.	GSO	MANDATORY	MTH 12-Apr-2006 HRS 2324		A/R			Complete
MOC : COMPLIED WITH									
FAA 2006-16-18 PARA(H) 34AD-29 : 550	UPDATE SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR(TAWS/RMI) SOFTWARE	GSO	MANDATORY	MTH 11-Jan-2007 HRS 2460		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE									
FAA 2006-16-18 34AD-29 : 550	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI)	GSO	MANDATORY	MTH 11-Jan-2007 HRS 2460		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE									
FAA 2006-19-04 34AD-32 : 550	APPLIANCE AD - HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS	GSO	MANDATORY	MTH 11-Jan-2007 HRS 2460		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE									
FAA 1998-04-38 30AD-01 : 550	AFM-LIMITATIONS SECTION-ICING		MANDATORY	MTH 02-Dec-1998 HRS 138		-			Complete
MOC : COMPLIED WITH									
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)	KLYH	MANDATORY	DAYS 18-Jun-2013 HRS 4504.7 LDG 3569		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2013-09-11 (G), INSPECTED AIRCRAFT A/C COMPRESSOR MOTOR AND FOUND P/N: 1134104-1, S/N: 937 INSTALLED.									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS	KLYH	MANDATORY	DAYS 18-Jun-2013 HRS 4504.7 LDG 3569		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2013-09-11 (H) (I) & (J), A/C COMPRESSOR MOTOR BRUSHES WERE CHANGED ON 01/16/2013 AT A/C HOBBS METER READING: 845.7, NEXT DUE AT A/C HOBBS METER READING: 1345.7.									
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION	KLYH	MANDATORY	MTH 18-Jun-2013 HRS 4504.7 LDG 3569 ACH 845.7			500	1345.7	Complete 215.7
MOC : COMPLIED WITH - COMPLIED WITH AD 2013-09-11 (H) (I) & (J), A/C COMPRESSOR MOTOR BRUSHES WERE CHANGED ON 01/16/2013 AT A/C HOBBS METER READING: 845.7, NEXT DUE AT A/C HOBBS METER READING: 1345.7.									
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM		MANDATORY			A/R			
MOC :									
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM		MANDATORY			A/R			
MOC :									
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS		MANDATORY	DAYS		30			
MOC :									
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM	KLYH	MANDATORY	MTH 18-Jun-2013 HRS 4504.7 LDG 3569		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2013-09-11 (G), INSPECTED AIRCRAFT A/C COMPRESSOR MOTOR AND FOUND P/N: 1134104-1, S/N: 937 INSTALLED.									
FAA 2015-17-12 PARA (G)	INSPECT THE A/C COMPRESSOR MOTOR TO DETERMINE WHETHER P/N FWA1134104-1 OR P/N FWA1134104-5 IS INSTALLED	UNK	MANDATORY	DAYS 29-Sep-2015 HRS 5339.8 LDG 4204		-			N/A
MOC : NOT APPLICABLE - AD2015-17-12 DOES NOT APPLY TO INSTALLED AIR CONDITIONING COMPRESSOR MOTOR PART NUMBER.									
FAA 2015-17-12 PARA (H)	DETERMINE THE HOUR READING ON THE A/C COMPRESSOR HOUR METER (IF, DURING THE INSPECTION REQUIRED BY PARA (G) OF THIS AD, ANY A/C COMPRESSOR MOTOR HAVING P/N FWA1134104-1 OR P/N FWA1134104-5 IS FOUND)	UNK	MANDATORY	DAYS 29-Sep-2015 HRS 5339.8 LDG 4204		-			N/A
MOC : NOT APPLICABLE - AD2015-17-12 DOES NOT APPLY TO INSTALLED AIR CONDITIONING COMPRESSOR MOTOR PART NUMBER.									
FAA 2015-17-12 PARA (I)	REPLACE THE A/C COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES (USING THE HOUR READING ON THE A/C COMPRESSOR HOUR METER DETERMINED IN PARA (H) OF THIS AD)	UNK	MANDATORY	MTH 29-Sep-2015 HRS 5339.8 LDG 4204		-			N/A
MOC : NOT APPLICABLE - AD2015-17-12 DOES NOT APPLY TO INSTALLED AIR CONDITIONING COMPRESSOR MOTOR PART NUMBER.									
FAA 2015-17-12 PARA (K)	DEACTIVATE THE A/C SYSTEM (IN LIEU OF REPLACING THE A/C COMPRESSOR MOTOR BRUSHES AS REQUIRED BY THIS AD)		MANDATORY			-			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-17-12 PARA (L)	IF THE A/C SYSTEM IS DEACTIVATED, AS SPECIFIED IN PARA (K), PRIOR TO THE A/C SYSTEM BEING REACTIVATED: PERFORM THE INSPECTION SPECIFIED IN PARA (H), AND DO THE REPLACEMENTS SPECIFIED IN PARA (I), AT THE TIMES SPECIFIED IN PARA (I). RETURN THE A/C SYSTEM TO SERVICE								
			MANDATORY			-			
	MOC :								
FAA 2015-17-12 PARA (M)	SEND THE REMOVED BRUSHES TO CESSNA AIRCRAFT COMPANY								
	UNK		MANDATORY	DAYS 29-Sep-2015		-			N/A
				HRS 5339.8					
				LDG 4204					
	MOC : NOT APPLICABLE - AD2015-17-12 DOES NOT APPLY TO INSTALLED AIR CONDITIONING COMPRESSOR MOTOR PART NUMBER.								
FAA 2015-17-12	AIR CONDITIONING - INSPECTIONS TO DETERMINE IF CERTAIN A/C COMPRESSOR MOTORS ARE INSTALLED AND TO DETERMINE THE ACCUMULATED HOURS ON CERTAIN A/C COMPRESSOR MOTOR ASSEMBLIES; AND REPETITIVE REPLACEMENT OF THE BRUSHES IN THE A/C COMPRESSOR MOTOR ASSEMBLY, OR, AS AN OPTION TO THE BRUSH REPLACEMENT, DEACTIVATION OF THE A/C SYSTEM AND PLACARD INSTALLATION; AND RETURN OF REPLACED BRUSHES TO CESSNA								
	UNK		MANDATORY	MTH 29-Sep-2015		-			N/A
				HRS 5339.8					
				LDG 4204					
	MOC : NOT APPLICABLE - AD2015-17-12 DOES NOT APPLY TO INSTALLED AIR CONDITIONING COMPRESSOR MOTOR PART NUMBER.								
FAA 1974-08-09 R02 053801	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R3)								
	LYH		MANDATORY	MTH 23-Sep-2008		-			Complete
				HRS 3322					
	MOC : COMPLIED WITH								
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION								
	KARR		MANDATORY	MTH 14-Feb-2018					Complete
				HRS 6219.7		1000		7219.7	439.6
				LDG 4895					
	MOC : COMPLIED WITH - COMPLIED WITH RECURRING AD 1974-08-09 R3 LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION AND INSPECTED PLACARDS REQUIRED IN PAR (G)(1) AND (G)(2). NEXT DUE IN 1000 HOURS.								
FAA 1974-08-09 11AD-01 : 550	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R3)								
	GSO		SUPERSEDED	MTH 27-Mar-2001		A/R			Complete
				HRS 1163					
	MOC : COMPLIED WITH								
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2								
	UNK		MANDATORY	MTH 21-Jul-2015		-			N/A
				HRS 5271.4					
				LDG 4149					
	MOC : NOT APPLICABLE - FOUND IT DOES NOT APPLY PER PART NUMBER OF THE SEATS								
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK								
	UNK		MANDATORY	MTH 21-Jul-2015		-			N/A
				HRS 5271.4					
				LDG 4149					
	MOC : NOT APPLICABLE - FOUND IT DOES NOT APPLY PER PART NUMBER OF THE SEATS								
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS								
	UNK		MANDATORY	MTH 21-Jul-2015		-			N/A
				HRS 5271.4					
				LDG 4149					
	MOC : NOT APPLICABLE - FOUND IT DOES NOT APPLY PER PART NUMBER OF THE SEATS								



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	UNK	MANDATORY	MTH 21-Jul-2015 HRS 5271.4 LDG 4149		-			N/A
MOC : NOT APPLICABLE - FOUND IT DOES NOT APPLY PER PART NUMBER OF THE SEATS									
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KARR		MTH 17-Oct-2017 HRS 6075.9 LDG 4777		-			N/A
MOC : NOT APPLICABLE - FAA AD 2017-16-01 DOES NOT APPLY BY PART NUMBER OF ELT INSTALLED. NO FURTHER ACTION REQUIRED.									
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT		MANDATORY			-			
MOC :									
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS		MANDATORY			-			
MOC :									
FAA 2007-11-17 26AD-07 : 550	IDENTIFY WIRES FOR ENGINE/APU FIRE EXTINGUISHING BOTTLES	LYH	MANDATORY	MTH 08-Aug-2007 HRS 2798		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE DUE TO INTENT ACCOMPLISHED DURING PREVIOUS ISSUE OF SB, SL, OR AD									
FAA 2010-01-03 26AD-10 : 550	APPLIANCE AD - IDENTIFY AND REMOVE FROM SERVICE ALL AFFECTED FIRE EXTINGUISHERS AND REPLACE WITH SERVICABLE UNITS	LYH	MANDATORY	MTH 10-Feb-2010 HRS 3629		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2010-04-16 PARA (G) 26AD-13 : 550	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT	LYH	MANDATORY	DAYS 11-Jun-2010 HRS 3718.8 LDG 2860		A/R			N/A
MOC : NOT APPLICABLE - AD 2010-04-16(G), EFF. DATE 03/08/2010, NOT APPLICABLE TO THIS AIRCRAFT DUE TO PART NUMBER OF PORTABLE FIRE EXTINGUISHERS INSTALLED. NO FURTHER ACTION REQUIRED.									
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI	LYH	MANDATORY	DAYS 11-Jun-2010 HRS 3718.8 LDG 2860		A/R			N/A
MOC : NOT APPLICABLE - AD 2010-04-16(G), EFF. DATE 03/08/2010, NOT APPLICABLE TO THIS AIRCRAFT DUE TO PART NUMBER OF PORTABLE FIRE EXTINGUISHERS INSTALLED. NO FURTHER ACTION REQUIRED.									
FAA 2006-06-03 28AD-02 : 550	WING FUEL BOOST PUMP WIRING	GSO	MANDATORY	MTH 03-Nov-2006 HRS 2429		A/R			Complete
MOC : COMPLIED WITH									
FAA 1997-05-03 34AD-21 : 550	APPLIANCE AD - ALLIEDSIGNAL AVIONICS, INC. MODELS GNS-XLS OR GNS-XL FLIGHT MANAGEMENT SYSTEMS	*CF	SUPERSEDED	MTH 28-Sep-1998		A/R			Complete
MOC : COMPLIED WITH									
FAA 1998-25-02 34AD-23 : 550	APPLIANCE AD - BFGOODRICH SKYWATCH SKY497	ICT	MANDATORY	MTH 01-Feb-1999 HRS 270		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2003-04-06 <i>34AD-27 : 550</i>	APPLIANCE AD - HNYWELL PRIMUS RNZ-850/851 NM		MANDATORY	MTH 18-Mar-2003 HRS 1495		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2003-13-08 <i>34AD-13 : 550</i>	APPLIANCE AD - TAWS 8000 TERRAIN AWARENESS	GSO	MANDATORY	MTH 18-Nov-2003 HRS 1586		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	UNK	MANDATORY	MTH 05-Mar-2015 HRS 5107.2 LDG 4019		-			N/A
MOC : NOT APPLICABLE - BFG SKYWATCH PN 805-10800-001SN SKY01900936									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION		MANDATORY	MTH		-			
MOC :									
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	UNK	MANDATORY	MTH 06-Jul-2015 HRS 5252.6 LDG 4133		-			N/A
MOC : NOT APPLICABLE - N/A BY MFG									
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS		MANDATORY			-			
MOC :									
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	UNK	MANDATORY	MTH 06-Jul-2015 HRS 5252.6 LDG 4133		-			N/A
MOC : NOT APPLICABLE - N/A BY MFG									
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	UNK	MANDATORY	MTH 06-Jul-2015 HRS 5252.6 LDG 4133		-			N/A
MOC : NOT APPLICABLE - N/A BY MFG									
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES		MANDATORY			-			
MOC :									
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	UNK	MANDATORY	DAYS 29-Jan-2016 HRS 5516.9 LDG 4326		-			N/A
MOC : NOT APPLICABLE - P/N AND S/N MASKS ARE NOT LISTED AS AFFECTED,N/A DUE TO INSTALLED MASKS P/N									
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	UNK	MANDATORY	DAYS 29-Jan-2016 HRS 5516.9 LDG 4326		-			N/A
MOC : NOT APPLICABLE - P/N AND S/N MASKS ARE NOT LISTED AS AFFECTED,N/A DUE TO INSTALLED MASKS P/N									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	UNK	MANDATORY	DAYS 29-Jan-2016 HRS 5516.9 LDG 4326		-			N/A
MOC : NOT APPLICABLE - P/N AND S/N MASKS ARE NOT LISTED AS AFFECTED,N/A DUE TO INSTALLED MASKS P/N									
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	UNK	MANDATORY	DAYS 29-Jan-2016 HRS 5516.9 LDG 4326		-			N/A
MOC : NOT APPLICABLE - P/N AND S/N MASKS ARE NOT LISTED AS AFFECTED,N/A DUE TO INSTALLED MASKS P/N									
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	UNK	MANDATORY	MTH 29-Jan-2016 HRS 5516.9 LDG 4326		-			N/A
MOC : NOT APPLICABLE - P/N AND S/N MASKS ARE NOT LISTED AS AFFECTED,N/A DUE TO INSTALLED MASKS P/N									
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	UNK	MANDATORY	MTH 29-Jan-2016 HRS 5516.9 LDG 4326		-			N/A
MOC : NOT APPLICABLE - P/N AND S/N MASKS ARE NOT LISTED AS AFFECTED,N/A DUE TO INSTALLED MASKS P/N									
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	UNK	MANDATORY	MTH 08-Jul-2016 HRS 5655.8 LDG 4448		-			N/A
MOC : NOT APPLICABLE - PBE POUCH NOT INSTALLED IN AIRCRAFT									
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12		MANDATORY			-			
MOC :									
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	UNK	MANDATORY	MTH 08-Jul-2016 HRS 5655.8 LDG 4448		-			N/A
MOC : NOT APPLICABLE - PBE POUCHES ARE NOT INSTALLED IN AIRCRAFT									
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12		MANDATORY			-			
MOC :									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED		MANDATORY			-			
MOC :									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED		MANDATORY			-			
MOC :									
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KARR	MANDATORY	MTH 17-Oct-2017 HRS 6075.9 LDG 4777		-			N/A
MOC : NOT APPLICABLE - FAA AD 2017-18-12 DOES NOT APPLY. PBE NOT INSTALLED IN AIRCRAFT. NO FURTHER ACTION REQUIRED.									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES		MANDATORY			-			
MOC :									
FAA 2010-18-09 PARA (E)(2) E1	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE	KLYH	MANDATORY	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		-			N/A
MOC : NOT APPLICABLE - AD 2010-18-09 (EFF. 09/10/2010) ON LH ENGINE, S/N: PCE-DA0101 NOT APPLICABLE DUE TIME IN SERVICE AND MOD STATUS OF THE INTERCOMPRESSOR BLEED VALVE (BOV) SERVO VALVE AS OF THEEFFECTIVE DATE OF THIS AD PER AD 2010-18-09 (E)(1). NO FURTHER ACTION REQUIRED.									
FAA 2010-18-09 PARA (E)(2) E2	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE	KLYH	MANDATORY	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		-			N/A
MOC : NOT APPLICABLE - AD 2010-18-09 (EFF. 09/10/2010) ON RH ENGINE, S/N: PCE-DA0107 NOT APPLICABLE DUE TIME IN SERVICE AND MOD STATUS OF THE INTERCOMPRESSOR BLEED VALVE (BOV) SERVO VALVE AS OF THEEFFECTIVE DATE OF THIS AD PER AD 2010-18-09 (E)(1). NO FURTHER ACTION REQUIRED.									
FAA 2010-18-09 PARA (E)(3) E1	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING	KLYH	MANDATORY	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		-			N/A
MOC : NOT APPLICABLE - AD 2010-18-09 (EFF. 09/10/2010) ON LH ENGINE, S/N: PCE-DA0101 NOT APPLICABLE DUE TIME IN SERVICE AND MOD STATUS OF THE INTERCOMPRESSOR BLEED VALVE (BOV) SERVO VALVE AS OF THEEFFECTIVE DATE OF THIS AD PER AD 2010-18-09 (E)(1). NO FURTHER ACTION REQUIRED.									
FAA 2010-18-09 PARA (E)(3) E2	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING	KLYH	MANDATORY	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		-			N/A
MOC : NOT APPLICABLE - AD 2010-18-09 (EFF. 09/10/2010) ON RH ENGINE, S/N: PCE-DA0107 NOT APPLICABLE DUE TIME IN SERVICE AND MOD STATUS OF THE INTERCOMPRESSOR BLEED VALVE (BOV) SERVO VALVE AS OF THEEFFECTIVE DATE OF THIS AD PER AD 2010-18-09 (E)(1). NO FURTHER ACTION REQUIRED.									
FAA 2010-18-09 E1	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE	KLYH	MANDATORY	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		-			N/A
MOC : NOT APPLICABLE - AD 2010-18-09 (EFF. 09/10/2010) ON LH ENGINE, S/N: PCE-DA0101 NOT APPLICABLE DUE TIME IN SERVICE AND MOD STATUS OF THE INTERCOMPRESSOR BLEED VALVE (BOV) SERVO VALVE AS OF THEEFFECTIVE DATE OF THIS AD PER AD 2010-18-09 (E)(1). NO FURTHER ACTION REQUIRED.									
FAA 2010-18-09 E2	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE	KLYH	MANDATORY	MTH 21-Oct-2011 HRS 4051.7 LDG 3200		-			N/A
MOC : NOT APPLICABLE - AD 2010-18-09 (EFF. 09/10/2010) ON RH ENGINE, S/N: PCE-DA0107 NOT APPLICABLE DUE TIME IN SERVICE AND MOD STATUS OF THE INTERCOMPRESSOR BLEED VALVE (BOV) SERVO VALVE AS OF THEEFFECTIVE DATE OF THIS AD PER AD 2010-18-09 (E)(1). NO FURTHER ACTION REQUIRED.									
FAA 2003-03-21 E1	ENGINE FUEL AND CONTROL - ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP	HEF		MTH 31-Mar-2003 HRS 1559.9		-			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 2003-03-21 E2	ENGINE FUEL AND CONTROL - ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP									
		HEF			MTH 31-Mar-2003 HRS 1559.9		-			Complete

MOC : COMPLIED WITH



CESCOM 10 - Aircraft Status Report

Owner: **J.A. AERO, INC**
 Aircraft Model: **550 - BRAVO**
 Aircraft Serial: **550B-0849**
 Unit: **0849** Reg No: **N560JA**
 Airworthiness: **27-Sep-1998**
 Print Date: **07-Nov-2019 8:18AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	6780.1	5306	04-Nov-2019	.17
ENG 1	6723.2	5242	04-Nov-2019	.17
ENG 2	6723.2	5242	04-Nov-2019	.17
AIR COND	1130		04-Jun-2019	.9

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
21FO-02A <i>21FO-02 : 550/A</i>	COOLING-VAPOR CYCLE FACTORY OPTION	*CF		15A FO	MTH 27-Sep-1998		-			
23FO-01X <i>23FO-01 : 550/X</i>	KHF-950 (PROVISIONS) FACTORY OPTION	*CF		631X FO	MTH 27-Sep-1998		-			
25FO-22Q <i>25FO-22 : 550/Q</i>	LH FWD RELIEF TUBE DRAIN FACTORY OPTION	*CF		131Q FO	MTH 27-Sep-1998		-			
33FO-04	LIGHT-TAIL FLOOD FACTORY OPTION	*CF		54 FO	MTH 27-Sep-1998		-			
34FO-04	LOCATOR BEACON-EMERGENCY FACTORY OPTION	*CF		175 FO	MTH 27-Sep-1998		-			
34FO-20	GPWS-WINDSHEAR FACTORY OPTION	*CF		691 FO	MTH 27-Sep-1998		-			
53FO-01B <i>53FO-01 : 550/B</i>	STUB WING BEEF-UP INSTL FACTORY OPTION	*CF		188B FO	MTH 27-Sep-1998		-			