

PROPELLER MAINTENANCE RECORDS

		Log No. A
Aircraft Registration No	NYDOLP	
Propeller Manufacturer_	Wartzell	
Hub Model HC-H3YA	E-1RF/F76930F	
Blade Design No. F7	6930F	6
Hub Serial No	145B	1 9
Blade Serial No's. 1. K25058 2. K25066 3. K25065		
4		
Pitch Range: High 42.1/2 Feather	Low 16,4/4/16,9	1/2
	2000 1	
Governor Manufacturer		
	N/143	
Serial No05040	20	
Date installed on aircraft	8/17/05	
Time Between Overhauls	(TBO) 2400 Hours	
If used on mu	ulti-engine aircraft:	
☐ Right	☐ Left	
☐ Front	☐ Rear	



(All applicable information must be filled in)

AEROTECH PUBLICATIONS INC.

www.adlog.com PO BOX 1359 / SOUTHOLD, NY 11971-0965 (631) 765-9375

(631) 765-9375 1-800-235-6444 FAX: (631) 765-9359

Page No. TOTAL TIME TOTAL TIME TACH OR RECORDING METER DESCRIPTION OF WORK PERFORMED-DATE IN SERVICE SINCE SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK OVERHAUL TOTALS brought forward from previous page This propeller S/N LX145B installed on Lancair LC41-550FG S/N 41512 at time of aircraft manufacture. For The Lancair Company 9-12-05 THE LANCAIR COMPANY This propeller has been dynamically balanced per the Microvibe user's manual and Lancair Document SA600001 Rev B. For The Lancair Company SUB-TOTALS this page

TOTALS-Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	SIGNATURE &	ESCRIPTION OF WORK PERFORMED— CERTIFICATE NO. OF PERSON PERFORMIN	IG WORK
				TOTALS brought for	ward from previous page	
	PROP MODEL: PROP S/N: REG. NO: 400L WORK ORDER	р 🥥	LPAF	Lincoln Park Aviation 125 Beaverbrook Road Incoln Park, NJ 07035 Phone: 973-633-0450	DATE 9/28/2 ACT PROP HOBBS: 16	SN:
	MENN, ON S CHI	OP inspected pro	opelier in accordant MOVED AND REPL SWIVEL SEAL WIT	AGED PROPELLER CONTROL R) REMOVED AND REPLACED A THREE DE-ICE BOOTS WIT OD-END WITH NEW (9) REMOVED AND REPLACED	н —
	The Aircraft, Air Federal Aviation below.	frame, Aicraft Eng Administration a	ine, Propeller or Ap nd is Approved for n	pliance identified above was repair sturn to particip. Pertinent details of	ed and inspected in accordance with current regulations of the of the repair are on file at this repair station under work order is	ted
	DATE: 9/28/2	006	SIGNED:	4	Inspector 2 Work Order: 66	336
	i j		Frank R Galella	, IA: 2764795	Printed by EBis 3 (datcomedia.co	m)
	PROP MODEL: PROP SIN: REG. NO: 400LP WORK ORDER:		LPAF R	ncoin Park Aviation speir Station No. LKPR101K 5 Beaverbrook Road soln Park, NJ 07035 one: 973-933-0450	DATE: 9/28/20 A/C TS PROP 1 HOBBS: 278	N: T:
-	Prop Entries (3) ANNUAL/PRO			with 100/annual inspection.		
	below	William State of Land	is rapioved for re-	lance identified above was repaire turn to service. Pertinent details of	d and inspected in accordance with current regulations of the the repair are on file at this repair station under work order lists INSPECTOR 2	sd
	DATE: 9/26/200	07	SIGNED: Frank R Galella	70	Work Order: 741	
- 4				Station No. LKPR101K	Printed by EBis 3 (datcomedia.com	n) —
	PROP MODEL: PROP SIN: REG. NO: 400LP WORK ORDER: 8 Prop Entries (3) ANNUAL/PROF		Rep 425 Linc Pho	ncoln Park Aviation rair Station No. LKPR101K Beaverbrook Road roin Park, NJ 07035 ne: 973-633-0450	DATE: 12/2/200 A/C TSN: 386 PROP T HOBBS: 386,	2
	The Aircraft, Airtrar Federal Aviation Ar- below.	me, Aicraft Engine, aministration and i	_	12-12-22-22-23-23	and inspected in accordance with current regulations of the ne repair are on file at this repair station under work order listed	_
-	DATE: 12/2/2008		SIGNED: Frank R Galella	19	INSPECTOR 2 Work Order: 8199	
i	1		Certified Repair Stu	ation No. LKPR101K	Printed by EBis 3 (datcomedia.com	
		_		Propeller Log		
		Hobbs: I certify	y that this pr	l Time: 436.5 opeller has been inspe	N400LP	
		an ann	ual inspect	ion and determined	to be in an airworthy	
			A HARM	k A&P 2919106 IA		

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
	1:)			
		H 1 ar cc	certify that to annual in andition	Propeller Log N400LP Total Time: 490.3 his propeller has been inspected in accordance with espection and determined to be in an airworthy Valk A&P 2919106 IA

Propeller Logbook Entry Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884						Authorized Cessna Service Center	
Date	N' Number	Make/Model	Serial#	Tach	Hobbs	Total Time	W. O.
5/25/2012	N400LP	HC-H3YF-1RF	LX145B		506.8	506.8	7148

I certify that this propeller has been inspected in accordance with an Annual Inspection and determined to be in an airworthy condition.

I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.

Authorized Signature:

lt police

Steven VanderValk A&P 2919106 IA

Propeller Logbook Entry Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884						Authorized Cessna Service Center	
Date	N' Number	Make/Model	Serial#	Tach	Hobbs	Total Time	W. O.
10/15/2013	N400LP	Cessna 400	41512		548.3	548.3	7621

condition.

I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.

Authorized Signature:

po mon

Steven VanderValk A&P 2919106 IA

Propeller Logbook Entry		Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884						
Date	N' Number	Make/Model	Serial#	Tach	Hobbs	Total Time	W. O.	
12/3/2018	N400LP	HC-H3YF-1RF	LX145B		559.6	559.6	9172	

I certify that this propeller has been inspected in accordance with an Annual Inspection and determined to be in an airworthy condition.

I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.

Authorized Signature:

St Volle

Steven VanderValk A&P 2919106 IA